7 12 DOOS 128 9 PB

INITIALS

**Defense Systems Division** 

Electronics Systems Group

Northrop Corporation

600 Hicks Road Rolling Meadows, Illinois 60008-1098 Telephone 312 259-9600 TWX 910 687-3785 TLX 270566

December 4, 1985

Mr. Rama Chaturvedi Manager, Permit Program Development Unit Division Land Pollution Control Illinois Environmental Protection Agency 2200 Churchill Road Springfield, IL 62706



U.S. EPA, REGION V

NORTHROP CORPORATION'S STANDBY TRUST FUND AGREEMENT

Dear Mr. Chaturvedi:

Enclosed please find a signed copy of Northrop Corporation's amended Standby Trust Fund Agreement for closure costs. Amendment V to the Agreement:

- Replaces the Performance Bond for \$15,000 (Surety Bond No. KO 2972700), incorrectly issued for our Defense Systems Division located in Rolling Meadows, IL, with a Financial Guarantee Bond for \$30,000. (original enclosed)
- Deletes the Financial Guarantee Bond for \$950,000 (Surety Bond No. KO 1048089-35, that was changed to Surety Bond No. KO 297441A on 11 June 1985 - change enclosed) issued to our Precision Products Division located in Norwood, MA. This facility is no longer licensed as a Treatment Storage and Disposal Facility, therefore closure cost insurance is not required.
- Notices the change in bond number of the Financial Guarantee Bond No. KO 48089-32 issued to our Aircraft Division located in Hawthorne, CA to Bond No. KO 297468A.

If you have any questions, or require additional information, please feel free to contact Ms. Lisa Riggle at (312) 394-7704.

LR:d1 Enclosure

cc: W. B. Terry List Division Counsel

Region V, USEPA

Jang hton

Vice President

Financial Management

AMENDMENT V TO

RESOURCE CONSERVATION

AND

RECOVERY ACT

STANDBY TRUST

FUND AGREEMENT

NORTHROP CORPORATION

AND

BANK OF AMERICA NT & SA

OCTOBER 28, 1985

# AMENDMENT V TO RESOURCE CONSERVATION and RECOVERY ACT STANDBY TRUST FUND

NORTHROP CORPORATION

Attest:	Thomas J. McCabe, Jr. Corporate Environmental Control Administrator	by: Mame: Robert Grothe  Title: Assistant Treasurer
	[Seal]	
		BANK OF AMERICA NT & SA  by Malleur Manual  Name: Marlene McDowall  Title: Assistant Vice President  by: Mame: HOLDH ROBIDEAUX  TACST OFFICER  Title:
Attest:	Thomas & Tyres	
Name:	Thomas E. Tyner	
Title:	Assistant Secretary BANK OF AMERICA N.T. & S.A.	
	[Seal]	

## <u>ACKNOWLEDGEMENT</u>

STATE OF CALIFORNIA COUNTY OF LOS ANGELES

SS

On October 28, 1985, before me, the undersigned, a Notary Public in and for said County and State, personally appeared Robert Grothe known to me to be the Assistant Treasurer of the Corporation that executed the within instrument and the officer who executed the within instrument on behalf of the Corporation therein named, and acknowledged to me that such Corporation executed the within instrument pursuant to Resolutions and procedures approved by its Board of Directors.



Notary's Signature: Sherry L. Cagueliall

## FINANCIAL GUARANTEE BOND

ed bond ex	ecuted: <u>08/19</u>	/85										
Effective date	. 04/01/85	(1)				7						
	Œ	2)										
Principal: NO	ORTHROP CORP	ORATION,	1840 C	entury	Park	East,	Los	Angeles,	CA.	90067		
						(3)						
Type of organi	zation: Corpo	ration				1	-					
S	oration: Calif	ornia	(4)									
State of incorp	oration:	<u>Ornia</u>	(5)		-							
Surety(ies):	INSURANCE C	OMPANY O	F NORTH	AMERI	CA, 5	757 W1:	lshir	e Blvd.,	Los	Angeles,	CA.	90036
				-		(6)						-
•												
•		·										
-												
								•				
USEPA I.D. N	o. 000627273	<u> </u>						Closure Amount (8)		Post-Closure Amount (9)		Closure and Post-Closure Amounts
me DEI	FENSE SYSTEM	S DIVISI	ON OF N	ORTHRO	P COR	PORATIO	ON	\$30,000.		-	Ş	30,000.
Address 60	00 Hicks Roa	d							•	· · · · · · · · · · · · · · · · · · ·		
City Ro	olling Meado	ws, Illii	nois	··-								
USEPA I.D. N	0.	-										
Name									÷			
Address												
City				·								
Please attach	a separate page if	more space is	needed fo	r all facili	ties.							Manager,
Total penal su	m of bond: \$ <u>30</u>	.000.00										
	КО 2		) (11	.)				Α.				

Know All Persons By These Presents, That we, the Principal and Surety(ies) hereto are firmly bound to the Illinois Environmental Protection Agency (hereinafter called IEPA), in the above penal sum for the payment of which we bind ourselves, our heirs, executors, administrators, successors and assigns jointly and severally; provided that, where the Surety(ies) are corporations acting as co-sureties, we, the Sureties, bind ourselves in such sum "jointly and severally" only for the purpose of allowing a joint action or actions against any or all of us, and for all other purposes each Surety binds itself, jointly and severally with the Principal, for the payment of such sum only as is set forth opposite the name of such Surety, but if no limit of liability is indicated, the limit of liability shall be the full amount of the penal sum.

This Agency is authorized to require, pursuant to Illinois Revised Statutes, 1981, Chapter 111 1/2, Section 21(f), that this information be submitted to the Agency by the owner or operator of a hazardous waste storage, treatment or disposal site. Failure to provide the information may result in a civil penalty against the owner or operator of not to exceed \$25,000 per day of violation. Falsification of this information by any person may constitute a Class 4 felony, and may also carry a fine for the first offense of not to exceed \$25,000 per day. This form has been approved by the Forms Management Center.

Whereas said Principal is required, under the Environmental Protection Act, Illinois Rev. Stat. 1981, ch. 111 1/2, par. 1001 et seq., as amended, to have a permit or interim status in order to own or operate each hazardous waste management facility identified above, and

Whereas said principal is required to provide financial assurance for closure, or closure and post-closure care, as a condition of the permit or interim status, and

Whereas said Principal shall establish a standby trust fund as is required when a surety bond is used to provide such financial assurance;

Now, Therefore, the conditions of the obligation are such that if the Principal shall faithfully, before the beginning of final closure of each facility identified above, fund the standby trust fund in the amount(s) identified above for the facility,

Or, if the Principal shall fund the standby trust fund in such amount(s) within 15 days after an order to begin closure is issued by the IEPA Director, the Illinois Pollution Control Board, or a U.S. district court or other court of competent jurisdiction.

Or, if the Principal shall provide alternate financial assurance, as specified in Subpart H of 35 Illinois Administrative Code Parts 724 or 725, as applicable, and obtain the IEPA Director's written approval of such assurance, within 90 days after the date notice of cancellation is received by both the Principal and the IEPA Director from the Surety(ies), then this obligation shall be null and void, otherwise it is to remain in full force and effect.

The Surety(ies) shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above. Upon notification by the IEPA Director that the Principal has failed to perform as guaranteed by this bond, the Surety(ies) shall place funds in the amount guaranteed for the facility(ies) into the standby trust fund as directed by the IEPA Director.

The liability of the Surety(ies) shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety(ies) hereunder exceed the amount of said penal sum.

The Surety(ies) may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the IEPA Director, provided, however, that cancellation shall not occur during the 120 days beginning on the date of receipt of the notice of cancellation by both the Principal and the IEPA Director, as evidenced by the return receipts.

The Principal may terminate this bond by sending written notice to the Surety(ies), provided, however, that no such notice shall become effective until the Surety(ies) receive(s) written authorization for termination of the bond by the IEPA Director.

(The following paragraph is an optional rider that may be included but is not required. If the parties do not choose to include it, please block out the following paragraph.)

Principal and Surety(ies) hereby agree to adjust the penal sum of the bond yearly so that it guarantees a new closure and/or post-closure amount, provided that the penal sum does not increase by more than 20 percent in any one year, and no decrease in the penal sum takes place without the written permission of the IEPA Director.

In Witness Whereof, the Principal and Surety(ies) have executed this Financial Guarantee Bond and have affixed their seals on the date set forth above.

The persons whose signatures appear below hereby certify that they are authorized to execute this surety bond on behalf of the Principal and Surety (ies).

Principal(s) NORTHROP CORPORATION

Signature

Typed Name

Typed Name

Title

Date

August 19, 1985

Signature

Typed Name

Typed Name

Date

Corporate seal

Corporate seal

## Corporate Surety(ies)

TUDOITZINOH O	OMPANY OF NORTH AMERIC	CA	Name	
Address 5757 Wilsh	ire Blvd.,Los Angeles,	CA. 90036	Address	
	nsylvania		State of incorporation	
Liability limit \$ In exc	ess of \$75,000,000.00		Liability limit \$	
Signature ()	JAU		Signature	
Typed name Wall	ace C. Doyle		Typed name	
Title Atto	rney in-Fact		Title	
				· · · · · · · · · · · · · · · · · · ·
Corporate seal		·	Corporate seal	
•				
				-
Co-surety(ies)				e.
Name			Name	
ddress	· · · · · · · · · · · · · · · · · · ·		Address	
State of incorporation	· · · · · · · · · · · · · · · · · · ·		State of incorporation	
Liability limit \$			Liability limit \$	
Signature	3"		Signature	
Typed name	· ··· ••		Typed name	
			Title	

Bond premium: \$ 225.00

COUNTERSIGNED

Philip Prass

ohnson & Higgins of Illinois, Inc.

101 N. Wacker Dr.

Chicago, Illinois 60606

## CALIFORNIA ACKNOWLEDGE BY SURETY

STATE OF CALIFORNIA ) )ss.
COUNTY OF Los Angeles )

On this 21st day of August in the year 1985, before me G. J. Gundersen, personally appeared James P. Strang personally known to me to be the person who executed the within instrument as Assistant Treasurer of Northrop Corporation and acknowledged to me that the corporation executed it.



Notary Public

## CALIFORNIA ACKNOWLEDGEMENT BY SURETY

STATE OF CALIFORNIA	· · · · · · · · · · · · · · · · · · ·	
COUNTY OF Los Angeles	ss.	<u>u</u>
On this 19th day of August	in the year 1985, before meDina Monsalve	personally
appeared Wallace C. Doyle	2	
personally known to me (or proved to	o me on the basis of satisfactory evidence) to be the person who	executed the within
instrument as attorney-in-fact of	INSURANCE COMPANY OF NORTH AMERICA	
and acknowledged to me that the corp	poration executed it.	
OFFICIAL SEAL DINA MONSALVE NOTARY PUBLIC - CALIFORNIA PRINCIPAL OFFICE IN LOS ANGELES COUNTY	Zina mon	Jabre_



## PRECISION PRODUCTS DIVISION

## NORWOOD, MASSACHUSETTS

By virtue of the attached letters dated September 9, 1985, from Mr. Steven A. DeGabriele, Acting Deputy Director, Licensing and Enforcement Branch, Commonwealth of Massachusetts Department of Environmental Quality Engineering to Mr. John Alleruzzo of Northrop Corporation, closure cost coverage is no longer needed at what were formerly considered the treatment, storage or disposal facilities at:


- 1. 934 Washington Street Norwood, MA MAD 000649707
- 2. 100 Morse Street Norwood, MA MAD 001829662

Please note also that the two other Precision Products Division facilities listed in Amendment IV, dated May 28, 1985, at:

- 1. 59 Davis Avenue Norwood, MA MAD 980913784
- 2. 823 Pleasant Street Norwood, MA MAD 900917363

were never considered treatment storage or disposal facilities and should never have been included for coverage.

Therefore, as each of the aforementioned four facilities is now officially considered a generator facility, closure cost insurance is no longer required.



# The Commonwealth of Massachusett. Executive Office of Environmental Affairs Department of Environmental Quality Engineering Division of Solid and Hazardous Waste One Winter Street, Boston, Mass. 02108

September 9, 1985

Mr. John Alleruzzo Northrop Corporation 100 Morse Street Norwood, MA 02062 Re: MAD 000649707

934 Washington Street

Norwood

Dear Mr. Alleruzzo:

This is in response to your letter of February 2, 1984 requesting a change in status from Treatment, Storage and Disposal Facility to Generator of hazardous waste. From the information provided it appears that your facility does not now treat, store (over 90 days), or dispose of hazardous waste at the above identified site.

This letter confirms that the status of your facility has been changed to Generator. Under Massachusetts hazardous waste regulations (310 CMR 30.340) a generator is allowed to accumulate hazardous waste on site for up to 90 days without a hazardous waste license.

For more complete information about the requirements for generators please refer to the full set of regulations (310 CMR 30.300), as well as the special requirements for wastewater treatment units listed in 30.605.

If this interpretation of your current status is incorrect, or at any time in the future you should change your location or activity to qualify for another status under the regulations, you must notify this office in writing.

Please contact the Compliance Branch of the Division of Solid and Hazardous Waste at (617) 292-5851 if you have any questions.

Sincerely,

Aville House for Steven A. Defabriele Acting Deputy Director

Licensing and Enforcement Branch

SAD/NW/td

cc: Gary Gosbee

State Waste Program, EPA DEQE Regional Office



The 'monwealth of Massachusetts

Executive Office of Environmental Affairs

Department of Environmental Quality Engineering

Division of Solid and Hazardous Waste

One Winter Street, Boston, Mass. 02108

September 9, 1985 MECEIVED

OEP 1 6 1985

Mr. John Alleruzzo Northrop Corporation 100 Morse Street Norwood, MA 02062 Re: MAD 001829662<sup>T. J.</sup> McCABE, JR.

100 Morse Street Norwood

Dear Mr. Alleruzzo:

This is in response to your letter of May 7, 1985 requesting a change in status from Treatment, Storage and Disposal Facility to Generator of hazardous waste. From the information provided it appears that your facility does not now treat, store (over 90 days), or dispose of hazardous waste at the above identified site.

This letter confirms that the status of your facility has been changed to Generator. Under Massachusetts hazardous waste regulations (310 CMR 30.340) a generator is allowed to accumulate hazardous waste on site for up to 90 days without a hazardous waste license.

For more complete information about the requirements for generators please refer to the full set of regulations (310 CMR 30.300), as well as the special requirements for wastewater treatment units listed in 30.605.

If this interpretation of your current status is incorrect, or at any time in the future you should change your location or activity to qualify for another status under the regulations, you must notify this office in writing.

Please contact the Compliance Branch of the Division of Solid and Hazardous Waste at (617) 292-5851 if you have any questions.

Sincerely,

Steven A. DeGabriele Acting Deputy Director

Licensing and Enforcement Branch

SAD/NW/td

cc: Gary Gosbee

State Waste Program, EPA DEQE Regional Office

Insurance Company of North America  Aetna Insurance Company  Aetna Fire Insurance Company  Pacific Employers Insurance Company	CIGNA Insurance Company Century Indemnity Company CIGNA Companies	GNA
Rider to be attached to and form a part of Bo	nd Number KO 10 48 08 9-35	
on behalf of NORTHROP CORPORATION		
1800 CENTURY PARK EAST, LOS ANGELES,	CALIFORNIA 90067	Principali,
and in favor of DIVISION OF HAZARDOUS WASTI	(Address) ES, DEPT. OF ENVIRONMENTAL QUALITY ENGINEERING	(Obligee),
	in the amount of TWENTY TWO THOUSAND AND NO/100	
Dollars (\$ 22,000.00 ) effective OCTOBER	1982	
The Principal and the Surety hereby consent	to changing the said bond as follows:	
THE BOND NUMBER :	INDICATED ON THE BOND IS HEREBY	-
KO 29 74 71 A		
This change is effective JUNE 11	19 <u><b>85</b></u>	
Nothing herein contained shall vary, alter or extend	any provision or condition of the bond other than as above state	d.
Signed, Sealed and dated this	day of <b>JUNE</b>	, 19 <u><b>85</b></u>
State of California )		
County of Los Angeles		
for said State, personally appears	before me, the undersigned, a Notary Public in ed	<del></del> .
· ·	to me on the basis of satisfactory evidence to subscribed to the within instrument and	
- <del></del>		
WITNESS my hand and official seal.	•	
G. J. NOTARY P LOS AN	CIAL SEAL GUNDERSEN PUBLIC - CALIFORNIA IGELES COUNTY Exp. Dec. 27, 1985	<del></del>

☐ CIGNA Insurance Company

Insurance Company of North America Aetna Insurance Company Aetna Fire Insurance Company	☐ CIGNA Insurance Company ☐ Century Indemnity Company	
Pacific Employers Insurance Company	CIGNA Companies	
Rider to be attached to and form a part of E	Bond Number KO 10 48 08 9-35	
on behalf of NORTHROP CORPORATION		
1800 CENTURY PARK EAST, LOS ANGELES	S, CALIFORNIA 90067	(Principal)
and in favor of DIVISION OF HAZARDOUS WAS	(Address) STES, DEPT. OF ENVIRONMENTAL QUALITY ENGINEERING	(Obligee)
	y) in the amount of TWENTY TWO THOUSAND AND NO/100	
Dollars (\$ 22,000.00 ) effective OCTOBE	IR 1 19 82	
The Principal and the Surety hereby conser	nt to changing the said bond as follows:	
THE BOND NUMBER AMENDED TO:	R INDICATED ON THE BOND IS HEREBY	-
KO 29 74 71 A		
This change is effective JUNE 11	19 <b>85</b>	
Nothing herein contained shall vary, alter or extend	d any provision or condition of the bond other than as above stated	d.
Signed, Sealed and dated this11TH	day of <b>JUNE</b>	. 19. <b>85</b>
NOR	THROP CORPORATION	
RVS	D-122	
	James P. Strang, Assistant Treasurer	***************************************
	TURANCE COMPANY OF NORTH AMERICA	
, ,	Viski & Moore	
V.	TCKI E. MOORE, ATTORNEY-IN-FACT	

# POWER OF ATTORNEY

# Insurance Company of North America a CIGNA company



Know all men by these presents: That INSURANCE COMPANY OF NORTH AMERICA, a corporation of the Commonwealth of Pennsylvania, having its principal office in the City of Philadelphia, Pennsylvania, pursuant to the following Resolution adopted by the Board of Directors of the said Company on December 5, 1983, to wit:

adopted by the Board of Directors of the said Company on December 5, 1983, to wit: RESOLVED. That pursuant to Articles 3.18 and 5.1 of the By-Laws, the following Rules shall govern the execution for the Company of bonds, undertakings, recognizences, contracts and other writings in the nature thereof That the President, any Senior Vice President, any Vice President, any Assistant Vice President, or any Attorney-in-Fact, may execute for and on behalf of the Company any and all bonds, undertak. That the President, any serior vice President, any vice resident, any vice resident, and vice resident and the same to be attested when necessary by the Corporate Secretary or any Assistant Corporate Secretary, and the same to be attested when necessary by the Corporate Secretary or any Assistant Corporate Secretary or an the Company, and Attorneys in-Fact to so execute or attest to the execution of all such writings on behalf of the Company and to affix the seat of the Company thereto The signature of the President, or a Senior Vice President, or a Vice President, or an Assistant Vice President and the seal of the Company may be affixed by facsimile on any power of attorney granted pursuant to this Resolution, and the signature of a certifying Officer and the seal of the Company may be affixed by facsimile to any certificate of any such power, and any such power or certificate. tricate bearing such facsimile signature and sear sharl be valid and binding on the Company Such other Officers of the Company, and Attorneys in-Fact shall have authority to certify or verify copies of this Resolution, the By-Laws of the Company, and any affidavit or record of the Company necessary to the discharge of their duties The passage of this Resolution does not revoke any earlier authority granted by Resolutions of the Board of Directors adopted on June 9, 1953, May 28, 1975 and March 23, 1977. does hereby nominate, constitute and appoint FRED B. ROBERTSON, CESAR F. JAVIER, VICKI E. MOORE, JOHN C. CANNING, LINDA ZAPPIA, and BRUCE A. POITEVIN, all of the City of Los Angeles, State of ---, each individually if there be more than one named, its true and lawful attorney-in-fact, to make, execute, seal and deliver on its behalf, and as its act and deed any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof. And the execution of such writings in pursuance of these presents, shall be as binding upon said Company, as fully and amply as if they had been duly executed and acknowledged by the regularly elected officers of the Company at its principal office. IN WITNESS WHEREOF, the said H.F. McCranie, Jr., Vice-President, has hereunto subscribed his name and affixed the corporate seal of the said INSURANCE COMPANY OF NORTH AMERICA this \_\_\_ OCTOBER **INSURANCE COMPANY OF NORTH AMERICA** by H. F. McCranie, JR COMMONWEALTH OF PENNSYLVANIA COUNTY OF PHILADELPHIA , A.D. 19\_84, before me, a Notary \_ day of \_\_\_\_ OCTOBER Public of the Commonwealth of Pennsylvania in and for the County of Philadelphia came H.F. McCranie, Jr., Vice-President of the INSURANCE COMPANY OF NORTH AMERICA to me personally known to be the individual and officer who executed the preceding in-Company the preceding instrument is the corporate seal of the preceding instrument is the corporate seal of the preceding instrument is the corporate seal of the preceding instrument is the corporation, and company the seal corporation and the preceding instrument is the seal corporation, and company the seal of Directors of said Company referred to in the preceding instrument is the corporate seal of the seal corporation. strument, and be acknowledged that he executed the same, and that the seal affixed to the preceding instrument is the corporate seal of WHEREOF, I have hereunto set my hand and affixed my official seal at the City of Philadelphia the day and year e written. SOAN T. CAREY - Notary Public **OF** Notary Public Philadelphia, Philadelphia County, PA My Commission Expires July 11, 1988 Secretary of INSURANCE COMPANY OF NORTH AMERICA, do hereby certify that the original POWER The foregoing is a full, true and correct copy, is in full force and effect. Whereof, I have hereunto subscribed my name as Secretary, and effixed the corporate seal of the Corporation.

11TH day of JUNE 19 85 this, (SEAL)

SRESSELS.

<ul><li>Aetna insurance Company</li><li>Aetna Fire insurance Company</li></ul>	Century Indemnity Company	MOGNIA
Pacific Employers Insurance Company	CIGNA Companies	CIGNA
·		
Rider to be attached to and form a part of Bond	d NumberKO 10 48 08 9-32	
on behalf ofNORTHROP_CORPORATION	(Name)	
1840 CENTURY PARK FAST, LOS ANCELES,	CALIFORNIA 90067	
and in favor of U.S. ENVIRONMENTAL PROTECTION	ON AGENCY (EPA)	(Obligee),
executed by the Company indicated above (Surety) in	the amount of ONE HUNDRED THIRTY OF	NE THOUSAND AND NO/10
Dollars (\$ 131,000.00 ) effective OCTOBER		
The Principal and the Surety hereby consent to	o changing the said bond as follows:	
THE BOND NUMBER AMENDED TO:	INDICATED ON THE BOND IS HEREBY	-
BOND NO. KO 29 7	V. 68 A	
DOND NO. NO 25 7	4 00 A	
This change is effective JUNE 11	19 <b>85</b>	
Nothing herein contained shall vary, alter or extend an	ny provision or condition of the bond other tha	an as above stated.
Signed, Sealed and dated this d	tay of JUNE	, <sub>19.</sub> <b>85</b>
I Partie In	AT	
State of California ) County of Los Angeles }		
On July 16, 1985 , before me, the	e undersigned, a Notary Public in	and to me or
for said State, personally appeared <u>James</u>	P. Strang , personally known	name is
proved to me on the basis of satisfactory	cknowledged that he executed the	same.
subscribed to the within instrument and a	CKNOW reaged chas in one of the	
WITNESS my hand and official seal.		
	$\mathcal{A}(A) = \mathcal{A}(A)$	
OFFICIAL SEAL G. J. GUNDERSEN NOTATY FUBLIC - CALIFORNIA LOS ANGELES COUNTY My Comm. Exp. Dec. 27, 1985	Notary Public's Signa	ature

☐ CIGNA Insurance Company

XX Insurance Company of North America

SEP 23 1985

Insurance Company of North America Aetna insurance Company Aetna Fire Insurance Company	<ul><li>CIGNA Insurance Company</li><li>Century Indemnity Company</li></ul>	" M CARE UR
Pacific Employers Insurance Company	CIGNA Companies	CIGIVA
	Bond Number KO 10 48 08 9-32	
on behalf of NORTHROP CORPORATION		
1840 CENTURY PARK EAST, LOS ANGELL	(Name) ES, CALIFORNIA 90067	(Principal),
and in favor of U.S. ENVIRONMENTAL PROT	ECTION AGENCY (EPA)	(Obligee),
executed by the Company indicated above (Sure	ety) in the amount of ONE HUNDRED THIRTY ONE	THOUSAND AND NO/100
Dollars (\$ 131,000.00 ) effective OCTO	BER 1 19 82	
The Principal and the Surety hereby cons		
	BER INDICATED ON THE BOND IS HEREBY	
AMENDED TO:	DEK INDICATED ON THE DOWN TO HEATEN	-
BOND NO. KO	29 74 68 A	
Date Iv. Iv	27 74 00 11	
,		
Traws 11	85	
This change is effective JUNE 11		
Nothing herein contained shall vary, alter or exte	end any provision or condition of the bond other than	
Signed, Sealed and dated this11TH	day of <b>JUNE</b>	, 19 <mark>.85</mark> .
<u>NO</u>	RITHROP CORPORATION	
B	a Plant	
IN	James P. Strang, Assistant Treasurer ISURANCE COMPANY OF NORTH AMERICA	
• Bv	Miki & Moore	
	VICKI E. MOORE, ATTORNEY-IN-FACT	

# insurance Company of North America a CIGNA company



Know all men by these presents: That INSURANCE COMPANY OF NORTH AMERICA, a corporation of the Commonwealth of Pennsylvania, having its principal office in the City of Philadelphia, Pennsylvania, pursuant to the following Resolution adopted by the Board of Directors of the said Company on December 5, 1983, to wit:

adobte	ed by the board of Directors of the s	aid Company on December 5, 1963, t	o wit:	
writings in	*RESOLVED, That pursuant to Articles 3 18 and the nature thereof.	5.1 of the By-Laws, the following Rules shall govern to	he execution for the Company of bonds, undertakings, recogn	szances, contracts and other
<del>(1)</del>	<ul> <li>ings_recognizances, contracts and other writings in Company affixed thereto, and that the President, a</li> </ul>	it the nature thereof, the same to be attested when nece ny Senior Vice President, any Vice President or any Asc	orney-in-Fact, may execute for and on behalf of the Company ssary by the Cotporate Secretary, or any Assistant Corporate i istant Vice President may appoint and authorize any other Off If the Company and to affix the seal of the Company thereto	Secretary, and the seal of the
12-	Any such writing executed in accordance with these	a Rules shall be as binding upon the Company in any cas	e as though signed by the President and attested to by the Con-	porate Secretary
(3)	The signature of the President for a Senior Vice P granted outsuant to this Resolution, and the signaturiticate bearing such facsimile signature and seal shi	ure of a certifying Officer and the seal of the Company t	sident and the seal of the Company may be affixed by facsim hay be affixed by Jacsimile to any certificate of any such power	 ife on any power of attorney (, and any such power or cer-
r <b>4</b> -	Such other Officers of the Company, and Attorneys necessary to the discharge of their duties	s in-Fact shall have authority to certify or verify copies o	f this Resolution, the By-Laws of the Company, and any affida	vit or record of the Company
151	The passage of this Resolution does not revoke any	earlier authority granted by Resolutions of the Board of	Directors adopted on June 9, 1953, May 28, 1975 and March 2,	3, 1977.''
CANN	ING, LINDA ZAPPIA, and	oint FRED B. ROBERTSON, C BRUCE A. POITEVIN, all c	CESAR F. JAVIER, VICKI E. MO of the City of Los Angeles,	OORE, JOHN C. State of
•		·		
recogn be as t of the	nizances, contracts and other writin binding upon said Company, as fully Company at its principal office. IN WITNESS WHEREOF, the sai	te, execute, seal and deliver onlits be gs in the nature thereof. And the exe y and amply as if they had been duly	half, and as its act and deed any and all be cution of such writings in pursuance of the executed and acknowledged by the regulation, has hereunto subscribed his name and at 15th.	onds, undertakings, nese presents, shall arly elected officers
day of		OCTOBER	13011	19 84
			INSURANCE COMPANY OF NORTH	9.
			H. F. McCRANIE, JR	Vice-President
COUN	ONWEALTH OF PENNSYLVANIA TY OF PHILADELPHIA On this	ss. 15th day of OCTO	BER AD 19.84, t	pefore me, a Notary
INSUI strume	RANCE COMPANY OF NORTH A ent, and be acknowledged that he or nany the acknowledged that he or nany the said corporate se	MERICA to me personally known to executed the same, and that the sea al and his signature were duly affixed Directors of said Company, referred to	iladelphia came H.F. McCranie, Jr. Video be the individual and officer who execute affixed to the preceding instrument is the dividual and direction of the salp in the preceding instrument, is now in for	ed the preceding in- ne corporate seal of id corporation, and rce.
first at	eye written		d my official seal at the City of Philadelph	ia the day and year
BEA	OF T	DOAN T. CAREY Notary Public Philadelphia, Philadelphia County, PA My Commission Expires July 11, 1988	OAN T. CAREY	Notary Public
12	The Whole impend Secretary of		RTH AMERICA, do hereby certify that t	he opoinal POWER
OF A	TO THEY, applying the foregoing is	a full, true and correct copy, is in full eunto subscribed my name as Sec II NH		
this		day of		D. 10
(SEAL	.)		James S. Wylkie	Secretary
			James J. Verne J. S.	J Secretary



1D 000 627 273

1LD 005 128 988

## NORTHROP

May 7, 1985

Northrop Corporation

1840 Century Park East Los Angeles, California 90067-2199 Elephone 213 553-6262

REGETVE

MAY 13 1985

STATO WASTE BRANCH U.S. EPA, REGION V

USEPA, Region V Waste Management Branch 230 South Dearborn Street Chicago, Illinois 60604

> Re: Hazardous Waste Performance Bond Bond No. K02972700 Penal Sum - \$30,000

## Gentlemen:

We enclose Bond No. K02972700 in the amount of \$30,000 effective April 1, 1985. This bond replaces K01048089-30 issued in January 1983.

The new bond amount has been increased from \$15,000 to \$30,000 as indicated on the "Increase Rider."

If you require additional information, please advise.

Very truly yours,

NORTHROP CORPORATION

Ruth Chapman Insurance Specialist Risk Management

RC:k1b

cc: Illinois EPA, Solid Waste Branch
2200 Churchill Road
Springfield, Illinois 62706
Thomas McCabe, Esq.
File - SB-31



# INSURANCE COMPANY OF NORTH AMERICA PHILADELPHIA, PA. 19101

Rider to be attached to and form a part of Bond Number KO 29 72 70 0

## INCREASE RIDER

on behalf of NORTHROP CORPORATION (Name)		
1840 Century Park East, Los Angeles, C. (Address)	(Principal),	
and in favor of ILLINOIS ENVIRONMENTAL P	ROTECTION AGENCY (IEPA)	(Obligee),
executed by the INSURANCE COMPANY OF NORS	'H AMERICA, as	
Surety, in the amount of FIFTEEN THOUSAN	D AND NO/100	(\$15,000.00)
Dollars, effective APRIL 1	19 85.	
The Principal and the Insurance Components of the said bond as follows:	oany of North America hereby co	nsent to
The Penalty of said bond is increase		
FROM: FIFTEEN THOUSAND AND NO/100 D	OLLARS (\$15,000.00)	
TO: THIRTY THOUSAND AND NO/100 D	OLLARS (\$30,000.00)	
EFFECTIVE DATE OF INCREASE:	APRIL 1, 1985.	
Nothing herein contained shall vary,	alter or extend any provision	or condition
of the bond other than as above stated.		
Signed, Sealed and dated this	5th day of April NORTHROP CORPORATION	, 19 85
	BY:	
	INSURANCE COMPANY OF NORTH	AMERICA
	By White	- in Foot

STATE OF	CAL	IFOR!	NIA
COUNTY	OF	Los	Angeles

}ss

ONAori 1 5 undersigned, a Notary Public in and for said County	, 19.85, before me, the and State, personally appeared
James P. Strang, Assistant Treasurer,	

OFFICIAL SEAL SHERRY L. COGESHALL NOTARY PUBLIC — CALIFORNIA PRINCIPAL OFFICE IN LOS ANGELES COUNTY

My Commission Expires August 14, 1985

known to me to be the person who executed the within instrument on behalf of the Corporation therein named, and acknowledged to me that such Corporation executed the within instrument pursuant to its By-laws or a Resolution of its Board of Directors.

CORPORATION ACKNOWLEDGMENT Manager or Officer

m No. 15

# **CALIFORNIA**

	ACKNOWLEDGEMENT BY SURETY	
STATE OF CALIFORNIA	)	
COUNTY OF Los Angeles	SS.	
On this 5th day of April	in the year 19_85, before me Dina Monsalve	personally
appeared Daniel Ortiz		,
personally known to me (or proved to	o me on the basis of satisfactory evidence) to be the person who execu	ted the within
instrument as attorney-in-fact of	INSURANCE COMPANY OF NORTH AMERICA	
and acknowledged to me that the corp	poration executed it.	
OFFICIAL SEAL &		
DINA MONSALVE NOTARY PUBLIC - CALIFORNIA		

PRINCIPAL OFFICE IN LOS ANGELES COUNTY MY COMMISSION EXPIRES APRIL 28, 1985

) ma Monsalre Notary Public

## **POWER OF ATTORNEY**

620112

# INSURANCE COMPANY OF NORTH AMERICA

PHILADELPHIA, PA.

Know all men by these presents: That INSURANCE COMPANY OF NORTH AMERICA, a corporation of the Commonwealth of Pennsylvania, having its principal office in the City of Philadelphia, Pennsylvania, pursuant to the following Resolution adopted by the Board of Directors of the said Company on May 28, 1975, to wit:

"RESOLVED, pursuant to Articles 3.6 and 5.1 of the By-Laws, the following Rules shall govern the execution for the Company of bonds, undertakings, recognizances, contracts and other writings in the nature thereof:

- (1) That the President, or any Vice-President, Assistant Vice-President, Resident Vice-President or Attorney-in-Fact, may execute for and in behalf of the Company any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof, the same to be attested when necessary by the Secretary, an Assistant Secretary or a Resident Assistant Secretary and the seal of the Company affixed thereto; and that the President or any Vice-President may appoint and authorize Resident Vice-Presidents, Resident Assistant Secretaries and Attorneys-in-Fact to so execute or attest to the execution of all such writings on behalf of the Company and to affix the seal of the Company thereto.
- (2) Any such writing executed in accordance with these Rules shall be as binding upon the Company in any case as though signed by the President and attested by the Secretary.
- (3) The signature of the President or a Vice-President and the seal of the Company may be affixed by facsimile on any power of attorney granted pursuant to this Resolution, and the signature of a certifying officer and the seal of the Company may be affixed by facsimile to any certificate of any such power, and any such power or certificate bearing such facsimile signature and seal shall be valid and binding on the Company.
- (4) Such Resident Officers and Attorneys-in-Fact shall have authority to certify or verify copies of this Resolution, the By-Laws of the Company, and any affidavit or record of the Company necessary to the discharge of their duties.
- (5) The passage of this Resolution does not revoke any earlier authority granted by Resolution of the Board of Directors on June 9,

City of Los Angeles, State of California
there there in the little time, there is a first the second to the second the second time of the contract the second
, each individually if there be more than one named,
its true and lawful attorney-in-fact, to make, execute, seal and deliver on its behalf, and as its act and deed
any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof. And the execution of such writings in pursuance of these presents, shall be as binding upon said Company, as fully
and amply as if they had been duly executed and acknowledged by the regularly elected officers of the
Company at its principal office
IN WITNESS WHEREOF, the said MICHAEL B. FODOR , Vice-President,
has hereunto subscribed his name and affixed the corporate seal of the said INSURANCE COMPANY OF
NORTH AMERICA this 22nd day of March 19 83
INSURANCE COMPANY) OF NORTH AMERICA
(SEAL) by Michael S. Forly
MICHAEL B. FODOR Vice President
STATE OF PENNSYLVANIA COUNTY OF DELAWARE SS.
On this day of, A. D. 19, before me, a Notary
Public of the COMMONWEALTH OF PA. in and for the County of DELAWARE came
MICHAEL B. FODOR , Vice-President of the INSURANCE
COMPANY OF NORTH AMERICA to me personally known to be the individual and officer who executed the preceding instrument, and he acknowledged that he executed the same; that the seal affixed to the preceding instrument is the
corporate seal of said Company; that the said corporate seal and his signature were duly affixed by the authority and
direction of the said corporation, and that Resolution, adopted by the Board of Directors of said Company, referred to in the preceding instrument, is now in force.
IN TESTIMONY WHEREOF, I have hereunto set my hand and affixed my official seal at the City of
the day and year first above written.  IOAN LOUGHRAN - Notary Public
(SEAL) Upper Darby, Delaware County, Pa.
My commission expires In. 12, 1987 JOAN LOUGHRAN
I, the undersigned, ************************************
the original POWER OF ATTORNEY, of which the foregoing is a full, true and correct copy, is in full force and effect.  In witness whereof, I have hereunto subscribed my name as ASSECTION Secretary, and affixed the corporate seal of the Corporation, this

#### PERFORMANCE BOND

Dated bond executed:03/27/85			
Effective date:04/01/85 (1)			
(2)			
Principal: NORTHROP CORPORATION, 1840 Century Park East,	Los Angeles,	CA. 90067	
(3)			
Type of organization: Corporation		- grantors	
Type of organization: Corporation (4)			
State of incorporation:California			
(5) .			
			9
Surety(ies): INSURANCE COMPANY OF NORTH AMERICA, 5757 Wils	hire Blvd.,	Los Angeles,	CA. 90036
(6)			
	VIEW		
A STATE OF THE RESERVE OF THE RESERV		A	
of all the literature and the literature and a section of			C11
Applied Comments of the Commen	Closure	Post-Closure	Closure and Post-Closure
USEPA I.D. No. 000627273	Amount	Amount	Amounts
(7)	(8)	(9)	(10)
Name DEFENSE SYSTEMS DIVISION OF NORTHROP CORPORATION	_ \$15,000.		\$15,000.
Address 600 Hicks Road			
City Rolling Meadows, Illinois			
USEPA I.D. No.			
(7)			
Name			
Name			
Address			
City			
Please attach a separate page if more space is needed for all facilities.			
Total penal sum of bond: \$ 15,000.00			
770 00 70 70 0			
Surety's bond number:KO 29 72 70 0			

Know All Persons By These Presents, That we, the Principal and Surety(ies) hereto are firmly bound to the Illinois Environmental Protection Agency (hereinafter called IEPA), in the above penal sum for the payment of which we bind ourselves, our heirs, executors, administrators, successors, and assigns jointly and severally; provided that, where the Surety(ies) are corporations acting as co-sureties, we, the Sureties, bind ourselves in such sum "jointly and severally" only for the purpose of allowing a joint action or actions against any or all of us, and for all other purposes each Surety binds itself, jointly and severally with the Principal, for the payment of such sum only as is set forth opposite the name of such Surety, but if no limit of liability is indicated, the limit of liability shall be the full amount of the penal sum.

This Agency is authorized to require, pursuant to Illinois Revised Statutes, 1981, Chapter 111 1/2, Section 21(f), that this information be submitted to the Agency by the owner or operator of a hazardous waste storage, treatment or disposal site. Failure to provide the information may result in a civil penalty against the owner or operator of not to exceed \$25,000 per day of violation. Falsification of this information by any person may constitute a Class 4 felony, and may also carry a fine for the first offense of not to exceed \$25,000 per day. This form has been approved by the Forms Management Center.

Whereas said Principal is required, under the Environmental Protection Act, Ill. Rev. Stat. 1981, ch. 111 1/2, par. 1001 et seq., as amended, to have a primit in order to own or operate each hazardous waste management facility identified above, and

Whereas said Principal is required to provide financial assurance for closure, or closure and post-closure care, as a condition of the permit, and

Whereas said Principal shall establish a standby trust fund as is required when a surety bond is used to provide such financial assurance;

Now, Therefore, the conditions of this obligation are such that if the Principal shall faithfully perform closure, whenever required to do so, of each facility for which this bond guarantees closure, in accordance with the closure plan and other requirements of the permit as such plan and permit may be amended, pursuant to all applicable laws, statutes, rules, and regulations, as such laws, statutes, rules, and regulations may be amended.

And, if the Principal shall faithfully perform post-closure care of each facility for which this bond guarantees post-closure care, in accordance with the post-closure plan and other requirements of the permit, as such plan and permit may be amended, pursuant to all applicable laws, statutes, rules, and regulations, as such laws, statutes, rules, and regulations may be amended.

Or, if the Principal shall provide alternate financial assurance as specified in Subpart H of 35 Illinois Administrative Code Part 724, and obtain the IEPA Director's written approval of such assurance, within 90 days after the date notice of cancellation is received by both the Principal and the IEPA Director from the Surety(ies), then this obligation shall be null and void, otherwise it is to remain in full force and effect.

The Surety(ies) shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.

Upon notification by the IEPA Director that the Principal has been found in violation of the closure requirements of 35 Illinois Administrative Code Part 724, for a facility for which this bond guarantees performances of closure, the Surety(ies) shall either perform closure in accordance with the closure plan and other permit requirements or place the closure amount guaranteed for the facility into the standby trust fund as directed by the IEPA Director.

Upon notification by the IEPA Director that the Principal has been found in violation of the post-closure requirements of 35 Illinois Administrative Code Part 724 for a facility for which this bond guarantees performance of post-closure care, the Surety(ies) shall either perform post-closure care in accordance with the post-closure plan and other permit requirements or place the post-closure amount guaranteed for the facility into the standby trust fund as directed by the IEPA Director.

Upon notification by the IEPA Director that the Principal has failed to provide alternate financial assurance as specified in Subpart H of 35 Illinois Administrative Code Part 724, and obtain written approval of such assurance from the IEPA Director during the 90 days following receipt by both to Principal and the IEPA Director of a notice of cancellation of the bond, the Surety(ies) shall place funds in the amount guaranteed for the facility (into the standby trust fund as directed by the IEPA Director.

The surety (ies) hereby waive(s) notification of amendments to closure plans, permits, applicable laws, statutes, rules, and regulations and agrees that no such amendment shall in any way alleviate its (their) obligation on this bond.

The liability of the Surety (ies) shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety (ies) hereunder exceed the amount of said penal sum.

The Surety(ies) may cancel the bond by sending notice of cancellation by certified mail to the owner or operator and to the IEPA Director, provided, however, that cancellation shall not occur during the 120 days beginning on the date of receipt of the notice of cancellation by both the Principal and the IEPA Director, as evidenced by the return receipts.

The principal may terminate this bond by sending written notice to the Surety(ies), provided, however, that no such notice shall become effective until the Surety(ies) receive(s) written authorization for termination of the bond by the IEFA Director.

(The following paragraph is an optional rider that may be included but is not required. If the parties do not choose to include this option, please block out the following paragraph.)

Principal and Surety(ies) hereby agree to adjust the penal sum of the bond yearly so that it guarantees a new closure and/or post-closure amount, provided that the penal sum does not increase by more than 20 percent in any one year, and no decrease in the penal sum takes place without the written permission of the IEPA Director.

In Witness Whereof, The Principal and Surety(ies) have executed this Performance Bond and have affixed their seals on the date set forth above.

The persons whose signatures appear below hereby certify that they are authorized to execute this surety bond on behalf of the Principal and Surety (ies).

Signature	Signature
Typed Name James P. Strang	Typed Name
Title Corporate Director-Assistant Treasurer	Title
Date March 27, 1985	Date
Corporate seal	Corporate seal
Corporate Surety(ies)	
Name INSURANCE COMPANY OF NORTH AMERICA	Name
Address 5757 Wilshire Blvd., Los Angeles, Ca. 90036	Address
State of incorporation Pennsylvania	State of incorporation
Liability limit \$ In excess of \$75,000,000.00	Liability limit \$
Signature Jun All	Signature
	Typed name
Typed name Daniel Ortiz	

Corporate seal

Corporate seal

Philip Trass

Johnson & Higgins of Illinois, Inc.

101 N. Wacker Dr.

Chicago, Illinois 60606

## Co-surety(ies)

Name	Name	1 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Address	Address	
State of incorporation	State of incorporation	And the state of the state of
Liability limit \$	Liability limit \$	
Signature	Signature	
Typed name	Typed name	The state of the s
Title	Title	

Corporate seal

Corporate seal

Bond premium: \$ <u>113.00</u>

(13)

# POWER OF ATTORNEY

620114

# INSURANCE COMPANY OF NORTH AMERICA

PHILADELPHIA, PA.

**Know all men by these presents:** That INSURANCE COMPANY OF NORTH AMERICA, a corporation of the Commonwealth of Pennsylvania, having its principal office in the City of Philadelphia, Pennsylvania, pursuant to the following Resolution adopted by the Board of Directors of the said Company on May 28, 1975, to wit:

"RESOLVED, pursuant to Articles 3.6 and 5.1 of the By-Laws, the following Rules shall govern the execution for the Company of bonds, undertakings, recognizances, contracts and other writings in the nature thereof:

- (1) That the President, or any Vice-President, Assistant Vice-President, Resident Vice-President or Attorney-in-Fact, may execute for and in behalf of the Company any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof, the same to be attested when necessary by the Secretary, an Assistant Secretary or a Resident Assistant Secretary and the seal of the Company affixed thereto; and that the President or any Vice-President may appoint and authorize Resident Vice-Presidents, Resident Assistant Secretaries and Attorneys-in-Fact to so execute or attest to the execution of all such writings on behalf of the Company and to affix the seal of the Company thereto.
- (2) Any such writing executed in accordance with these Rules shall be as binding upon the Company in any case as though signed by the President and attested by the Secretary.
- (3) The signature of the President or a Vice-President and the seal of the Company may be affixed by facsimile on any power of attorney granted pursuant to this Resolution, and the signature of a certifying officer and the seal of the Company may be affixed by facsimile to any certificate of any such power, and any such power or certificate bearing such facsimile signature and seal shall be valid and binding on the Company.
- (4) Such Resident Officers and Attorneys-in-Fact shall have authority to certify or verify copies of this Resolution, the By-Laws of the Company, and any affidavit or record of the Company necessary to the discharge of their duties.
- (5) The passage of this Resolution does not revoke any earlier authority granted by Resolution of the Board of Directors on June 9, 1953."

does hereby nominate, constitute and appoint WALLACE C. DOYLE and DANIEL ORTIZ, both of the City of Los Angeles, State of California

City of Los Angeles, State of California
Province the first making the province of the first state of the first
, each individually if there be more than one named, its true and lawful attorney-in-fact, to make, execute, seal and deliver on its behalf, and as its act and deed any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof. And the execution of such writings in pursuance of these presents, shall be as binding upon said Company, as fully and amply as if they had been duly executed and acknowledged by the regularly elected officers of the Company at its principal office.  IN WITNESS WHEREOF, the said MICHAEL B. FODOR , Vice-President, has hereunto subscribed his name and affixed the corporate seal of the said INSURANCE COMPANY OF NORTH AMERICA this 22nd day of March 19 83
TO THE PARTY OF TH
DATE 09/20/18 INSURANCE COMPANY OF NORTH AMERICA
RIN #
(SEAL) by WICHAEL B. FODOR Vice-President
MICHAEL B. FODOR
STATE OF PENNSYLVANIA COUNTY OF DELAWARE SS.
On this day of, A. D. 19, before me, a Notary
Public of the COMMONWEALTH OF PA. in and for the County of DELAWARE came
MICHAEL B. FODOR, Vice-President of the INSURANCE
COMPANY OF NORTH AMERICA to me personally known to be the individual and officer who executed the preceding
instrument, and he acknowledged that he executed the same; that the seal affixed to the preceding instrument is the corporate seal of said Company; that the said corporate seal and his signature were duly affixed by the authority and
direction of the said corporation, and that Resolution, adopted by the Board of Directors of said Company, referred to
in the preceding instrument, is now in force.
IN TESTIMONY WHEREOF, I have hereunto set my hand and affixed my official seal at the City of the day and year first above written.
JOAN LOUGHRAN - Notary Public
(SEAL)  Upper Darby, Delaware County, Pa:  Notary Public.
My commission expires
I, the undersigned, Wisistant Secretary of INSURANCE COMPANY OF NORTH AMERICA, do hereby certify that the original POWER OF ATTORNEY, of which the foregoing is a full, true and correct copy, is in full force and effect.
In witness whereof, I have hereunto subscribed my name as ASSECTION Secretary, and affixed the corporate seal
In witness whereof, I have hereunto subscribed my name as Assistant Secretary, and affixed the corporate seal of the Corporation, this 27th day of March 19.85

(SEAL)

# **TSD File Inventory Index**

Date Jane 18, 2004 Initial CM General

acility Name harthroad Guranman	) Sip	Tens Crentin (Two Felder Site)	
Facility Identification Number	2000	25 128 98X	
A.1 General Correspondence		B.2 Permit Docket (B.1.2)	
A.2 Part A / Interim Status		1 Correspondence	
1 Correspondence		.2 All Other Permitting Documents (Not Part of the ARA)	
.2 Notification and Acknowledgment		C.1 Compliance - (Inspection Reports)	1
.3 Part A Application and Amendments	V	C.2 Compliance/Enforcement	
4 Financial Insurance (Sudden, Non Sudden)	1/-	.1 Land Disposal Restriction-Notifications	17
5 Change Under Interim Status Requests		.2 Import/Export Notifications	
6 Annual and Biennial Reports		C.3 FOIA Exemptions - Non-Releasable Documents	+
A.3 Groundwater Monitoring		D.1 Corrective Action/Facility Assessment	T
1 Correspondence		1 RFA Correspondence	
2 Reports		.2 Background Reports, Supporting Docs and Studies	+
A.4 Closure/Post Closure	1	.3 State Prelim, Investigation Memos	
1 Correspondence		4 RFA Reports	1
2 Closure/Post Closure Plans, Certificates, etc		D. 2 Corrective Action/Facility Investigation	1
A.5 Ambient Air Monitoring	<del>-   \</del>	1 RFI Correspondence	+
1 Correspondence		.2 RFI Workplan	$\dagger$
2 Reports		3 RFI Program Reports and Oversight	
B.1 Administrative Record		4 RFI Draft /Final Report	7

Total -2

5 RELQAPP	7 Lab data   Soil Sampling/Groundwater
6 RFI QAPP Correspondence	8 Progress Reports
7 Lab Data, Soil-Sampling/Groundwater	D.5 Corrective Action/Enforcement
8 RFI Progress Reports	1 Administrative Record 3008(h) Order
9 Interim Measures Correspondence	.2 Other Non-AR Documents
10 Interim Measures Workplan and Reports	D.6 Environmental Indicator Determinations
0.3 Corrective Action/Remediation Study	1 Forms/Checklists
1 CMS Correspondence	E. Boilers and Industrial Furnaces (BIF)
.2 Interim Measures	.1 Correspondence
3 CMS Workplan	.2 Reports
4 CMS Draft/Final Report	F Imagery/Special Studies (Videos, photos, disks, maps, blueprints, drawings, and other special materials.)
5 Stabilization	G.1 Risk Assessment
6 CMS Progress Reports	.1 Human/Ecological Assessment
.7 Lab Data, Soil-Sampling/Groundwater	.2 Compliance and Enforcement
D.4 Corrective Action Remediation Implementation	.3 Enforcement Confidential
1 CMI Correspondence	.4 Ecological - Administrative Record
2 CMI Workplan	.5 Permitting
3 CMI Program Reports and Oversight	.6 Corrective Action Remediation Study
4 CMI Draft/Final Reports	.7 Corrective Action/Remediation Implementation
.5 CMI QAPP	.8 Endangered Species Act
6 CMI Correspondence	9 Environmental Justice

Note Transmittal Letter to Be included with Reports
Comments Dournals as net justify induded filder perochedule

A.2 Part A/ Interim Status

NORTHROP GRUMMAN

May 2, 2001

Ms. Nikki Burkett State of Illinois Environmental Protection Agency Division of Land Pollution Control 1021 N. Grand Avenue, East P.O. Box 19276 Springfield, IL 62794-9276

Re:

Corporate Name Change

Dear Ms. Burkett:

Electronic Sensors and Systems Sector

Northrop Grumman Corporation

Post Office Box 17319 Baltimore, Maryland 21203

PROGRAM MANAGEMENT BRANCH Waste, Pesticides & Toxics Division U.S. EPA - REGION 5

RECEIVED

MAY 1 6 2001

IEPA-DLPC

Please be advised that on April 2, 2001, Northrop Grumman Corporation changed its name to Northrop Grumman Systems Corporation and became a wholly owned subsidiary of a holding company known as Northrop Grumman Corporation. Northrop Grumman Systems Corporation will continue to hold all assets and liabilities presently held, and all information regarding the facilities and their points of contact will remain unchanged. This name change will not result in a change in the facilities' operations, and we will continue to comply with all current requirements and/or conditions. The following is a list of the affected facilities and their respective EPA Identification numbers:

- Northrop Grumman, Defensive Systems Division ILR000045963 1605 Rohlwing Road
- Northrop Grumman, Defensive Systems Division ILD981088826 520 Hicks Road
- Northrop Grumman, Defensive Systems Division / ILD005128988 600 Hicks Road

Thank you for your attention to this matter. If you have any questions or need further information, please feel free to call me at (410) 765-8832.

Very truly yours,

Kip Keenan, Manager Environmental Resources ES3

cc:

Dick Grieves

Northrop Grumman

David Gurrie

Northrop Grumman

CERT/RR: 7000 1670 0005 4527 6662

RCRA RECURUS KUUM sticides O Toxics Division

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

111 West Jackson Blvd. CHICAGO, ILLINOIS 60604

REPLY TO ATTENTION OF

APR 1 6 1982

Anthony Swetonic, Facility Engineer - Manager Northrop Corporation - Defense Systems Division 600 Hicks Road Rolling Meadows, Illinois 60008

RE: Interim Status Acknowledgement USEPA ID No. ILD 005 128 988 FACILITY NAME: NORTHROP CORPORATION - DEFENSE SYSTEMS DIVISION

Dear Mr. Swetonic:

This is to acknowledge that the U.S. Environmental Protection Agency (USEPA) has completed processing your Part A Hazardous Waste Permit Application. It is the opinion of this office that the information submitted is complete and that you, as an owner or operator of a hazardous waste management facility, have met the requirements of Section 3005(e) of the Resource Conservation and Recovery Act (RCRA) for Interim Status. However, should USEPA obtain information which indicates that your application was incomplete or inaccurate, you may be requested to provide further documentation of your claim for Interim Status. Our opinion will be reevaluated on the basis of this information.

As an owner or operator of a hazardous waste management facility, you are required to comply with the interim status standards as prescribed in 40 CFR Parts 122 and 265, or with State rules and regulations in those States which have been authorized under Section 3006 of RCRA. In addition, you are reminded that operating under interim status does not relieve you from the need to comply with all applicable State and local requirements.

The printout enclosed with this letter identifies the limit(s) of the process design capacities your facility may use during the interim status period. This information was obtained from your Part A Permit application. If you wish to handle new wastes, to change processes, to increase the design capacity of existing processes, or to change ownership or operational control of the facility, you may do so only as provided in 40 CFR Sections 122.22 and 122.23.

As stated in the first paragraph of this letter, you have met the requirements of 40 CFR Part 122.23; your facility may operate under interim status until such time as a permit is issued or denied. This will be preceded by a request from this office or the State (if authorized) for Part B of your application. Please contact Arthur Kawatachi of my staff at (312) 886-7449, if you have any questions concerning this letter or the enclosure.

Sincerely yours,

Karl J. Klepitsch, Jr., Chie

Waste Management Branch

TB\$ 92

Enclosure

cc: J. J. McNaughton, Vice President - Financial Management

## FACILITY NAME

NORTHROP CORPORATION DEFENSE SYSTEMS DIV

EPA ID NUMBER

FACILITY OPERATOR

NORTHROP CORP DEFENSE SYSTEMS DIV

RETYPE

FACILITY OWNER

NORTHROP CORP DEFENSE SYSTEMS DIV

FACILITY LOCATION

600 HICKS RD

ROLLING MEADOWS

IL 60008

PROCESS CODE

DESIGN CAPACITY

UNIT OF MEASURE

501

5811,00000

G

******	90 NY 50 NO DE DE DE		1965 FOLK STOR (		1 55 58 58 58 50 M
	PRO-	APPROPRIATE	*		
	CESS	UNITS OF	*	UNIT OF .	
PROCESS	CODE	MEASURE	*	MEASURE	CODE
南京市市区市区市区市区市区市区市区市区市区市区市区市区市区市区市区市区市区市区市	医医尿管切迹板	医囊骨管管理 医皮肤结合	茶	<b>医乳体 100 医医皮肤 医皮肤 100 医皮肤</b>	
STOPAGE:			· *	GALLONS	G
sact poor coar year part 1991 sans			44	LITERS	L
CONTAINER	S01	G OR L	*	CUBIC YARDS	Ϋ́ L
TANK	502	G OR L	荣	CUBIC METERS	C
WASTE PILE	503	Y OR C	黄	GALLONS PER DAY	Ū
SURFACE IMPOUNDMENT	504	G OR L	*	LITERS PER DAY	V
DISPOSAL:			黄	TONS PER HOUR	D
COLUMN TWO SAME AREA TOWN AREA (AND			*	METRIC TONS\HOUR	W
INJECTION WELL	D79	G.L.U. OR V	*	GALLONS\HOUR	E
LANDFILL	D80	A OR F	*	LITERS\HOUR	H
LAND APPLICATION	D81	B OR Q	幹	ACRE-FEET	A
OCEAN DISPOSAL	D82	U OR V	*	HECTAPE-METER	F
SURFACE IMPOUNDMENT	D83	G OR L	*	ACRES	В
TREATMENT:	een tot wat	40 00 00	àb.	HECTARES	Ğ.
the age and one had the one feet age			**	POUNDS\HOUR	J
TANK	TO1	U OR V	帧	KILOGRAMS\HOUR	R
SURFACE IMPOUNDMENT	T02	U OR V	*	TONS PER DAY	N
INCINERATOR	T03	D.W.E. OR H	華	METRIC TONS\DAY	S
OTHER	104	J,R,N,S,U,V	*	mettre enminer.	i)



## ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY (VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER	*	ILD005128988	REACKNOWLE	DGEMENT
		NORTHROP CORPORA 600 HICKS RD ROLLING MEADOWS		60008
INSTALLATION ADDRESS		600 HICKS RD	IL	60008

EPA Form 8700-12B (4-80)

09/28/81

Please print or type	e with ELITE type (12	c' ers/inch) in the uns	haded areas only.		orm Approved OMB No. 158-S7901 SA No. 0246-EPA-OT
& EPA	NOTIFICATI	O. OF HAZARDOL			CTIONS: If you received a preprin-
INSTALLA- TION'S EPA .D. NO.		oK		0 Informathrough	iffix it in the space at left. If any of the ation on the label is incorrect, draw a line in it and supply the correct information.
I. STALLATION	_ 1LD0051289	<b>788</b>		comple	appropriate section below. If the label is te and correct, leave Items I, II, and III blank, If you did not receive a preprinted
INSTALLA- TION II. MAILING ADDRESS	MORTHROP C 600 HICKS ROLLING MEAL	ORFORATION RD OWS IL 6000	° 000117	AUG 20 PO er's to the CATIO	complete all items. "Installation" means a site where hazardous waste is generated, , stored and/or disposed of, or a trans- s principal place of business. Please refer INSTRUCTIONS FOR FILING NOTIFI- IN before completing this form. The
III OF INSTAL- LATION	600 HICKS ROLLING MEAT		8	(Section	ation requested herein is required by law in 3010 of the Resource Conservation and iry Act).
FOR OFFICIAL	USE ONLY				
C		COMM	MENTS		
C 15 16					55
s I I I	ION'S EPA I.D. NUM	BER APPROVED	OATE RECEIVED (yr., mo., & day)		
F		1 1 16	700010		
I. NAME OF IN	STALLATION				
30					67
II. INSTALLAT	ION MAILING AD				
c I I I		STREET OR P.O. BOX			
3 15 16		5 U 1 C		45	
<u>c.</u>	CITÝ	OR TOWN	s	T. ZIP CODE	
4			40 41	42 47 -	510
III. LOCATION	OF INSTALLATIO	ET OR ROUTE NUMBER			
c	JIRE	- OR ROUTE NUMBER			
5 15 16				45	The second secon
e I I I	CITY	OR TOWN		T. ZIP CODE	
15   16			40 41	42 47 -	51
IV. INSTALLA	FION CONTACT	ID TITLE (last, first, & job	title)	Edition of P	HONE NO. (area code & no.)
SWETC			ACILENG	M G R.3	12.870.5710
V. OWNERSHIE				45 46	- 48 49 - 51 52 - 55
		A. NAME OF INSTALL	ATION'S LEGAL OWN	ER	
8 NORTE	ROPCO	RPORATIO	n dsd	20 20 4 7 1	en para vives successións fi
B. TYPE OF	OWNERSHIP riate letter into box)	VI. TYPE OF HAZARI	OUS WASTE ACT	IVITY (enter "X	"in the appropriate box(es))
F = FEDERA		X A. GENERATI	ION	B. TRANSI	PORTATION (complete item VII)
M = NON-FI	EDERAL 56	C. TREAT/ST		60	GROUND INJECTION
VII. MODE OF		N (transporters only – e			120 mars 120 mm to make make a
A. AIR	B. RAIL	C. HIGHWAY	D. WATER	E. OTHER (specif	y):
	SUBSEQUENT NO		tallation's first notifica	tion of hazardous	waste activity or a subsequent notification.
his is not your f	irst notification, enter	your Installation's EPA I.D	. Number in the space	provided below.	
					C. INSTALLATION'S EPA I.D. NO.
X A. FIRS	TNOTIFICATION	B. SUBSEQUENT	NOTIFICATION (co	mplete item C)	1140005128488
TOO WILLIAM TO SHOULD SEE THE SECOND	ON OF HAZARDO				
Please go to the rev	NAME AND ADDRESS OF TAXABLE PARTY.	provide the requested inform	nation.	: 1 8 198N	CONTINUE ON REVERSE

	ES (continued from )		A STATE OF THE PARTY OF THE PAR	Charles and the same of the sa
ROM NON—SPECIFIC ources your installation	SOURCES. Enter the handles. Use additional	four—digit number from Il sheets if necessary.	40 CFR Part 261.31 fo	or each listed hazardous
2	3	4 4 4	5	6
FIOLOIS				
	23 - 26	23 - 26	23 - 26	23 - 26
8 101	9	10	11	12
	22 26	22 26	23 26	23 • 25
BOM SPECIFIC SOUR	100		R Part 261.32 for each	fisted hazardous waste f
your installation handle	s. Use additional sheets	if necessary.		
14	15	16	17	18
			22 26	23 - 26
	21	22	23	2.4
				Desire La Tarres
		23 5 22	22 24	23 - 26
2.6	27	28	29	30
				23 25
23 - 26 A	DOUS WASTES Enter		from 40 CEB Part 261	
indles which may be a h	azardous waste. Use ad	ditional sheets if necessa	rry.	
	- p			36
32				
P 0 3 0	U 0 0 2			
23 - 26	23 - 26	23 - 26		23 - 26
38	39	1111		
				Card Sale
23 - 26	2,3 26	23 - 26	23 - 26	48
44	45	46	47	
23 - 26	23 - 26	23 - 26	23 + 26	23 - 26
ASTES. Enter the four	-digit number from 40	CFR Part 261,34 for ea	ch listed hazardous was	te from hospitals, veterii
		e diamental and the training	SCHOOL A.	
50	51	52	53	54
				54
50	5 [	52	53	23 - 26
50 23 - 26 NON-LISTED HAZA	51 23 - 26 RDOUS WASTES. Mar	52 23 25 k''X'' in the boxes corre	53	23 - 26
50 23 - 26 NON-LISTED HAZA	5 [	52 23 25 k''X'' in the boxes corre	53	23 - 26 teristics of non-listed
NON-LISTED HAZAI tallation handles. (See	DOUS WASTES. Mar 40 CFR Parts 261.21 —	52  23 25  k "X" in the boxes corre 261.24.)	53 23 - 26 esponding to the charac	teristics of non–listed
NON-LISTED HAZAI tallation handles. (See	51 23 - 26 RDOUS WASTES, Mar 40 CFR Parts 261.21 -	52 23 25 k "X" in the boxes corre	53 23 - 26 esponding to the charac	23 - 26 teristics of non-listed
NON-LISTED HAZAI tallation handles. (See	DOUS WASTES. Mar 40 CFR Parts 261.21 —	52  23 25  k "X" in the boxes corre 261.24.)	53 23 - 26 esponding to the charac	teristics of non–listed
NON-LISTED HAZAI tallation handles. (See  LE  of law that I have and that based on my itted information is	RDOUS WASTES. Mar 40 CFR Parts 261.21 — 2. CORROSIVE 002)  personally examined inquiry of those ind true, accurate, and of	x"X" in the boxes corrected. (D003)  and am familiar with dividuals immediately complete. I am aware	esponding to the characterive  the information storesponsible for obt	teristics of non-listed  4. TOXIC (D000)  Abmitted in this and aining the informatic
NON-LISTED HAZAI tallation handles. (See  LE  of law that I have and that based on my itted information is	RDOUS WASTES. Mar 40 CFR Parts 261.21 — 2. CORROSIVE 002)  personally examined inquiry of those in true, accurate, and of ibility of fine and im	by the state of th	esponding to the characterive  the information storesponsible for obter that there are signi	teristics of non-listed    4. TOXIC (D000)  ubmitted in this and aining the informatic ficant penalties for su
NON-LISTED HAZAI tallation handles. (See  LE  of law that I have and that based on my itted information is	RDOUS WASTES. Mar 40 CFR Parts 261.21 — 2. CORROSIVE 002)  personally examined inquiry of those in true, accurate, and of ibility of fine and im	x"X" in the boxes corrected. (D003)  and am familiar with dividuals immediately complete. I am aware	esponding to the characterive  the information storesponsible for obter that there are signi	teristics of non-listed  4. TOXIC (D000)  Abmitted in this and aining the informatic
NON-LISTED HAZAI tallation handles. (See  LE  of law that I have and that based on my itted information is	RDOUS WASTES. Mark 40 CFR Parts 261.21—  2. CORROSIVE  12. CORROSIVE  14. Personally examined inquiry of those incitrue, accurate, and cibility of fine and im	by the state of th	isponding to the characterive  the information storesponsible for obter that there are significantly	teristics of non-listed    4. TOXIC (D000)  ubmitted in this and aining the informatic ficant penalties for su
	POUCT HAZAR andles which may be a hazar 26 and 26 a	POUT installation handles. Use additional and a section of the sec	as pources your installation handles. Use additional sheets if necessary.    2	2

600 Hicks Road Rolling Meadows, Illinois 60008

> Telephone: 312/259-9600 TWX: 910/687-3785

March 16, 1984

Mr. William H. Miner, Chief Technical, Permits, and Compliance Section United States Environmental Protection Agency Region V 230 South Dearborn Street, Chicago, IL 60604



Re: Part A Permit Application ILD 005128988 GTSD, PA

Dear Mr. Miner:

The attached revised Part A permit application is being submitted in response to your written request of January 10, 1984. If there are any questions regarding our application, please contact Lisa Riggle at 259-9600, Ext. 5957.

Respectfully submitted,

President, Financial Management

Prepared by: Lisa Riggle

Chemical Engineer Northrop Corp. D.S.D.

dp

Attachment

c: A. Swetonic

## NORTHROP

600 Hicks Road Rolling Meadows, Illinois 60008

> Telephone: 312/259-9600 TWX: 910/687-3785

December 16, 1983

John McGuire Federal E.P.A. Regional Administrator Region 5 230 S. Dearborn Street Chicago, Illinois 60604

> E.P.A. I.D. #ILD 005128988 G. TSO PA

Dear Sir:

This letter is to inform you that Northrop Corporation's Defense Systems Division, at 600 Hicks Road is expanding its facility. The 40,000 sq. ft. addition will contain offices, electronic labs and an area for hazardous waste treatment.

Attached, for your reference, is a plan showing the expansion with existing and future hazardous waste areas indicated.

Sincerely,

McNaughton Vice President, Financial Mgm't.

Northrop Corporation

Defense Systems Division

600 Hicks Road


Rolling Meadows, IL 60008

Richard Carlson, Ill. E.P.A.

A. Swetonic, Northrop Corp.

Attachment

BRAN June 12 June 1



VII. SIC CODES (4-digit, in order of priority)			MAN Y		· · ·
A. FIRST		c 1 1 1	Langeiful	B. SECOND	
3, 6, 7, 9 (specify) HAZARDOUS WASTE		7	(specify)		0
C. THIRD		15/16 - 19		D. FOURTH	Market Compression
(specify)		7	(specify)		
5 16 - 19		15 16 - 19			
/III. OPERATOR INFORMATION	A. NAME				B. Is the name listed in
<u> </u>			1 1 1 1 1		Item VIII-A also the owner?
N O, R, T, H, R, O, P, , C, O, R, P,	, D, E, F, E, N, S, E,	S, Y, S, T, E, I	MS DIV	ISION	YES NO
5 16	-	nuar have if "Other	2. manifort	Terror	55
F = FEDERAL M = PUBLIC (other the		(specify)	, specify.)		(area code & no.)
S = STATE O = OTHER (specify) P = PRIVATE	P 56				2 5 9 9 6 0 0
	OR P.O. BOX				
6, 0, 0, 1, 1, C, K, S, 1, R, O, A, D,					
			55	IN INDIAN LAND	
F. CITY OR TO		G.STAT		IX, INDIAN LAND	The second secon
B ROLLING MEADOL	V S	1 L	60008	☐ YES	⊠ NO
5 16		40 41 42	47 - 51	52	
C. EXISTING ENVIRONMENTAL PERMITS	AND STATE OF				
A. NPDES (Discharges to Surface Water)		ons from Proposed	Sources)		
0 N D N A	9 P D N A		1 1 30		
B. UIC (Underground Injection of Fluids)	The state of the s	HER (specify)			
D N A	9 DNA		(spec	ify)	LET AT THE PLAN TO BE
5 16 17 18	30 15 16 17 18	upp (angeiful	30		
C. RCRA (Hazardous Wastes)	E. 01	HER (specify)	(spec	ify)	
D R D N A	9 DNA		30		
XI. MAP			To the managed to		
Attach to this application a topographic r	nap of the area extending	to at least one r	nile beyond pro	perty bounderies.	The map must show
the outline of the facility, the location of treatment, storage, or disposal facilities,	reach of its existing and and each well where it is	proposed intake niects fluids under	e and discharge erground Include	structures, each of de all springs river	its hazardous waste
water bodies in the map area. See instructi				so an opinigo, niver	J dire Garage
XII. NATURE OF BUSINESS (provide a brief de	scription)				
THE PROPERTY OF THE PARTY OF TH					
ELECTRONIC COUNTER M	TACUDES DEEENSE	CVCTEMC			
ELECTRONIC COUNTER M	EASURES - DEFENSE	STOTEMS			
		-			
				an water	¥
XIII. CERTIFICATION (see instructions)				Mark united	
I certify under penalty of law that I have	personally examined an	d am familiar wit	h the information	on submitted in thi	is application and all
attachments and that, based on my inquapplication, I believe that the information	ury of those persons in n is true, accurate and c	nmediately respo omplete. I am av	nsible for obtai ware that there	ning the informati are significant nen	on contained in the
false information, including the possibility	of fine and imprisonme	nt.		are significant pen	arries for submitting
A. NAME & OFFICIAL TITLE (type or print)	B. SIGN	ATURE )	no	C.	DATE SIGNED
John J. McNaughton	the	1. 5	aug th		3/15/84
Vice President, Financial M	anagement				
C					
C , , , , , , , , , , , , , , , , , , ,					

15 16 EPA Form 3510-1 (6-80) REVERSE

Pleas (fill-	e p	rint o	er to	pe in the unshaded a spaced for elite type	reas or	nly 2 charanter	s/ir	nch).									For	m Approve	ed OMB No.	158	-580	0004		
FO		NA NA	3	EPA		ZAR JI	US	WA	AST	E P	ERN	AIT Pro	gram	PL	IC	A1	rion 5	TIT	0 0 5 1	2	8	9	8 8	T/A C
		FFI	CL	L USE ONLY			VE.	200		1														
				DATERECEIVED												CO	MMENTS							
AP	2	OVE		(yr., mo., & day)																- Ardes			Œ	
II. I	IR	ST (	OR	REVISED APPLI	CATIO	ON																		TOTAL SE
Place revis EPA	e an ed a	"X" applie . Nu	in eati	the appropriate box on. If this is your fir er in Item I above.	in A or	B below (nication and	you	u alrı	eady	knov	you	r fa	cility'	vhet 's El	her	thi	is is the first applica . Number, or if this	ition you a is a revised	are submittin d application	g fo	r yo ter y	ur fa our	cility facili	or a ty's
A. F				PLICATION (place STING FACILITY (S	ee insti		de	finit									71 2	NEW FAC		OR	NEV	V FA	CILI	TIES,
8	7	YR.		OPER (use t	he box	ING FACII N BEGAN es to the le	or ft)	THE	DA	TEC	ONST	RU	стіс					74 75 76	DAY (N	ION	BE	& do	y) OI OR O BE	PERA-
В, 1	10000			APPLICATION (p			) an	a co	mpie	te Ite	m 1 a	000	e)		-	-	72	FACILIT	Y HAS A R	CRA	PE	RMI	т	
III.	PR	OCI	SS	ES - CODES AN	D DES	IGN CAP	AC	ITI	ES	AV II	No.	Wir.									3.0	HE IN	Fig.	SHIPS !
6	nte	ring (	cod	ODE — Enter the cores. If more lines are process (including its	needed	, enter the	cod	e(s)	in th	e spai	ce pro	pivid	ed. I	far	proc	ess	will be used that is	ed at the fa not includ	acility. Ten l ded in the list	ines t of	are code	pro es be	ided low,	for then
B. F	RO	CES	SD	ESIGN CAPACITY -	- For e	ach code e	nter	ed in	col	ımn .	A ent	er ti	he cap	paci	ty c	of t	he process.							1911
1	. 1	OMA	JN	T - Enter the amoun	it.													and the first						7.00
2				MEASURE - For e used. Only the units										ie tr	om	the	e list of unit measur	e codes be	low that des	CLID	es tr	ie ur	III OT	
	1.	icase	110	With the second section of the second	PRO-	APPROP							Jou.					PRO-	APPROP	RIA	TE	LIMI	TS O	=
					CESS	MEASU	RE	FOR	PRO	CES								CESS	MEASUF	REF	OR	PRO	CES	
-	_		PR	OCESS	CODE	DESI	GN	CAI	ACI	TY	-			-	-	PR	OCESS	CODE	DESI	GN	CAP	AC	TY	
-	orag			We are a will also a second						-			Trea		nt:	_								
	IN		ER	(barrel, drum, etc.)	501	GALLON	50	R LI	TER				TAN					T01	GALLONS LITERS P	ER	DAY	-		7 74
W	AST	E PI	LE		503	CUBIC Y	ETE	RS									POUNDMENT	T02	GALLONS LITERS P	ERI	DAY			
			HM	POUNDMENT	504	GALLON	s o	RLI	TER	S			INC	INE	RA	то	R	T03	TONS PER					1;
	_	sal:		(m. )	D70	C * 1 1 ON	~ ~			_									GALLONS LITERS P				OR	
		FIL		/ELL	D79 D80	GALLON ACRE-FE	ET	(the	volu	me th	at		OTH	ER	(U	se f	or physical, chemic	al, T04	GALLONS LITERS P				OR	100
						would cov depth of c	me	foot,	OR				proc	esse	s ne	ot o	logical treatment occurring in tanks,		LITERSE	= (** )	JAI			
				CATION	D81	ACRES O	RI	HECT	ARI				ators	s. L	esc	ribe	ndments or inciner- e the processes in							1
				OSAL	D82	GALLON:	ER	DA	Y				ine s	pac	e pi	rovi	ided; Item III-C.)							
SU	RF	ACE	IM	POUNDMENT	D83	GALLON	s o	R.L.	TER	5							A ALMERICAN							
UI	VIT	OF	ИE	ASURE	MEAS COL	URE		UNI	TOF	ME	ASUF	RE	By -			ME	NIT OF EASURE CODE U	INIT OF N	MEASURE				UNIT IEAS COI	URE
				******															T					
				S				TON	FRIC	TON	SPE	RH	OUR				D H		METER					
				RS				GAL	LOP	IS PE	RH	DUF	2				E H		S					
EXA	MIF	LE	O	R COMPLETING ITE	EM III	shown in li		num	bers .	X-1 a	and X	-2 b	elow,	1: 1	fa	cili	ty has two storage t	anks, one	tank can hol	d 20	0 ga	llon	s and	the
ē C	ì	ling	P	DUP		T/A C	1	1	1	1	1	1	1	1	1	1	1111	11		1	1	1	1	1
1 2	18.		T	P Process	ALCOHOLD TO	14 15	CI	1	1	1	1	1		1		1	B. PROCES	E DECIG	NCABAC	ITV				
BER		PRO		B. PROCESS	DESI	SN CAPA	-1			1	FOR	-61	ER		PR		B. PROCES	J DESIG	IN CAPAC				F	OR
E V		ESS		1 0000	OLI BUT			OF N	MEA-	OF	FICI		m	C	ES	E		MOUNT		OF	ME	A-	OFF	SE
LINE	(fre	om li	31	1. AMC (spec				SU	RE		NLY		LINE		one		1. A	MOONI		1 6	uRi	7		ILY
JZ	4		B 1				27	co	de)	21		24	JZ	16		18	10		27	C	ode		4	- 32
V I	C			600			27	2		5.5		26	5	10		1.0					-		T	7.
V-1	S	0 2	2	000				(	7				2				a)	TK THE	TABLE TO					
X-2	T	0.	3	20				1	3				6					80						
1	ς	0		14 000				C					7											

Continued from the front.	
III. PROCESSES (continued	7
C. SPACE FOR ADDITIONAL INCLUDE DESIGN CAPACI	F

C. SPACE FOR ADDITIONAL PROCESS CODES O., FOR DESCRIBING OTHER PROCESSES (code "TO4 y. FOR EACH PROCESS ENTERED HER

IV.	DESCR	IPTION (	OF HAZA	RDOUS WA	STES
					-

- A. EPA HAZARDOUS WASTE NUMBER Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/ that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

### D. PROCESSES

- 1. PROCESS CODES:
  - For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER — Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.


2. In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.

3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

**EXAMPLE FOR COMPLETING ITEM IV** (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

			E					UNIT								. 6			D. PROCESSES
LINE NO.	W (e	AS	Z A STI er c	EN	0	B. ESTIMATED ANNUAL QUANTITY OF WASTE	5	MEA URE enter ode)		1. PROCESS CODES (enter)			5		2. PROCESS DESCRIPTION (if a code is not entered in D(I))				
X-1	K		0 .	5	4	900		P	T	0	3	L	8	3 0					000,45 1,9 2
X-2		) (	)	0	2	400		P	T	0	3	L	) 8	3 0	)			u u	os 110-T
X-3	BL	) (	2	0	I	100		P	T	0	3	L	8	3 0	)				
X-4	+ L	) (	0	0	2						1								included with above

	EPA	I.D	. N	UM	BER (enter from page 1)  5 1 2 8 9 8 8 1	lave II	lore	w w w w w w w w w w w w w w w w w w w	-	STREET, SQUARE, SQUARE	IAL USE C	Pom Approved OMB No. 158-\$80004
1 2					ON OF HAZARDOUS WASTE	S (co	ontin	1 2		DOF		13 14 15 23 - 26
LINE NO.	HA WA (en	ST	EI	D.	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C.U OF N SU (en coo	RE ter		1. PROCI	ESS CODE		2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	23 F	0	0	3	6,000	P		S 0 1	27 - 29	27 - 29	27 - 29	Recycled
2	F	0	0	5			E					Included in above
3	F	0	0	2	10,000	P		S 0 1			1 1	Recycled
4	F	0	0	1	40,000	P		S 0 1				Recycled
5	F	0	0	7	10,000	P		S 0 1				Recycled
6	Р	0	2	9	540	P		S 0 1	ı i			Destroyed off site
7	Р	0	3	0						1 1	1 1	Included in above
8	Р	1	0	4	1,700	P		S 0 1				Recycled
9	U	1	5	1	15	P		S 0 1		1		Recycled
10	D	0	0	1	8,000	P		S 0 1		1 9		
11	U	1	5	4								Included in above
12	F	0	0	6	3,600	P		S 0 1				Recycled Recycled
13	D	0	0	7								Included in above
14	D	0	0	1	15,000	P		S 0 1	T 0 1	1 1		Sludge disposed off site
15	D	0	0	2	12,000	P		S 0 1	T 0 1	1.1	1 1	Sludge disposed off site
16	Р	0	9	8	10,000	P		S 0 1	T 0 1			Sludge disposed off site
17	U	1	2	2								Included in above
18	D	0	0	3	1	P		S 0 1	T 0 1			
19	D	0	0	7	5,000	P		S 0 1	T 0 1	-		Sludge disposed off site
20								I. I	1 1		1 1	
21												
22										1 1		, , , , , , , , , , , , , , , , , , ,
23												
24					*					1 1		
25					J.						1 1	
26	23			26	27			27 - 29	27 - 20	27 - 29	27 - 29	
EPA	Form	35	510			100		The second second				CONTINUE ON REVERSE



Continued from page 4.		Form Approved OMB No. 158-S80004
V. FACILITY DRAWING (see page 4)		
567ppp		
		1
		NAME OF THE PARTY
***************************************		
SACRET IN THE SA		
		No.
A A A A A A A A A A A A A A A A A A A		
TO THE PROPERTY OF THE PROPERT		
	·	
PROPORTION		
The second secon		
CONTRACTOR OF THE CONTRACTOR O		
THE PARTY OF THE P		
Section (Fig. )		
Name of the state		
N. Company of the Com		
THEORYGINA		
RASSINGOOO		
· ·		
the second secon		
REGORDANISM		
No. of the control of		
EPA Form 3510-3 (6-80)	PAGE 5 OF 5	
ata tuni duna io-ovi	rade our o	

FEB 2 4 1983

John J. McRaughton, Vice President Morthrop Corp. Defense Systems Division 600 Hicks Road Rolling Meadows, Illinois 60008

RE: ILD 005128988

Dear Mr. McMaughton:

This is to acknowledge receipt of your amended Part A Permit Application of December 14,1982. Your company has the approval of the United States Environmental Protection Agency to increase its hazardous waste container storage capacity from 5,811 gallons to 7,600 gallons. This approval is effective retroactively as of December 20,1962.

In addition to this approval of your change during interim status, you must obtain the written approval of the Director of the Illinois Environmental Protection Agency in accordance with the provisions of Part 700.105 (c) of the Illinois hazardous waste regulations. Further, since the State of Illinois has received Phase I Interim Authorization under §3005 of the Resource Conservation and Recovery Act, you are required to comply with Part 725 of the Illinois hazardous waste regulations in lieu of the Federal regulations at 40 CFR Part 265. Operation under interim status does not relieve you of the need to comply with other applicable Federal, State and local requirements.

Please contact Mr. Greg Weber of my staff, at (312) 886-3719, if you have any questions regarding this matter.

Sincerely.

Basil G. Constanteles, Director Waste Management Division

cc: Tom E. Cavanagh, Jr., IEPA

5HW:G.WEBER:ad 2/14/83 Disk #5 No. 5 ad

DATE:

Ammendment to Part A Permit Application. Northrop Corp. Rolling Meadows, Illinois

Karl J. Klepitsch, Jr., Chief Waste Management Branch

то: B.G. Constantelos, Director Waste Management Division

- 1. Background: Increased business activity at this facility has increased production to the extent that more hazardous waste is being generated.
- 2. Part A change requested: The company wants to increase its container process design capacity from 5811 gallons to 7,600 gallons.
- 3. Results of proposed changes: This change will allow the company to store an increase of 1789 gallons of hazardous waste.
- 4. Additional information: This is a minor change to an existing facility.
- 5. Does the change constitute reconstruction as defined in 40 CFR 122.23(c)(5). Answer: No
- 6. Does the facility have interim status? Answer: Yes
- 7. Recommendation: The company should be allowed to increase its container storage capacity.
- Justification: 40 CFR 122.23(c)(2) allows an increase in design capacity because of a lack of available storage capacity.

### References:

1. EPA identification number: ILD 005128988

10HW 2/15/83

### 2. Notification:

Date: August 18, 1980 Waste Activities: G, TSD

### 3. Part A application:

Date: November 18, 1980

Design Processes: 501

Process Design Capacity: 58116

### 4. Revised Part A application

Date: December 14, 1982
Design Processes: Sol
Process Design Capacity: 7600 G

lease print or type in the unshaded areas on infill—in areas are spaced for eilte type, i.e., 12 cha		D.1	1 0-2-	Form Approved OMB No. 1	58-R0	175	
				ATION IL EPA I.D. NUMBER			T/A C
Co	nsolid Genera	ated Il Ins	Permits Pi tructions"	before starting.)	.8.9	8,6	8 D
LABELITEMS	1	1	11	If a preprinted label has b	een p	rovid	ed, affix
EPÀ I.D. NUMBÈR	1/	/	R	it in the designated space. ation carefully; if any of i	t is in	ncorre	ct, cross
III. FACILITY NAME	//	/	1/7	through it and enter the appropriate fill—in area be	low. A	Also, i	if any of
FACILITY		/	14	the preprinted data is abserted to the label space like	sts the	e info	ormation
MAILING ADDRESS PLASE PLA	ACE	LA	<b>PEDIN</b>	THIS SPACE RANGE that should appear), pleas proper fill—in area(s) below	ow. If	f the	label is
111111111111111111111111111111111111111	1	/	/ DR	complete and correct, you Items I, III, V, and VI	excep	t VI-I	B which
FACILITY		/	//	must be completed regard items if no label has been	provi	ided.	Refer to
LOCATION		/	//	the instructions for deta tions and for the legal a	uthori		
	1	/	//	which this data is collected.		Complete Company	
II. POLLUTANT CHARACTERISTICS	whotho	r 1/0	u pood to	submit any permit application forms to the EPA. If you ans	awer "	ves" 1	to any
questions you must submit this form and the supplemen	tal for	m li	sted in the	e parenthesis following the question. Mark "X" in the box in	the tr	nira co	olumn
if the supplemental form is attached. If you answer "no" is excluded from permit requirements; see Section C of the	to ea	ich q ictio	uestion, y ns. See also	ou need not submit any of these forms. You may answer "no o, Section D of the instructions for definitions of <b>bold—face</b>	I term	our ac	itivity
SPECIFIC QUESTIONS	H	MAR	K'X'	SPECIFIC QUESTIONS	YES	MAR	K'X'
A. Is this facility a publicly owned treatment works	YES	NO	ATTACHED	B. Does or will this facility (either existing or proposed)			ATTACHE
which results in a discharge to waters of the U.S.? (FORM 2A)		Χ		include a concentrated animal feeding operation or aquatic animal production facility which results in a		X	
C. Is this a facility which currently results in discharges	16	17 V	18 .	discharge to waters of the U.S.? (FORM 2B)  D. Is this a proposed facility (other than those described	19	20 X	21
to waters of the U.S. other than those described in A or B above? (FORM 2C)		X 23	24	in A or B above) which will result in a discharge to waters of the U.S.? (FORM 2D)	25	A 26	27
E. Does or will this facility treat, store, or dispose of				F. Do you or will you inject at this facility industrial or municipal effluent below the lowermost stratum con-		V	
hazardous wastes? (FORM 3)	X			taining, within one quarter mile of the well bore, underground sources of drinking water? (FORM 4)	31	X 32	22
G. Do you or will you inject at this facility any produced water or other fluids which are brought to the surface		29	30	H. Do you or will you inject at this facility fluids for spe-		34	33
in connection with conventional oil or natural gas pro- duction, inject fluids used for enhanced recovery of		Χ		cial processes such as mining of sulfur by the Frasch process, solution mining of minerals, in situ combus-		Χ	
oil or natural gas, or inject fluids for storage of liquid				tion of fossil fuel, or recovery of geothermal energy? (FORM 4)	37	38	39
hydrocarbons? (FORM 4)  1. Is this facility a proposed stationary source which is one of the 28 industrial categories listed in the in-	34	35	36	J. Is this facility a proposed stationary source which is     NOT one of the 28 industrial categories listed in the			
structions and which will potentially emit 100 tons per year of any air pollutant regulated under the		V		instructions and which will potentially emit 250 tons per year of any air pollutant regulated under the Clean		X	iii) ma
Clean Air Act and may affect or be located in an attainment area? (FORM 5)	40	X		Air Act and may affect or be located in an attainment area? (FORM 5)		A4	45
II. NAME OF FACILITY	40	Harmin					N. E.
N.O.R.T.H.R.O.PC.O.R.PD	, E , F	, E,E	N.S.E				
V, FACILITY CONTACT				restriction of the particular state of the contract of the con	69		450
A. NAME & TITLE (last, f	irst, &	title		B. PHONE (area code & no.)			
SWETONIC ANTHONY	F <i>F</i>	4 C	IL.	ENG. MGR312 259 9600	)		
/. FACILITY MAILING ADDRESS	THE STATE OF	ME	Per all	45 46 - 48 49 - 51 52 - 51			
A. STREET OR P.O.						3100	
600 HICKS ROAD							
B. CITY OR TOWN				C.STATE D. ZIP CODE			
ROLLING MEADOWS	1 1			I L 6 0 0 0 8			
VI, FACILITY LOCATION	(Section)	151	fyr grid.	40 41 42 47 - 51			STATE OF THE PARTY.
A. STREET, ROUTE NO. OR OTHER	SPECI	FIC	IDENTIF	IER .	H		
600 Hicks Road				THE PROPERTY OF THE PROPERTY O	า		
B. COUNTY NAME		A		(in line)			
COOK	TT	1		21 and 82	ט		
C. CITY OR TOWN	-			D. STATE E. ZIP CODE F. COUNTY CODE			
DOLL INC. MEADONS	TT	1	1 1 1	I L 6 0 0 0 8			
15 16				40 41 42 47 - 31 32 - 54			
EPA Form 3510-1 (6-80)				CONT	INUE	ONI	REVERS

CONTINUED FROM THE FRONT  VII. SIC CODES (4-digit, in order of priority)			
A. FIRST  (specify)	c (specify)	B, SECOND	
7 3 6 7 9 HAZARDOUS WASTES	7		
C. THIRD	(specify)	D. FOURTH	
VIII. OPERATOR INFORMATION	110		
A. NAME	! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! !		B. Is the name listed in Item VIII-A also the owner?
8 NORTHROP CORP DEFENSE S	YSTEMS, DIV	,I ,S ,I ,O ,N ,	₩ YES □ NO
C. STATUS OF OPERATOR (Enter the appropriate letter into the answ F = FEDERAL M = PUBLIC (other than federal or state) / (s	er box; if "Other", specify.) pecify)		eg code & no.)
S = STATE O = OTHER (specify) P = PRIVATE  O = OTHER (specify)  P = PRIVATE	pecify)	A 3.1.2 2.	5 9 9, 6, 0, 0 21 22 20
E, STREET OR P.O. BOX			
6 Q Q H I C K S , R Q A D ,	G.STATE H. ZIP CODE	IX. INDIAN LAND	
B ROLLING MEADOWS	I. L. 6, 0, 0, 0, 8		on Indian lands? XINO
15 16 -	40 A1 42 47 - 51	52	
	s from Proposed Sources)	santa ara Satelles en en ken	
9 N D N A 9 P D N A 35 16 17 18	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	R (specify)	Pify)	
9 U D N A 9 D N A, 15 16 17 18 30 18 16 17 18  C, RCRA (Hazardous Wastes) E. GTHE	R (specify)		
9 R D N A	(spec	ify)	aannastaa ja j
XI, MAP			
Attach to this application a topographic map of the area extending the outline of the facility, the location of each of its existing and processing and processing and processing areas of the second of the existing and processing areas of the second of the existing and processing areas of the existing and processing areas of the existing and processing areas of the existing areas of the existin	proposed intake and discharge	structures, each of its	hazardous waste
treatment, storage, or disposal facilities, and each well where it injumater bodies in the map area. See instructions for precise requirement		de all springs, rivers a	ing other surface
XII. NATURE OF BUSINESS (provide a brief description)			
ELECTRONIC COUNTER MEASURES - DEFENSE SYS	TEMS		
		•	4.
			and the second s
XIII. CERTIFICATION (see instructions)			
I certify under penalty of law that I have personally examined and attachments and that, based on my inquiry of those persons important to the last	nediately responsible for obta	ining the information	contained in the
application, I believe that the information is true, accurate and confalse information, including the possibility of fine and imprisonment			
JOHN J. MC NAUGHTON	I to Thunk		ATE SIGNED
VICE PRESIDENT, FINANCIAL MANAGEMENT COMMENTS FOR OFFICIAL USE ONLY	- James Joseph	Dec	. 14, 1982
EPA Form 3510-1 (6-80) REVERSE		<b>**</b>	

**EXAMPLE FOR COMPLETING ITEM III** (shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.

T/A C

11	2		-		DUP 1	1		/ ,	1	\	1	11.	111	111	111	1	1	1	/	1	
	CZ /	A.	PR	20-	B. PROCESS DESIGN CAPAC	ITY				-	R	A. PRO-	B. PR	OCESS DESI	GN CAPACI	TY					
LINE	NOMBE	fro	ES om	S list e)	1. AMOUNT (specify)	2. UN OF ME SUR (ente code	EA-	OFF U	OR ICIA ISE NLY		LINE	CESS CODE (from list above)	WIII	1. AMOUNT		OF SI	UNI ME URE enter ode)	A-	OFF U OI	OR ICI/ ISE NLY	AL
X-			0	2	600	G 28		29	4	32	5	16 - 18	19		27		28		2.9		32
X-	2	T	0	3	20	E					6			1122	ta f						
1	S	; (	)	1	7600	G					7										
2											8				(E. g. 1						
3											9										
4				1.0	19 - 27	28		29		32	10	16 - 18,			27		28		29		32

	from t	

TIT	PR	OCE	CCEC	(continued)
LEE .	LIL	ULL	CALCO	continueu/

SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

### IV. DESCRIPTION OF HAZARDOUS WASTES

- EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE CODE	METRIC UNIT OF MEASURE CODE
POUNDSP	KILOGRAMS
TONS	METRIC TONS

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

#### D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant,

Note: Four spaces are provided for entering process codes, If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.

  In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter
- 'included with above" and make no other entries on that line,
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

**EXAMPLE FOR COMPLETING ITEM IV** (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

11.5			EP/				UNIT										D. PROCESSES						
LINE NO.	W	AS	TE	ON	B. ESTIMATED ANNUAL QUANTITY OF WASTE	5	MÉA URE enter ode)								1. PROCESS CODES (enter)							5	2. PROCESS DESCRIPTION (if a code is not entered in $D(I)$ )
X-1	K	0	5	4	900		P	T	0	3	L	) (	8 (	0									
X-2	D	0	P	2	400		P	T	0	3	L	) (	8 (	0									
X-3	D	0	0	1	100		P	T	0	3	L	) (	8 1	0									
X-4	D	0	0	2						The second			J.				included with above						

FOR OFFICIAL USE ONLY EPA I.D. NUMBER (enter from page 1) I L D 0 0 5 1 2 8 9 8 8 W DUP DUP DESCRIPTION OF HAZARDOUS WASTES (continued) C. UNIT OF MEA-SURE (enter code) D. PROCESSES A. EPA HAZARD. WASTENO B. ESTIMATED ANNUAL QUANTITY OF WASTE NO. 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter code) - 29 27 F 0 0 3 P S 0 1 5280 RECYCLED INCLUDED WITH THE ABOVE F 0 0 5 F 0 0 2 P RECYCLED 10,000 S 0 1 4 F 0 0 1 40,000 P S 0 1 RECYCLED 5 P F 0 0 7 10,000 S 0 1 RECYCLED 6 P 0 2 9 P 540 5 0 1 0 8 0 P 0 3 0 INCLUDED WITH THE ABOVE 8 P S 0 1 RECYCLED P 1 0 4 1,650 P U 1 5 1 15 S 0.1 RECYCLED 10 P D 0 0 1 501080 7,920 11 INCLUDED WITH ABOVE U 1 5 4 F 0 0 6 3,600 P S 0 1 0 8 0 RECYCLED 13 INCLUDED WITH ABOVE D 0 0 7 14 15 16 17 18 19 20 25 26

EPA Form 3510-3 (6-80)

A. NAME (print or type)

including the possibility of fine and imprisonment.

IL. SWETONIE

PAGE 4 OF 5


B. SIGNATURE

**CONTINUE ON PAGE 5** 

C. DATE SIGNED

### NORTHROP PRIVATE

# CORPORATE FACILITIES PLAN IMPLEMENTATION PLOT PLAN



Please print or type in the unshaded areas only fill—in areas are spaced for elite type, i.e., 12 characte.			Form Approved OMB No. 1	58-R0175	116
FORM SEPA	SENERA	L INFORM		8.98	8 3 6
GENERAL (Read	Consoli the "Gener	dated Permits P	'before starting.)  GENERAL INSTR	COLUMN TO THE REAL PROPERTY.	13 14 11
EPA I.D. NUMBER	11	111,	If a preprinted label has to it in the designated space.	Review the	e inform-
II. FACILITY NAME	111		ation carefully; if any of i through it and enter the appropriate fill—in area be	correct dat low. Also,	ta in the if any of
FACILITY MAILING ADDRESS PI FASE	PLACE	LAREL IN	the preprinted data is absorbed for the label space if that should appear), pleas proper fill—in area(s) below	ists the infi e provide	formation it in the
The same of the sa	LEACE	LADEL III	proper fill—in area(s) belocomplete and correct, you items I, III, V, and VI	need not	complete
FACILITY			must be completed regard items if no label has been	<i>dless)</i> . Com provided.	nplete all Refer to
LOCATION	1//	111	the instructions for detitions and for the legal a which this data is collected.	uthorizatio	
I. POLLUTANT CHARACTERISTICS					
INSTRUCTIONS: Complete A through J to determ questions, you must submit this form and the supplemental form is attached. If you answer	olemental for	orm listed in th ach question, v	submit any permit application forms to the EPA. If you and e parenthesis following the question. Mark "X" in the box in you need not submit any of these forms. You may answer "notes, Section D of the instructions for definitions of bold—face	o" if your a	ioiuinn
	or the insu	MARK'X'		MAF	RK'X'
A. Is this facility a publicly owned treatment	YES Works	NO ATTACHED	B. Does or will this facility (either existing or proposed)	YES NO	ATTACHE
which results in a discharge to waters of the (FORM 2A)	U.S.?	X 17 18	include a concentrated animal feeding operation or aquatic animal production facility which results in a discharge to waters of the U.S.? (FORM 2B)	X 19 20	21
C. Is this a facility which currently results in disc to waters of the U.S. other than those describ	harges ped in	X	D. Is this a proposed facility (other than those described in A or B above) which will result in a discharge to waters of the U.S.? (FORM 2D)		27
A or B above? (FORM 2C)  E. Does or will this facility treat, store, or disp hazardous wastes? (FORM 3)	2	23 24	F. Do you or will you inject at this facility industrial or municipal effluent below the lowermost stratum containing, within one quarter mile of the well bore, underground sources of drinking water? (FORM 4)	X	
G. Do you or will you inject at this facility any pro- water or other fluids which are brought to the s	urface	29 30	H. Do you or will you inject at this facility fluids for spe- cial processes such as mining of sulfur by the Frasch		
in connection with conventional oil or natural gaduction, inject fluids used for enhanced recovoil or natural gas, or inject fluids for storage of	ery of liquid	X	process, solution mining of minerals, in situ combus- tion of fossil fuel, or recovery of geothermal energy? (FORM 4)	V	30
hydrocarbons? (FORM 4)  I. Is this facility a proposed stationary source work one of the 28 industrial categories listed in the state of the state o	the in-	35 36	J. Is this facility a proposed stationary source which is NOT one of the 28 industrial categories listed in the		
structions and which will potentially emit 10 per year of any air pollutant regulated und Clean Air Act and may affect or be located	er the	X	instructions and which will potentially emit 250 tons per year of any air pollutant regulated under the Clean Air Act and may affect or be located in an attainment	X	
attainment area? (FORM 5)  II. NAME OF FACILITY	40	45 42	area? (FORM 5)	43 44	45
SKIP NORTHROP CORP		FENSE	SYSTEMS DIVISION		
5 16 - 29 30  IV. FACILITY CONTACT				69	
A. NAME & TITLE	(last, first, é		B. PHONE (area code & no.)	1	
2 S.W.E.T.O.N.I.C. A.N.T.H.O.N	Y F	A.C.I.L.	ENG. MGR 3 1 2 2 5 9 9 6 0 1	0	
V. FACILITY MAILING ADDRESS	R P.O. BO)				
3600 Hicks Road					
B. CITY OR TOWN			C.STATE D. ZIP CODE		
4 ROLLING MEADOWS			I I 6 0 0 8	No.	
VI. FACILITY LOCATION  A. STREET, ROUTE NO. OR O'	THER SPEC	LEIC IDENTIE	TER THE THE TERM THE		
5600 HICKS ROAD	T T T				
B. COUNTY NAME			45		
COOK			70		
C. CITY OR TOWN		1111	D. STATE E. ZIP CODE F. COUNTY CODE		
ROLLING MEADOWS			I L 6 Ø Ø Ø 8 Ø 3 / 52 - 54		
EPA Form 3510-1 (6-80)			MAY 18 1980 CON.	TINUE ON	REVERS

CONTINUED FROM THE FRONT				
VII. SIC CODES (4-digit, in order of priority)			1 30 30	
A, FIRST	ls. I	(specify)	B. SECOND	
7 3 6 7 9 (specify) HAZARDOUS WASTES	7	(specify)		
6 16 - 18 C. THIRD			D. FOURTH	
c       (specify)	7	(specify)		
B 16 - 19	. 15 16	- 19		A CONTRACTOR OF THE CONTRACTOR
VIII. OPERATOR INFORMATION	A. NAME			B. Is the name listed in
<u> </u>				item VIII-A also th
5 16			V,I,S,I,O,N,	YES NO
C. STATUS OF OPERATOR (Enter the appropriate in F = FEDERAL M = PUBLIC (other than federal o		"Other", specify.)	D. PHONE	(area code & no.)
S = STATE O = OTHER (specify) P = PRIVATE	P			2 5 9 9 6 0 0
E. STREET OR P.O. B	0X 			
6 p p HICKS ROAD		55		
F. CITY OR TOWN		G.STATE H. ZIP COD	Is the facility locate	The state of the s
BROLLING MEADOWS		IL 6000	8 YES	NO
15 16	40	41 42 47 -	52	
X. EXISTING ENVIRONMENTAL PERMITS		A CONTRACTOR OF THE CONTRACTOR		
A. NPDES (Discharges to Surface Water)  CITIII I I I I I I CIT	PSD (Air Emissions from Pi			
9 N D, N, A, , , , , , 9 P	DNA			
B. UIC (Underground Injection of Fluids)	E. OTHER (speci)	5y)		
9 U D N A	DNA	(sp	ecify)	N N N N N N N N N N N N N N N N N N N
15 16 17 18 - 30 15 16	17 18 -	30		
C. RCRA (Hazardous Wastes)	E, OTHER (speci,		ecify)	
9 R D N A 9	D N A	1 1 1 30		
XI. MAP				
Attach to this application a topographic map of the the outline of the facility, the location of each of treatment, storage, or disposal facilities, and each water bodies in the map area. See instructions for product of the second se	its existing and proposed well where it injects flui	d intake and discharg	e structures, each of	its hazardous waste
XII. NATURE OF BUSINESS (provide a brief description)	coloc rodali amonto.		110/54	Control of the Contro
All, NATORE OF BUSINESS (provide a brief description)		Service of the American	Security of the second	
E O LULVIO 8 M	wrare ga		not ded	
ELECTRONIC COUNTER MEASURES - I	DEFENSE SYSTEMS	E	9:8/51	
			- 101	
- 00000112841170	D. FHE.I	2 5 A. W. W. H.		
				3 - 3 - 3 - 3 - 3
			r 11 50 m 3 24	
XIII. CERTIFICATION (see instructions)				
I certify under penalty of law that I have personal attachments and that, based on my inquiry of the application, I believe that the information is true, false information, including the possibility of fine a	hose persons immediatel accurate and complete.	y responsible for ob	taining the informati	ion contained in the
A. NAME & OFFICIAL TITLE (type or print)	B. SIGNATURE		C	DATE SIGNED
J.J. McNaughton	000	2 /2 /		11-18-80
Vice President Financial Mgr.	X.7. M	Jays he	~	71 0 0 0
COMMENTS FOR OFFICIAL USE ONLY				
C				
15 16 PA Form 3510-1 (6-80) REVERSE	A A			557
EPA Form 3510-1 (6-80) REVERSE	. 173			

RCR	A		9	EPA		ZAR U	Consc	AS dida	TE I	PEF	RM its P	IT A	API	PLI	CA	TI	FILD Ø 5 1 2 8 9 8 8 2	1
				AL USE ONLY	Jac Car	I HAMILY	HIE	1	17.00	MA	in.	T LAB	18-11	Tay Is			THE RESERVE OF THE PROPERTY OF	1-11
(PP	RO	VE	D	(yr., mo., & day)											CC	OW.	MMENTS	
I. F	RS	T	OR	REVISED APPL	ICATIO	ON	185		1	Total .		1	100	EVI)	100		NAMES OF THE OWNER OF THE OWNER.	100
lace	an '	"X"	" in	the appropriate box	in A or	B below (ma	rk or	ne bo	ox on	ily) 1	to in	dicat	e w	heth	ner t	his	is is the first application you are submitting for your facility or	ra
PAI	.D.	Nu	ımb	ion. If this is your fi er in Item I above. PLICATION (place										s EP.	A 1.1	D. N	<ol> <li>Number, or if this is a revised application, enter your facility'</li> </ol>	\$
3	X,		7 -	STING FACILITY (	See instr Complet	ructions for a te item belou ING FACILI	lefini v.) TIES	tion	of "	exist	ing"	facil	ity.	yr.,	mo.,	& MEI	2.NEW FACILITY (Complete item below.)  FOR NEW FACILITI PROVIDE THE DATI (yr., mo., & day) OPE; TION BEGAN OR IS EXPECTED TO BEG	RA-
3. R	73 E V	ISI	ED	APPLICATION ()	olace an	"X" below		ompl	lete I	tem	I ab	ove)					2. FACILITY HAS A RCRA PERMIT	
II E	72						CIT	IFS	7		Q DI	0.73	y 110		1		72	230
en de	I. PROCESSES — CODES AND DESIGN CAPACITIES  PROCESS CODE — Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process (including its design capacity) in the space provided on the form (Item III-C).  PROCESS DESIGN CAPACITY — For each code entered in column A enter the capacity of the process.																	
1.	A	MO	UN	T - Enter the amou	nt. each am	ount entered	in co	olum d bel	n B(	1), e houl	nter	the o	code				e list of unit measure codes below that describes the unit of	
					PRO- CESS	APPROPR											PRO- APPROPRIATE UNITS OF CESS MEASURE FOR PROCESS	
			PE	ROCESS	CODE	DESIG						-				RO	ROCESS CODE DESIGN CAPACITY	-
Sto	100		IER	(barrel, drum, etc.)	501	GALLONS	OR L	ITE	RS				reat	mer K	nt:	-	TOT GALLONS PER DAY OR	
TAI	NK				502 503	GALLONS CUBIC YAI	RDS	OR							EIN	ИРС	POUNDMENT TO2 GALLONS PER DAY OR LITERS PER DAY	
			E IN	POUNDMENT	504	GALLONS			RS			11	ICI	NEF	RAT	OR	T03 TONS PER HOUR OR METRIC TONS PER HOUR;	
	EC.	TIC		WELL	D79	GALLONS	ORL	ITE	RS						100	at.	GALLONS PER HOUR OR LITERS PER HOUR	
LA				and the state of	D80	would cover	T (the	e vol acre	ume to a	that		th	iern	nal c	or bi	olo	for physical, chemical, T04 GALLONS PER DAY OR LITERS PER DAY	
				ICATION	D81	depth of on HECTARE- ACRES OR	MET	ER				St	irfa	ce in	npol	und	occurring in tanks, ndments or inciner- e the processes in	
oc	EAI	N D	DISF	POSAL	D82	GALLONS LITERS PE GALLONS	PER R DA	DAY	OR			th	ie sj	pace	pro	vid	e the processes in ided; Item III-C.)	
aul		-ul	- 11/	CONDMENT	UNIT		on L	HE							1	JNI	NIT OF UNIT O	F
UN	IT (	OF	ME	ASURE	MEAS	URE	UN	IT C	)F M	EAS	URE	E		N	M	IEA	EASURE MEASURE CODE UNIT OF MEASURE CODE	RE
																	V ACRE-FEET	
CU	BIC	M	ARI	RS		Y	ME	TRI	CTO	PER	PER	UR .	UR.				W ACRESBE HECTARESQ	
GA	LL	ON	SP	ER DAY		U	LIT	FERS	S PE	RHO	OUR		E18911	-			н ity has two storage tanks, one tank can hold 200 gallons and th	e
ther	cai	n he	old	400 gallons. The fac	cility also	o has an inci	nerato	or th	at ca	n bu	irn u	p to	20	gallo	ons p	per	er hour.	_
2				D U P		3 1 14 15	ITY	1	1	1		1	-	/	1	1	B. PROCESS DESIGN CAPACITY	
BER	CI			B. PROCESS	DESIG	SHEAFAC		UNIT	-	FC		,	III	CI	PRO		FOR	
J ve	fro	m l	E ist		OUNT cify)		OF	MEA	4-	US	CIA	H Z		(from	DE m lis	it	1. AMOUNT OF MEA- SURE USE	
iž	ab						C	nter		ON	41		Z		ove)		code)	
<u>-1</u>	S		2	600	)	27		G	26		3		5	1.6	- 16	1	19 - 27 26 29 -	32
(-2	T	0	3	20	)			E					6					
1	3 9	\$	1	5811	pop	3		G			1		7					
2	1				-							8	3					
3													9					
4	6	-	18	19		27		28	29			1 1	0	1.6	- 1	a 1	19 27 28 29 -	32
PA	-	-	-	0-3 (6-80)						P	AGI	E 1	OF	- 5			CONTINUE ON REVE	RSE

(fill—in areas are spaced for elite type, i.e., 12 characters/inch).

Form Approved OMB No. 158-S80004 176

TITE	DD	OC	PECEE	(continued)
BAR.	LL	UL	EDDED	continued

SPACE FOR ADDITIONAL PROCESS CODES (INCLUDE DESIGN CAPACITY. FOR DESCRIBING OTHER PROCESSES (code "TO FOR EACH PROCESS ENTERED HERE

### IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis, For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant,
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	a a a a a a T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste,

#### D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.

  In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter
- 'included with above" and make no other entries on that line,
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

**EXAMPLE FOR COMPLETING ITEM IV** (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.


			EP		1			JNIT	1	Ш								1		D. PROCESSES
LINE NO.	W	AS	TE	NO de)	1	B. ESTIMATED ANNUAL QUANTITY OF WASTE	SL (e	MEA- JRE nter ode)		1. PROCESS CODES (enter)								S		2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K	0	5	4		900		P	T	0	3	3	D	8	0		1		0	हर्ष के अध्येष वर्ष
X-2	D	0	0	2		400		P	T	0	3	3	D	8	0				1-1	
X-3	D	0	0	1		100		P	T	0	15	3	D	8	0					
X-4	D	0	0	2		MATERIAL STREET														included with above

NO	TË:	Ph	oto	cop	y th	is page before completing if	have n	nore	than 26 w		THE RESERVE AND ADDRESS.			roved OMB No. 158-S80004
8	_				71	BER (enter from page 1)	1	1.	s	FC	ROFFICI	AL USE O		-////////
W	I	L	D	Ø	Ø	5 1 2 8 9 8 8 3 1	1	1	W	-	DUP		3 2 DUP	20
	V. I	ES	CR	IP.	rio	N OF HAZARDOUS WASTI	S (co	onti	A STATE OF THE PARTY OF THE PAR		V. Tabl			
FILE	NO.	WA	ST		D.	B. ESTIMATED ANNUAL QUANTITY OF WASTE	(en	RE ter		1. PROCE	SS CODES		2. PRO	ocess description e is not entered in D(1))
	12	23	1	d	26	$528\phi\phi\phi\phi$	coo	6	27 - 29	27 - 29	ter)	27 - 29	(1) 2 000	e is not entered in D(1))
	2	F	1	1	3	5289 Ø Ø Ø	I		501	501	1 1	1 1	SOLD FOR RE	CYCLING
	3	P	p		ø	30 00 0	I		-080	SØI	1 1	1 1	DOLLD I OIL ILL	O L O LILLIA
	4	P	1	ø	4	6 Ø Ø Ø	I		0 8 0	501	1 1	1 1		
	5	U		1	1	15 $\phi \phi \phi$	I		080	SØI	1 4			
	6	D	1	1		7920 000	I		080	SøI	1 1	1		4
	7	U			4	.,   1   1			, I, I	1 1			INCLUDED WI	TH ABOVE
	8	D	,	ø	7	ιρφφ φφφ	I	2	080	SØI	1 1			C AND R F
	9										La lou			
	10								Les de	100				STATE TO BE SHOWN
	11				ia I	27					- 14			In a tree of Parison
	12													
	13												4	gr.8
	14													Carlo
	15													
	16												La Tanan	*
	17										11,	1		
	18								- 1 - 1 -		1-1	11		
H	19	1							11	11		1 1	-10/4/2013	AND ADD PROPERTY
H	20								1 1		4.	1 1	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
H	21								1 1	1	1 1	-1 1	* 1 - 1 - 1 - 1	
H	22					8-1-		1	11	1 1	11,	1 1	A VIII DI VIO	vid. minorina Vi <del>ce Lesicent</del>
H	23	5							1 1	1 1	1 1			Harris Statement
-	24					Α.			11			1 1	u-Tu-	4
L	25 26								1	Ţ	1	1 1	-1 / 4	
		23 Fort			3 (6	27 - 35 6-80)	3	6	27 - 29	27 - 29	27 - 29	27 + 29		CONTINUE ON REVERSE
-	11					The state of the s			PAGE	3	OFS			A PART OF THE PART

IV. DESCRIPTION OF HAZARDOUS WAST			
E. USE THIS SPACE TO LIST ADDITIONAL	(continued) ROCESS CODES FROM ITEM D(1) ON PAGE		310
E. OSE THIS SPACE TO LIST ADDITIONAL			-6
			5_
Service of the servic			
. *		Figure 3 palktones	
A CAMPAGAN IN A 12		months and a s	
	- 11 41 11 11	311995 3604	
		2028 2015	
	V 0 8 0 8		
		504 (SI) T 1 4 FIG	
in the state of th		U 13 %	
FI L D Ø Ø 5 1 2 8 9 8 8 3 6		0.20000 7000	
1 2 [3 14 15]			THE W
V. FACILITY DRAWING  All existing facilities must include in the space provide	ed on page 5 a scale drawing of the facility <i>(see instructio</i>	ns for more detail). F6:A 55	
VI. PHOTOGRAPHS			
All existing facilities must include photographs treatment and disposal areas; and sites of future	(aerial or ground—level) that clearly delineate all e storage, treatment or disposal areas (see instruct	ions for more detail). F6:B/56	
VII. FACILITY GEOGRAPHIC LOCATION			
LATITUDE (degrees, minutes, & se		DE (degrees, minutes, & seconds)	
4 2 4 6 69 69	71	8 74 75 76 77 - 79	
VIII. FACILITY OWNER		CANADA DE LA COMPONIONE	(FRIE
	Para Para Para Will on Form 1 "Connect Informa	tion" place on "Y" in the how to the left an	(1-814) d
	tor as listed in Section VIII on Form 1, "General Informa	tion", place an "X" in the box to the left an	d
X A. If the facility owner is also the facility operat skip to Section IX below.	or as listed in Section VIII on Form 1, "General Information or as listed in Section VIII on Form 1, complete the following the		d
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operate.			
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF I	or as listed in Section VIII on Form 1, complete the following	owing items:  2. PHONE NO. (area code d	
A. If the facility owner is also the facility operation is skip to Section IX below.  B. If the facility owner is not the facility operator.  1. NAME OF 1	or as listed in Section VIII on Form 1, complete the following	owing items:	
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN	2. PHONE NO. (area code d	
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1  E  3. STREET OR P.O. BOX	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN	2. PHONE NO. (area code d	
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1  E  IS  S. STREET OR P.O. BOX  IX. OWNER CERTIFICATION  I certify under penalty of law that I have person	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  C G 45 15 16	z. PHONE NO. (area code do so	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1.  E  15 16  3. STREET OR P.O. BOX  T  IX. OWNER CERTIFICATION  I certify under penalty of law that I have person documents, and that based on my inquiry of the submitted information is true, accurate, and co	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  G  4. CITY OR TOWN  FACILITY'S LEGAL OWNER  4. CITY OR TOWN  FACILITY'S LEGAL OWNER  4. CITY OR TOWN  FACILITY OR TOWN  FACILITY'S LEGAL OWNER	2. PHONE NO. (area code do so	& no.)
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1.  I NAME OF 1.  S. STREET OR P.O. BOX  I Certify under penalty of law that I have person documents, and that based on my inquiry of the submitted information is true, accurate, and con including the possibility of fine and imprisonments.	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  C  G  45 15 16  Innally examined and am familiar with the informations individuals immediately responsible for obtaining the complete. I am aware that there are significant penalent.	2. PHONE NO. (area code of section of submitted in this and all attached in the information, I believe that the lities for submitting false information,	& no.)
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1.  I NAME OF 1.  S. STREET OR P.O. BOX  I Certify under penalty of law that I have person documents, and that based on my inquiry of the submitted information is true, accurate, and con including the possibility of fine and imprisonment.  A. NAME (print or type)	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  G  4. CITY OR TOWN  FACILITY'S LEGAL OWNER  4. CITY OR TOWN  FACILITY'S LEGAL OWNER  4. CITY OR TOWN  FACILITY OR TOWN  FACILITY'S LEGAL OWNER	2. PHONE NO. (area code de la seconda de la	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  C  As 15 16  In ally examined and am familiar with the informations individuals immediately responsible for obtainment.  B. SIGNATURE  B. SIGNATURE	2. PHONE NO. (area code of section of submitted in this and all attached in the information, I believe that the lities for submitting false information,	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  6. C	2. PHONE NO. (area code de la seconda de la	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  5. CITY OR TOWN  6. C	ion submitted in this and all attached in the information, I believe that the	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	anally examined and am familiar with the information of individuals immediately responsible for obtainment.  B. SIGNATURE  B. SIGNATURE  Anally examined and am familiar with the information of individuals immediately responsible for obtainment.  B. SIGNATURE  Anally examined and am familiar with the informations individuals immediately responsible for obtainment of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of	ion submitted in this and all attached in the information, I believe that the	& no.)
A. If the facility owner is also the facility operate skip to Section IX below.  B. If the facility owner is not the facility operate 1. NAME OF 1. NAME (print or type)  J.J. McNaughton  Vice President Financial Mana X. OPERATOR CERTIFICATION  I certify under penalty of law that I have person documents, and that based on my inquiry of the submitted information is true, accurate, and continuous continuous of the submitted information is true, accurate, and continuous of the submitted information is tru	anally examined and am familiar with the information of individuals immediately responsible for obtainment.  B. SIGNATURE  B. SIGNATURE  Anally examined and am familiar with the information of individuals immediately responsible for obtainment.  B. SIGNATURE  Anally examined and am familiar with the informations individuals immediately responsible for obtainment of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of individuals immediately responsible for obtainment in the information of	ion submitted in this and all attached in the information, I believe that the	& no.)
B. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  5. CITY OR TOWN  6. C	ion submitted in this and all attached in the lities for submitting false information,  C. DATE SIGNED  11–18–80  cion submitted in this and all attached in the lities for submitting false information,	& no.)
A. If the facility owner is also the facility operat skip to Section IX below.  B. If the facility owner is not the facility operated to the facil	or as listed in Section VIII on Form 1, complete the following facility's LEGAL OWNER  4. CITY OR TOWN  5. CITY OR TOWN  6. C	2. PHONE NO. (area code of the state of the	& no.)

### NORTHROP PRIVATE

## CORPORATE FACILITIES PLAN IMPLEMENTATION PLOT PLAN





JAN 1 0 1984

Mr. J.J. McNaughton Vice President, Financial Management Northrop Corporation Defense Systems Division 600 Hicks Road Rolling Meadows, Illinois 60008

> Re: Part A Permit Application ILD 005128988

Dear Mr. McMaughton:

Thank you for your letter of December 16, 1983, notifying U.S. Environmental Protection Agency (U.S. EPA) of the proposed expansion of your facility's hazardous waste treatment capacity. Please be advised that increases in the design capacity of hazardous waste processes, for interim status facilities, may be made only if a revised Part A permit application is submitted prior to such changes (along with a justification explaining the need for the changes) and the changes are approved by U.S. EPA-40 CFR §270.71. Enclosed is an application package which may be used to update your Part A permit application.

Please contact Mr. Gale Mruska of my staff, at (312) 886-0989, if you have any questions concerning the revision to your permit application. We will process your request for an increase hazardous waste treatment capacity upon receipt of your revised Part A permit application.

Sincerely yours,

ORIGINAL SIGNED BY WILLIAM H. MINER

William H. Miner, Chief Technical, Permits, and Compliance Section

Enclosure

cc: Lawrence Eastep, IEPA

5HW:G.HRUSKA:ns:1/5/84

TYPIST AUTHOR STU #1 STU #2 STU #3 TPS WMB WMD CHIEF C

FEB 2 4 1983

John J. McNaughton, Vice President Northrop Corp. Defense Systems Division 600 Hicks Road Rolling Meadows, Illinois 60008

RE: ILD 005128988

Dear Mr. McNaughton:

This is to acknowledge receipt of your amended Part A Permit Application of December 14,1982. Your company has the approval of the United States Environmental Protection Agency to increase its hazardous waste container storage capacity from 5,811 gallons to 7,600 gallons. This approval is effective retroactively as of December 20,1982.

In addition to this approval of your change during interim status, you must obtain the written approval of the Director of the Illinois Environmental Protection Agency in accordance with the provisions of Part 700.105 (c) of the Illinois hazardous waste regulations. Further, since the State of Illinois has received Phase I Interim Authorization under §3005 of the Resource Conservation and Recovery Act, you are required to comply with Part 725 of the Illinois hazardous waste regulations in lieu of the Federal regulations at 40 CFR Part 265. Operation under interim status does not relieve you of the need to comply with other applicable Federal, State and local requirements.

Please contact Mr. Greg Weber of my staff, at (312) 886-3719, if you have any questions regarding this matter.

Sincerely,

Basil G. Constantelos, Director Waste Management Division

cc: Tom E. Cavanagh, Jr., IEPA

5HW:G.WEBER:ad 2/14/83 Disk #5 No5 line ad

INITIALS 2-14-83

600 1 16 1831

One 2/16

These 2/16
Chief Chief Direct
12/17/65 2/13/83

Defense Systems Division

## NORTHROP

600 Hicks Road Rolling Meadows, Illinois 60008

WASIL IMPROCESSENT BRANCH
EPA, REGION V

October 27, 1981

United States
Environmental Protection Agency
Region V
Diane Parker
230 So. Dearborn
Chicago, Il. 60604

Dear Miss Parker:

In response to your questions on Oct. 26, 1981, concerning the submittal of E.P.A. forms by the Northrop Corporation in Rolling Meadows, the following corrections should be made.

On the reverse side of Form 1, Section VIII A, the facility operator is the same as facility owner. On Form 3, Section IV, the process code should read SO 1 instead of O8O as indicated on form.

We appreciate having the two omissions called to our attention, please do not hesitate to contact us if further information is required.

Yours truly, Cathony X Quetonic

Anthony L. Swetonic Facilities Manager

Northrop Corp.

A.4 Closure/ Post-Closure



Illinois Environmental Protection Agency 2200 Churchill Road, Springfield, IL 62706

217/782-6762

Refer to: 0312730002 -- Cook County

Northrop Corporation

Closure Plan Approved: March 9, 1987 Log #C-295 ILD005128988 Log # A-133

RCRA-Closure

December 21, 1987

Northrop Corporation 600 Hicks Road Rolling Meadows, Illinois 60008-1098

Dear Mr. Langlois:

The closure plan modification and certification submitted by Northrop Corporation has been reviewed and approved by this Agency.

The subject hazardous waste management facility was inspected by a representative of this Agency on November 2, 1987. The inspection revealed that the closure activity was completed in accordance with the approved closure plan.

Certification that the container storage areas (SO1) have been closed in accordance with the approved closure plan by the owner/operator, Robert Langlois, and the independent registered professional engineers, George E. Heck and Donald R. Schwegel, of Illinois was received at this Agency October 22, 1987.

The Agency has determined that the closure of the container storage areas has apparently met the requirements of Interim Status Standards, 35 Ill. Admin. Code, Part 725 (40 CFR, Part 265). Please note, the Agency has withdrawn your Part A application dated December 14, 1982 to reflect the status change due to completed closure activities.

This facility must continue to meet the requirements of 35 IAC Section 722 -Standards Applicable to Generators of Hazardous Waste.

In accordance with the requirements of 35 IAC 725.243(h), further maintenance of certain financial assurance mechanisms is no longer needed. Therefore, this Agency herewith returns the Surety Bond dated August 19, 1985.

Changes well be Submitted to Data Entry 1/7 M.V.



Page 2

If you have any questions, please contact Karen Nachtwey at 217/782-0892.

Very truly yours,

Lawrence W. Eastep, P.E., Manager

Permit Section

Division of Land Pollution Control

LWE:KEN:sls/4391g,59-60

cc: Maywood Region

USEPA Region V, Mary Murphy USEPA Region V, Art Kawatachi

Baxter & Woodman, P.E.

Division File

Financial Assurance Unit Compliance Monitoring

ILT 000627273

## NORTHROP



January 25, 1983

USEPA, Region V Waste Management Branch 230 S. Dearborn Street Chicago, IL. 60604

> RE: Closure/Post Closure Financial Guarantee

### Gentlemen:

In compliance with Federal Law, we enclose Bond #KO-1048089-30 guarantying our financial obligation under the Resource Conservation and Recovery Act (RCRA). The bond provides coverage for Northrop's Defense Systems Division, site location: 600 Hicks Rd., Rolling Meadows, IL.

Very truly yours,

NORTHROP CORPORATION

Gary K. Brucker

Corporate Administrator

Risk Management

GKB/mbh Encl.

cc: T. McCabe

RECEIVED

WASTE MANAGEMENT BRANCH

### FINANCIAL GUARANTEE BOND

DATE BOND EXECUTED: 1/12/83

EFFECTIVE DATE: 10/1/82

PRINCIPAL:

NORTHROP CORPORATION

1800 Century Park East.

ADDRESS:

Los Angeles, CA 90067

TYPE OF ORGANIZATION: CORPORATION

STATE OF INCORPORATION:

CALIFORNIA

SURETY:

INSURANCE COMPANY OF NORTH AMERICA

5757 Wilshire Blvd. Los Angeles, CA 90036

EPA. ID NO.

NAME & ADDRESS

PENAL SUM

ILD000627273

DEFENSE SYSTEMS DIVISION of NORTHROP CORPORATION

\$15,000-TOTAL

600 Hicks Rd.

Rolling Meadows, Illinois

KNOW ALL PERSONS BY THESE PRESENTS, That we, the Principal and Surety hereto are firmly bound to the U.S. Environmental Protection Agency (hereinafter called EPA), in the above penal sum for the payment of which we bind ourselves, our heirs, executors, administrators, successors, and assigns, jointly and severally; provided that, where the Sureties are corporations acting as co-sureties, we, the Sureties bind ourselves in such sum "jointly and severally" only for the purpose of allowing a joint action or actions against any or all of us, and for all other purposes each Surety binds itself, jointly and severally with the Principal, for the payment of such sum only as is set forth opposite the name of such Surety, but if no limit of liability is indicated, the limit of liability shall be the full amount of the penal sum.

WHEREAS, said Principal is requires, under the Resource Conservation and Recovery

Act as amended (RCRA), to have a permit or interim
status in order to own or operate each hazardous waste management facility identified above, and

WHEREAS, said Principal is required to provide financial assurance for closure, or closure and post-closure care, as a condition of the permit or interim status, and

WHEREAS, said Principal shall establish a standby trust fund as is required when a surety bond is used to provide such financial assurance;

NOW, THEREFORE, the conditions of the obligation are such that if the Principal shall faithfully, before the beginning of final closure of The Facility identified above, fund the standby trust fund in the amount(s) identified above for the facility,

Or, if the Principal shall fund the standby trust fund in such amount(s) within

15 days after an order to begin closure is issued by an EPA Regional Administrator
, or a U. S. district court or other court or competent jurisdiction,

Subpart H of 40 CFR part 264 or 265, as applicable, and obtain the  EPA Regional Administrator's written approval of such assurance within  90 days after the date notice of cancellation is received by both the  Principal and the EPA Regional Administrator from the Surety, then this obligation shall be null and void, otherwise it is to remain in full force and effect.  THE Surety shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.  UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in which the Facility is located
EPA Regional Administrator's written approval of such assurance within 90 days after the date notice of cancellation is received by both the Principal and the EPA Regional Administrator from the Surety, then this obligation shall be null and void, otherwise it is to remain in full force and effect.  THE Surety shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.  UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
days after the date notice of cancellation is received by both the Principal and the EPA Regional Administrator from the Surety, then this obligation shall be null and void, otherwise it is to remain in full force and effect.  THE Surety shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.  UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
Principal and
obligation shall be null and void, otherwise it is to remain in full force and effect.  THE Surety shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.  UPON NOTIFICATION byan EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed bythe EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the _Principal and to the EPA Regional Administrator for the Region in
THE Surety shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.  UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
UPON NOTIFICATION by an EPA Regional Administrator that the Principal has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
has failed to perform as guaranteed by this bond the Surety shall place funds in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator.  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
in the amount guaranteed for the facility into the standby trust fund as directed by the EPA Regional Administrator  THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
THE LIABILITY of the Surety shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
of payments hereunder, unless and until such payment or payments shall amount in the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
the aggregate to the penal sum of the bond, but in no event shall the obligation of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
of the Surety hereunder exceed the amount of said penal sum.  THE SURETY may cancel the bond by sending notice of cancellation by certified mail to the Principal and to the EPA Regional Administrator for the Region in
mail to the Principal and to the EPA Regional Administrator for the Region in
mail to the Principal and to the EPA Regional Administrator for the Region in
which the Facility is located
provided, however, that cancellation shall not occur during the 120 days
beginning on the date of receipt of the notice of cancellation by both the
Principal and the EPA Regional Administrator , as evidenced by the
return receipts.
THE PRINCIPAL may terminate this bond by sending written notice to the Surety
provided, however, that no such notice shall become effective until the Surety
receive(s) written authorization for termination of the bond by the

IN WITNESS WHEREOF, the Principal and Surety have executed this Financial Guarantee Bond and have affixed their seals on the date set forth above.

THE PERSONS whose signatures appear below hereby certify that they are authorized to execute this surety bond on behalf of the Principal and Surety and that the wording of this Surety Bond is identical to wording specified in 40 CFR 264151(b) as such regulations were constituted on the date this bond was executed.

is located

		<b>-3-</b>
ITNESS O	er hands and se	als this 12th day of January , 19 83.
ATTEST:	· · · · · · · · · · · · · · · · · · ·	NORTHROP CORPORATION (SEAL)  (Principal)
		BY:
	÷	INSURANCE COMPANY OF NORTH AMERICA  5757 WILSHIRE BLVD., LOS ANGELES, CA 90036  (Corporate Surety)
		BY: And Address
		Wallace C. Doyle, Attorney-in-fact In excess of \$75,000,000 LIABILITY LIMITS: (See Federal Register)
		STATE OF INCORPORATION: PENNSYLVANIA
		ANNUAL PREMIUM: \$113.00
		•
•		

-

... مو<sup>ت</sup> ...

### ACKNOWLEDGMENT BY SURETY

STATE OF CALIFORNIA		SS.					2	
County of Los Angeles		1						
On this 12th day of	f Janu	ary	. 19	983 , be	fore me.		a Monsa	lve .
a notary public in and for the St	ate of California w	ith principal				Los An	geles	
residing therein, duly commissio						6		,
								,
known to me to be the person w			within insti	rument as	the attorr	ney-in-fa	ct of the	
INSURANCE COMPANY	OF NORTH AME	RICA						,
the corporation named as Surety	in said instrument	and acknow	wledged to i	me that he	subscribe	ed the na	ame of said	corporation
thereto as Surety, and his own n			6					F
thereto as Surety, and his own h	ame as attorney-m	-ract.						
IN WITNESS WHEREOF, I	have hereunto set	my hand and	affixed my	z official s	eal at my	office i	n the afores	said County.
the day and year in this certifica				orrionar o	, ac 111,			
	te ilist above witt	CII.			/ "			0
OFFICIAL SEAL				X	-	)//	- 110	. Ino
DINA MONSALVE				X	) Med	n	ousa	$\omega$
NOTARY PUBLIC - CALIFORNIA			Notary Pub	lic				
PRINCIPAL OFFICE IN	(seal)	,						
LOS ANGELES COUNTY								
MY COMMISSION EXPIRES APRIL 28, 1985	P							

### INSURANCE COMPANY OF NORTH AMERICA

PHILADELPHIA, PA.

Know all men by these presents: That INSURANCE COMPANY OF NORTH AMERICA, a corporation of the Commonwealth of Pennsylvania, having its principal office in the City of Philadelphia, Pennsylvania, pursuant to the following Resolution adopted by the Board of Directors of the said Company on May 28, 1975, to wit:

"RESOLVED, pursuant to Articles 3.6 and 5.1 of the By-Laws, the following Rules shall govern the execution for the Company of bonds, undertakings, recognizances, contracts and other writings in the nature thereof:

- (1) That the President, or any Vice-President, Assistant Vice-President, Resident Vice-President or Attorney-in-Fact, may execute for and in behalf of the Company any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof, the same to be attested when necessary by the Secretary, an Assistant Secretary or a Resident Assistant Secretary and the seal of the Company affixed thereto; and that the President or any Vice-President may appoint and authorize Resident Vice-Presidents, Resident Assistant Secretaries and Attorneys-in-Fact to so execute or attest to the execution of all such writings on behalf of the Company and to affix the seal of the Company thereto.
- (2) Any such writing executed in accordance with these Rules shall be as binding upon the Company in any case as though signed by the President and attested by the Secretary.
- (3) The signature of the President or a Vice-President and the seal of the Company may be affixed by facsimile on any power of attorney granted pursuant to this Resolution, and the signature of a certifying officer and the seal of the Company may be affixed by facsimile to any certificate of any such power, and any such power or certificate bearing such facsimile signature and seal shall be valid and binding on the Company.
- (4) Such Resident Officers and Attorneys-in-Fact shall have authority to certify or verify copies of this Resolution, the By-Laws of the Company, and any affidavit or record of the Company necessary to the discharge of their duties.
- (5) The passage of this Resolution does not revoke any earlier authority granted by Resolution of the Board of Directors on June 9, 1953."

does hereby nominate, constitute and appoint WALLACE C. DOYLE, of the City of Los Angeles, State of California

beate of carriornia			
its true and lawful attorney-in-fact, to any and all bonds, undertakings, recognized execution of such writings in pursuant and amply as if they had been duly Company at its principal office.  IN WITNESS WHEREOF, the sail has hereunto subscribed his name and NORTH AMERICA this	gnizances, contracts and other ce of these presents, shall be a executed and acknowledged of the MICHAEL B. FODOR d affixed the corporate seal of	er on its behalf, and as i writings in the nature th as binding upon said Co by the regularly elected of the said INSURANCE	ts act and deed nereof. And the ompany, as fully officers of the Vice-President, COMPANY OF
NORTH AMERICA this25th_	day of	June.	. 19.81
STATE OF ILLINOIS COUNTY OF COOK	b Mic	NCE JOMBANY, OF NO Least 15. Tool L B. FODOR	NETH AMERICA Vice-President
On this25th_Public of the STATE OF ILLINOIS	day ofJune	, A. D. 19.81, befo	
MICHAEL B. FODOR  COMPANY OF NORTH AMERICA to me per instrument, and he acknowledged that he corporate seal of said Company; that the sedirection of the said corporation, and that in the preceding instrument, is now in force.  IN TESTIMONY WHEREOF, I have the day and year first above written.	ersonally known to be the individue executed the same; that the seal said corporate seal and his signat Resolution, adopted by the Board hereunto set my hand and affixed	, Vice-President of ual and officer who execute affixed to the preceding is ure were duly affixed by the of Directors of said Comp	the INSURANCE ed the preceding nstrument is the he authority and pany, referred to of CHICAGO

My commission expires 2/6/85

1, the undersigned, \*\*\*

1, the undersigned, \*\*

the Corporation, this 12th day of January 19.83

BS-15579 Ptd. in U.S.A.

(SEAL)

TAMES S. WYLLIE

PHYLLIS DUBAK

XXXXXXXSecretary

Notary Public.

Alexander & Alexander of California Inc. 3550 Wilshire Boulevard Los Angeles, California 90010 Telephone 213 385-5211 TWX 910-321-2907



July 6, 1982

Mr. Thomas B. Golz U.S. Enviornmental Protection Agency Region V Waste Management Branch 230 S. Dearborn Street Chicago, Illinois 60604

Mr. Tom Cavanagh Division of Land Pollution Control, #24 2200 Churchill Road Springfield, Illinois 62706

#### Gentlemen:

Please be advised that Alexander & Alexander, Inc., which is a duly licensed insurance broker and/or agent, is presently and will continue throughout the 90 day period commencing July 6, 1982 to diligently pursue closure/post-closure insurances, conforming to specifications of E.P.A. regulation with available qualified insurers, on behalf of Northrop Corporation, 1800 Century Park East, Los Angeles, California 90067.

Details of locations, E.P.A. numbers and estimates of closing costs provided by Northrop are enclosed.

Yours very truly,

ALEXANDER & ALEXANDER OF CALIFORNIA, INC.

Robert E. Rayfield

Assistant Vice President

cc: G. F. Curtis, Senior V.P. ALEXANDER & ALEXANDER, INC. 1211 Avenue of the Americas New York, New York 10026

enclosures

### NORTHROP CORPORATION 1800 Century Park East Los Angeles, CA. 90067

UNIT AND LOCATION/S	EPA NUMBER	EST. CLOSING COST		
DEFENSE SYSTEMS DIVISION 600 Hicks Road Rolling Meadows, IL, 60008	ILD005128988	\$ 15,000		

C.2 Compliance/ Enforcement

46



217/782-6761

Refer to: 0312730002 -- Cook County

Forthrop Corp. ILEO (651 28 908 MCRA - Permits

May 6, 1988

Morthrop Corp. 600 Bicks Rd. Rolling Kendows, Illinois 60006

Atta: Environmental Coordinator or

Flant Farager

Dear Str:

According to Agency files, your facility currently manages bazardous waste in containers and/or tasks subject to the requirements of 35 IAC 700-725. 35 IAC 703.167(f) states that interim status for any hazardous waste storage or treatment facility will be terminated November 8, 1992, unless the facility submits Part B of the RCRA permit application for these units to this Agency by Movember 8, 1988. This letter is written to (1) make you aware of this requirement and (2) describe the actions which must be taken in response to tels requirement.

According to 38 IAC 703.167(f), if an existing facility desires to (1) store hazardous waste on-site for greater than minety (50) days, (2) treat hazardous maste, or (3) store bezardous maste as a commercial facility after Hovember 8. 1992, it must submit Part B of the ACHA permit application to this Agency by November 8, 1988. The information which must be contained in this application is described in 35 IAC 703, Subpart D. The enclosed document, entitled "RCRA Permit Suidance" provides more detail regarding the necessary contents of the application and also identifies several guidence documents which will be useful in developing the application. Also included in this document is the form which must be used when submitting the application.

If a facility does not desire to continue storing and/or treating hazardous waste after Movember 8, 1992, it must close the storage and/or treatment unit(s) present at the facility prior to this date. Closure, in this instance, basically means that all contamination must be removed from the unit(s) and if necessary, from the area surrounding these units. The requirements which must be met in closing these units are contained in 35 IAC 725, Subpart G. For you convenience, guidance for the development of a closure plan is contained in the enclosed document entitled "Instructions for the Preparation of Closure Plans for Interio Status ACRA Hazardous Waste Facilities." PLEASE NOTE THAT A CLOSDRE PLAN DOES NOT NEED TO BE SUBSITIED AT THIS TIME. IT MUST HOWEVER, BE SUBMITTED TO THE AGENCY NO LATER THAN MAY 8. 1992.



Page 2

In some instances, there may be several interim status hazardous waste management units at a facility. The facility may desire to pursue a final RCRA permit for a portion of these units and close the rest of them. Because of the uncertainty associated with this option, all interim status units at a facility must be included in Part B of the RCRA permit application, unless a closure plan for the units being closed is submitted with the Part B. If a closure plan is submitted with the Part B, the application need only address those units which will remain in operation.

The only alternatives available for bazardous waste treatment and storage facilities to meet the requirements of 35 IAC 7C3.157(f) are (1) submit Part B of the RCRA perett application by Hovember 3. 1988 or (2) close by Hovember 3. 1992. However, some facilities may have previously filed Part A of the RCRA permit application in error and now feel that the hazardous waste management activities carried out at the facility do not require a RCRA permit (i.e. the Part A was filed for protective measures). If this is the case, the Agency requests that infernation supporting this position be submitted no later than Rovember 8, 1988. The Agency can then review the information submitted and correct its records accordingly. The information which must be submitted to make this demonstration is contained in the enclosed document entitled "Facility Part A Withdrama | Request Form."

Finally, some facilities may have closed or are currently closing in accordance with an IEPA approved closure plan. (Please bear in mind this letter is going out to over 200 facilities; some closed facilities may inadvertently receive this letter.) In this instance, the Agency requests that a copy of (1) the closure plan approval letter and (2) the letter from the Agency accepting the certifications of the owner/operator and the registered professional engineer that closure was carried out in accordance with the approved closure plan (if closure has been completed) be submitted by November 8, 1988. The Agency will again be able to review this information and correct its records accordingly.

Because of the large number of facilities subject to the requirements of 35 IAC 703.157(f), the Agency requests that all facilities receiving this letter complete the enclosed form entitled "MCRA Pereit Information Form." The form has been developed such that it can be used by a facility failing into any of the five categories described above (pursuing a final permit, planning to close, pursuing a permit for only a portion of the interio status units and closing the other units, pretective filers, closed in accordance with an IEPA approved closure plan). This form must be submitted to the Agency no later than November 8, 1968, along with all required attachments. Failure to do so may subject a facility to enforcement under State and/or Federal regulations and possible monetary penalties up to \$25,000 per day of noncompliance.



Page 3

The RCEA Permit Information Form and all required attachments must be submitted in triplicate (original and two (2) copies) to the following address:

Permit Section, RCRA Unit Division of Land Foliation Control Illinois Environmental Protection Agency 2200 Churchill Road P.O. Box 19275 Springfield, IL 62794-9276

If you have any questions regarding this letter, please contact Jim Hoore at 217/782-9875.

Very truly yours,

Laurence W. Easter, P.E., Namager Perett Section Division of Land Poliution Control

LHE: JKN: rd13131/13145

Enclosures

cc: Division File Compliance Maywood Region USEPA Legion V

### RECEIVED

JUN 21 1982

WASTE MANAGEMENT BRANCH EPA, REGION V

一一つないはいのはままり

217/782-6760

Refer to: 03127302 - Cook County - Rolling Meadows/Northrop Corp. D.S.D.

June 17, 1982

Mr. James Nelson Northrop Corp. D.S.D. 600 Hicks Road Rolling Meadows, Illinois 60068 Northrop Corp. 1800 Century Park East Los Angeles, California 90067

Gentlemen:

After reviewing the Interim Status Standards inspection conducted on your facility, we discovered an error in the I.E.P.A. site number issued to your facility. On your copy the number assigned is 03127307. This number should be corrected to read 03127302. Please make the necessary correction and use the new number on any future correspondence.

By copy of this letter, we are informing the U.S.E.P.A. of the error and necessary correction needed to be made.

Thank you for your cooperation.

Sincerely,

James C. Reid, Manager Field Operations Section Division of Land Pollution Control

JCR/BB/mks/5

cc: Bob Stone - U.S.E.P.A Northern Region



### El. vironmental Protection Agency

2200 Churchill Road, Springfield, Illinois 62706

217/782-6760

Refer to: 03127302 - Cook County - Rolling Meadows/Northrop Corp. D.S.D.

ILD005128988

June 2, 1982

Bob Stone U. S. Environmental Protection Agency Region V 230 South Dearborn Chicago, Illinois 60604

Dear Bob:

The copy of the above referenced site has an error in the site number on the I. S. S. Inspection. Your copy of the inspection has the site number 03127307 and this should be 03127302. Please make the necessary corrections to your copy.

Your cooperation is appreciated. Should you have any questions regarding this change, please contact Barb Ballard at the above telephone number.

Sincerely,

James C. Reid, Manager
Field Operations Section
Division of Land Pollution Control

JCR/BB/tk/14-2

cc: Northern Region Division File

RECEIVED

JUN 04 1982

OFFICE OF GRANT SUPPORT AIR AND HAZARDOUS MATERIALS DIVISION & EPA, REGION V

PARS 6-7-82



## 176 S. First Street Maywood, IL. 60153. 767

312/345-9780

Refer to: 03127307 - Cook County - Rolling Meadows/Northrop Corp D.S.D. ILD005128988 .

May 7, 1982

Mr. James Nelson
Northrop Corp. DSD
Northrop Corporation
600 Hicks Road
Rolling Meadows, Illinois 60008
Northrop Corporation
1800 Century Park East
Los Angeles, Ca. 90067

Dear Mr. Nelson:

On March 23, 1982, representatives of the Illinois Environmental Protection Agency (IEPA) conducted an inspection of Northrop Corp. Defense Systems Division, Rolling Meadows, Ill. This inspection was conducted by the Illinois Environmental Protection Agency under a Cooperative Arrangement with, and authorization of, the United States Environmental Protection Agency (USEPA). The purpose of the inspection was to determine your facility's compliance status with the Resource Conservation and Recovery Act (RCRA) of 1976, P.L. 94-580, as amended. During the inspection the following deficiencies were observed:

Pursuant to 40 CFR 265.15(b) the owner/operator is to establish and maintain inspection records and schedules which detail records of malfunctions, operator errors, discharges, safety and emergency equipment, security devices, and operating and structural devices. Your facility is deficient in that no inspection logs or schedules were available for review.

Pursuant to 40 CFR 265.16, the owner/operator is required to establish and maintain records relating to the training of personnel involved in hazardous waste management, including a description of the job title for each position at the site, a written job description, a description of training and records detailing the training given to each such individual. The owner/operator is deficient in that no job titles or job descriptions are maintained as required.

Pursuant to 40 CFR 265.73 the owner/operator must keep a written operating record at the facility. The operating record must include the following:

- 1) A description and the quantity of each hazardous waste received and the method(s) and date(s) of its treatment, storage or disposal at the facility as required by Appendix I.
- The location and quantity of each hazardous waste within the facility including cross-references to specific manifest document numbers.

- 3) Records and results of waste analyses and trial tests.
- 4) Summary reports and details of all incidents that require implementation of the contingency plan.
- 5) Records and results of inspections.
- 6) Monitoring and testing data.
- 7) All closure cost estimates and for disposal facilities all post-closure cost estimates.

Your facility is deficient in that no operating record was available for review.

The owner/operator must have a closure plan at the facility. The plan must include a description of how and when the facility will be partially closed, if applicable, and ultimately closed. The plan must address the steps needed to decontaminate facility equipment. Also required is an estimate of the maximum inventory of wastes in storage or treatment on site at any given time and a schedule for final closure including the anticipated date when wastes will no longer be required. The owner/operator must submit his closure plan to the Regional Administrator at least 180 days before the date he expects to begin closure. These requirements are pursuant to 40 CFR 265.112. Your facility is deficient in that no closure plan had been developed as required.

The owner/operator must have a contingency plan at the facility. The contingency plan must address the actions to be taken by facility personnel in response to fires, explosions, or any unplanned release of hazardous waste or hazardous constituents to the environment. The plan must describe the arrangements agreed to by local police, fire departments, hospitals and emergency response The names, addresses, and phone numbers of all persons qualified to act as emergency coordinators must be included in the The contingency plan must list all emergency equipment at the facility, including the location, a physical description, and a brief summary of the capabilities of each item on the list. facilities where evacuation could be necessary a plan describing evacuation routes and signals used to begin evacuation must be included in the contingency plan. These requirements are pursuant to 40 CFR Part 265 Subpart D. Your facility is deficient in that a) no arrangements had been made with local emergency response teams, b) no listing of facility emergency equipment had been compiled, and c) emergency coordinators had not been identified as required.

Requirements contained in 40 CFR 265.53(b) were not complied with in that copies of the contingency plan were not submitted to local emergency response organizations.

You are hereby requested to submit to this office, within 15 days of receipt of this letter, a description of steps taken to correct the above deficiencies. Failure to correct these deficiencies may result in enforcement actions initiated by USEPA pursuant to 40 USC 6928. Please send your reply to the above address. Should you have any questions concerning this matter, please contact Glenn Sternard of my starf at the above number.

Sincerely,

Amund P. Bulg

Kenneth P. Bechely, Northern Region Manager Field Operations Section Division of Land Pollution Control

KPB: GJS: prb

Enclosure: Inspection Report

cc: Division File
Northern Region
U.S. E.P.A. - Regio

U.S. E.P.A. - Region V

## RCRA INSPECTION REPORT - INTERIM STATUS STANDARDS TREATMENT, STORAGE, AND DISPOSAL FACILITIES Form A - General Facility Standards

### I. General Information:

(A)	Facility Name:	Northrop Corp Detense Systems Divisions
(B)	Street:	600 Hicks Rd
(C)	City:	Colling Meanows (D) State: IL (E) Zip Code: 60008
(F)	Phone: (312	) 259-9600 (G) County:
(H)	Operator:	SAME.
(IJ)	City:	(K) State:(L) Zip Code
(M)	Phone:	(N) County:
(0)	•	NORTHROP Corporation
(P)	Street:	1800 CENTURY Park East
(Q)	City: L	OS Angeles (R) State: CA (S) Zip Code: 90067
		) 553 -6262 (U) County:
(V)	Date of Inspec	tion: <u>3-23-82</u> (W) Time of Inspection (From) 10:00 A (To) 1145 A
(X)	Weather Condit	ions: 45° Sunny

(Y).	Person(s) Interviewed	Title	Telephone
	AMES NELSON	Maint Supr.	(312) 259-9600
, .		(Proj. Co-od)	
(Z)	Inspection Participants	Agency/Title	Telephone
	Glenn Sternard	ICPA / EPS	(312) BAS-9780
	Glenn Sternard Lynn Crivers	ZEPA SPS	i.e.
(AA)	Preparer Information		
	Name Glenn Sternard	Agency/Title	Telephone
	<u>II.</u>	SITE ACTIVITY:	
,	Complete sections I through VII for facilities. Complete the forms (in to the site activities identified b	parenthesis) in section V	
X	A. Storage and/or Treatment Containers (I)	D. Incineration and (O and P)	/or Thermal Treatment
	<ul><li>2. Tanks (J)</li><li>3. Surface Impoundments (K)</li><li>4. Waste Piles (L)</li></ul>	E. Chemical, Physic Treatment (Q)	cal, and Biological
	B. Land Treatment (M)		
	C. Landfills (N)		•

 $\frac{\text{Note:}}{\text{IX and X of this form as appropriate.}} \\ \frac{\text{In facility is also a generator or transporter of hazardous waste complete sections}}{\text{IX and X of this form as appropriate.}}$ 

### III. GENERAL FACILITY STANDARDS: (Part 265 Subpart B)

,
·
·
- <del></del>

### ...i. GENERAL FACILITY STANDARDS Continued

		•	Yes	No	NI*	Rémarks
	4.	Inspection schedule?		V .	***	*
	5.	Safety, emergency equipment?	/	, +++	+++	govnit Agency Qudits lorly
•	6.	Security devices?				year forsately.
	7.	Operating and structural devices?			***	
	8.	Inspection log?	+		***	***********
(E)		personnel training records lude: (Effective 5/19/81)				
	1.	Job titles?	***		***	
	2.	Job descriptions?	,			****
	3.	Description of training?			***	*****
	4.	Records of training?		•	***	***
	5.	Have facility personnel received required training by 5-19-81?			***	
•	6.	Do new personnel receive required training within six months?	1		***	
					, -	
(F)	rec	required are the following special quirements for ignitable, reactive, or compatible wastes addressed?				
	1.	Special handling?		/ 	***	\$\$####################################
	2.	No smoking signs?		***	***	*********
	3.	Separation and protection from ignition sources?	_		***	*****

### IV. PREPAREDNESS AND PREVENTION: (Part 265 Subpart C).

(A)	Maintenance and Operation of Facility:	Yes No NI* Remarks
* *	Is there any evidence of fire, explosion, or release of hazardous waste or hazardous waste constituent?	
(B)	If required, does the facility have the following equipment:	
	1. Internal communications or alarm systems?	/ Northrop maintains own seconty system
	2. Telephone or 2-way radios at the scene of operations?	
82	3. Portable fire extinguishers, fire control, spill control equipment and decontamination equipment?	
	Indicate the volume of water and/or foam	available for fire control:
(C)	Testing and Maintenance of Emergency Equipment:	
(c)		
(c)	<ul><li>Emergency Equipment:</li><li>1. Has the owner or operator established testing and maintenance procedures</li></ul>	
(C)	<ol> <li>Has the owner or operator established testing and maintenance procedures for emergency equipment?</li> <li>Is emergency equipment maintained in operable</li> </ol>	

(E)		there adequate aisle space unobstructed movement?	_	· ·			
,		V. CONTINGENCY PLAN (Part 265	AND E Subp	MERGE Dart D	NCY PRO	CEDURES:	
(A)		s the Contingency Plan contain the lowing information:	Yes	No	NI*	Remarks	
	1.	The actions facility personnel must take to comply with §265.51 and 265.56 in response to fires, explosions, or any unplanned release of hazardous waste? (If the owner has a Spill Prevention, Control, and Countermeasures (SPCC) Plan, he needs only to amend that plan to incorporate hazardous waste management provisions that are sufficient to comply with the requirements of this Part (as applicable.)					
	2.	Arrangements agreed by local police departments, fire departments hospitals, contractors, and State and local emergency response teams to coordinate emergency services pursuant to §265.37?		<u> </u>		No ARRANGEMENT	in waiting
	3.	Names, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinators?		<u>/</u>	· · · · · · · · · · · · · · · · · · ·	No E-coordina	for listed
	4.	A list of all emergency equipment at the facility which includes the location and physical description of each item on the list and a brief outline of its capabilities?		<u>/</u>			:
	5.	An evacuation plan for facility personnel where there is a possibilithat evacuation could be necessary? (This plan must describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes?)	ty			posted in facility, most be include	but. Ed W/plan

•		Yes No NI*	Remarks
(B)	Are copies of the Contingency Plan available at site and local emergency organizations?		
(C)	Emergency Coordinator		
	Is the facility Emergency Coordinator identified?		
	2. Is coordinator familiar with all aspects of site operation and emergency procedures?		Peasons to be appointed
	3. Does the Emergency Coordinator have the authority to carry out the Contingency Plan?		and will hove authority.
(D)	Emergency Procedures		
•	If an emergency situation has occurred at this facility, has the Emergency Coordinator followed the emergency procedures listed in 265.56?		Not necoen to date.
	VI. MANIFEST SYSTEM, RE (Part 265	CORDKEEPING, AND F Subpart E)	REPORTING
		Yes No NI*	Remarks
(A)	Use of Manifest System		
	1. Does the facility follow the procedures listed in §265.71 for processing each manifest?	<u>n</u> /a	
	2. Are records of past shipments retained for 3 years?	<del>-</del>	
(B)	Does the owner or operator meet requirements regarding manifest discrepancies?	<u> </u>	

### VI. RECORDKEEPING - Continued

(C)	Operati	ng Record			et.			
,	mai rec	es the owner or operator ntain an operating cord as required in 5.73?			·			
	con	es the operating record tain the following ormation:						
	**b.	The method(s) and date(s) of each waste's treatment, storage, or disposal as required in Appendix I?	_	_	· ·	. <u>.                                   </u>		-
	c.	The location and quantity of each hazardous waste within the facility?		<u>/</u>				
	***d•	A map or diagram of each cell or disposal area showing the location and quantity of each hazardous waste? (This information should be cross-referenced to specific manifest number, if waste was accompanied by a manifest.)	NA					
	e.	Records and results of all waste analyses, trial tests, monitoring data, and operator inspections?	1		7 .			
	f.	Reports detailing all incidents that required implementation of the Contingency Plan?	. ·	_				
 -	g.	All closure and post closure costs as applicable? (Effective 5-19-81)		<u></u>				
					•			

<sup>\*\*</sup> See page 33252 of the May 19, 1980, Federal Register.

<sup>\*\*\*</sup> Only applies to disposal facilities

### VII. CLOSURE AND POST CLOSURE (Part 265 Subpart G)

			Yes	No	NI*	Remarks	
(A)	Clos	sure and Post Closure				·	
·	1.	Is the facility closure plan available for inspection by May 19, 1981?		_	· 	· · · · · ·	
	2.	Has this plan been submitted to the Regional Administrator		1		closure	has not been
	3.	Has closure begun?				·	we.
	4.	Is closure estimate available by May 19, 1981?					
(B)	Post	t closure care and use of property					
	a po	the owner or operator supplied ost closure monitoring plan? fective by May 19, 1981)			<u>u/a</u>		
Faci	litv	VIII. FACI (Part 265, Su  USE AND MANAGEM Name: Neethrop DSD	bpart I	s I th	iru R) TAINERS	nsnection	3-23-8z
i ac i	i i cy	Halle: NOSCAMOB DJ					<u> </u>
			res	No	NI*	Remarks	
	1.	Are containers in good condition?					
	2.	Are containers compatible with waste in them?	<u>.v/</u>	/	<del></del>		
	3.	Are containers stored closed?					
	4.	Are containers managed to prevent leaks?	<u></u>	_	4		
	5.	Are containers inspected weekly for leaks and defects?	_	<u> </u>	•	-	
	6.	Are ignitable & reactive wastes stored at least 15 meters (50 feet) from the facility property line? (Indicate if waste is ignitable or reactive.)	<u>/</u>				· · · · · · · · · · · · · · · · · · ·

. 7.	Are incompatible wastes stored in separate containers? (If not, the provisions of 40 CFR 265.17(b) apply.)	1	~~~			P <del></del>	·	tipe alor Alos ann ann ann tipe agr-a
8.	Are containers of incompatible waste separated or protected from each other by physical barriers or sufficient distance?			-	*****			
	ſ	J TANKS			•	,		-
Facility	Name: NA	-	Date	of	Inspection	• •		
1.	Are tanks used to store only those wastes which will not cause corrosileakage or premature failure of the tank?	on,	:	<del></del>			· · · · · · · · · · · · · · · · · · ·	
2.	Do uncovered tanks have at least 60 cm (2 feet) of freeboard, or dikes or other containement structures?			-	· · · · · · · · · · · · · · · · · · ·			,
3.	Do continuous feed systems have a waste-feed cutoff?							
4.	Are waste analyses done before the tanks are used to store a substantially different waste than before?	10-10-10	***	-	•		,,,,,,,	
5.	Are required daily and weekly inspections done?	***	***					*****
6.	Are reactive & ignitable wastes in tanks protected or rendered non-reactive or non-ignitable? Indicate if waste is ignitable or reactive. (If waste is rendered non-reactive or non-ignitable, see treatment requirements.)							******
7.	Are incompatible wastes stored in separate tanks? (If not, the provisions of 40 CFR 265.17(b) apply.)		•		****			****

Yes No

NI\*

Remarks

			,			,
,		Yes	No	NI*	Remarks	
	Has the owner or operator addressed the waste analysis requirements of 265.402?		<del></del>	÷ .		
4.	Are inspection procedures followed according to 265.403?			_		
5.	Are the special requirements fulfilled for ignitable or reactive wastes?					
6.	Are incompatible wastes treated? (If yes, 265.17(b) applies.)	·			- Control of the Cont	· ·
	tanks, transport vehicles, vessels, of hazardous only because they exhibit to or are listed as hazardous wastes in Complete this section if the owner or hazardous waste that is subsequently significant disposal.	the con Subpan IX opera	rrosiv rt D or tor of	ity cha f 40 CF a TSD	racteristic under R Part 261 only f facility also gen	40 CFR §261.2 or this reasor erates
	1. MANIFE	EST RE	QUIREM	ENTS		
			No	NI*	Remarks	
(A)	Does the operator have copies of the manifest available for review?	<u></u>	<u>/</u>		•	
(B)	Do the manifest forms reviewed contain the following information: (If possible, make copies of, or record information from, manifest(s) that do not contain the critical elements)					
	1. Manifest document number?					
	<ol> <li>Name, mailing address, telephone number, and EPA ID Number of Generator</li> </ol>	/	/			

			, 00 110	11.2		
	3.	Name and EPA ID Number of Transporter(s)?	<u>/</u> _	<i>4</i>		
•	4.	Name, address, and EPA ID Number of Designated permitted facility and alternate facility?	<u> </u>			
	5.	The description of the waste(s) (DOT shipping name, DOT hazard class DOT identification number)?	· <u>/</u>	<del></del>		
	6.	The total quantity of waste(s) and the type and number of containers loaded?	, · 	· <u></u>		-
	7.	Required certification?	<u> </u>			_
	8.	Required signatures?	✓ <u> </u>	· <u>—</u>		
(C)		es the owner or operator submit ception reports when needed?				
		2. PRE-TRANSF	ORT REQUI	REMENTS		
(A)	wit (Re	waste packaged in accordance th DOT Regulations? equired prior to movement of cardous waste off-site)	<u> </u>		·	
(B)	in con (Re	e waste packages marked and labeled accordance with DOT regulations accerning hazardous waste materials? equired to movement of hazardous ste off-site)	<u>/</u>			
(C)		required, are placards available transporters of hazardous waste?	<u>/</u> _	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	

Use this section to briefly describe site activities observed at the time of the inspection. Note any possible violations of Interim Status Standards.

Site Activity: Northrop's Rolling Meadows facility produces electronic counter-measures - Defense systems is RADAR Detection systems. There are research | Development facilities in addition to the production activities. The majority of production activity appears to be electronic component assembly. Remarks: Northrop produces several waste streams duhich the majority originate from degreesing / cleaning operation.

Among the solvents are (classified FOOI, FOO3) methylene chloride, Freen TMS 150 propyl f methyl dochol, acetone.

The facility also disposes waste Humissac, a material which is grayed on components to minimize the effects of high humidity on these components. The waste is compined with a thinner - usually resulting from deanup operation. Humiseal is applied by spray application similies to paint approx application.

The facility has applied for the startes of generator storage of hornerous waste. As such the following deficiencies were noted:

- No facility inspection schedule on log is maintained
- D No job titles or lob descriptions, as required, ARE maintained
- 3 No facility operating excord.
- De No closure plan en closure cost estimate were available for review.
- 1 Incomplète contingency plan: 10 no arrangement w/ local Emergency res. teams
  - no itemization of Emergency Equipment.
  - @ Emergency coordinators not identified
  - @ Plan was not on file ul tocal emergency response teams.

### ENVIRONMEN L PROTECTION AGENCY STATE OF LINOIS

 $\frac{2}{(1)} - \frac{1}{(8)} - \frac{3}{(8)} = \frac{3}{(8)}$ RSFDVATION REPORT - SITE INVENTORY NO

Gr Ph Pr OP Op Te C1	oun oto evi ERA era mpo ose	es T d Wa s Ta ous FION ting rari d No	Ins AL ly t C	n: ( ) : pect STAT	Yes Yes Yes	s ( rfac s ( n _ : (	) cce( )	CO. /// No No	(I)	L.H	Pre OF Fil.	In OPI	ter ous ERA	Par F T Vie	ty) rom o wed rre	S	on :: :: ::	((##	St Sa A.	ora 1va	ge ge 30)	W I	ett eat nsp	er her ect Sit	te (2) Sen or e O	(2) pen HOR .A. ian e)	7): IZA Pe ce Ord	Yes TIO	(25 No	(2 No ) ) )	9) ( )
SA DE	TER	LORA NERA		EMAI	RKS	t <u>ke</u>		43			16.			les a	2.75				70	20		7.	LP	C 4	1,		5 01		0	(62	2)
		15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		L Edi	790 2001 2014 2014 2014	lack can be	EUC	- 16 - 16 - 16 - 16 - 16 - 16 - 16 - 16	0.ds 8.8 e. 2 l.ds	5 16 - 16 - 16 - 16 - 16 - 16 - 16 - 16	of the state of th	SAL AL	SE British Marie	19. 1. 1. 2. 1. 2. 1.	LE DE S	7 1	12 51 7 11 11 11	eor eor has hah	90 00 2 3 2 3 2 3 2 3	61 / 59 : 1 : 1	the steer	li 00 180 Vin	de Al	lar en ble	180 180 180 180				2 / /2 1 - 3 / 2 2 - 4 / 2 (a - / 2	AU E	
	IN	ΓERV	IEW		* 04 * 14 * 1	7/1 2 = 5 2 A = 1			JES JES S	Jes Cali Day	brd V		a se		63 - 6	les IS	(s) (s) (d)	the Level PP		hi hi kac		10 S	(1 E)	LICA LICA LICA LICA LICA LICA LICA LICA		100 AG	0/L			Te Vi	_
	DIA	AGRA	M:		16 16	tar far			distribution of the second	a n c	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	is s	c d	hac hac	lals		14 2   c	v. 4	us e	es r	2.0 AWA	VZ.	A e	4	(ov	-(c)	(Bu	) (a)			
			6		15.	4(3)		ŧ	i)	aux	İn									3,,			7 (c	ea car		UME (ALL)	D.	F3.	40	aw cdi	
			6			8	Los	ared ared		296	in	· self		Em																	

D. Corrective Action



#### ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 – (217) 782-3397 JAMES R. THOMPSON CENTER, 100 WEST RANDOLPH, SUITE 11-300, CHICAGO, IL 60601 – (312) 814-6026

ROD R. BLAGOJEVICH, GOVERNOR

DOUGLAS P. SCOTT, DIRECTOR

April 23, 2007

Certified Mail 7004 2510 0001 8616 6485

Northrop Gromman Attn: Environmental Coordinator 500/600/600a Hicks Road Rolling Meadows, Illinois 60008

Re:

0312730002 -- Cook County

Northrop Gromman ILD005128988 RCRA Permit

Dear Environmental Coordinator:

The Illinois EPA and the United States Environmental Protection Agency (U.S. EPA) have compiled a list of all facilities deemed appropriate and important to address using the Resource Conservation and Recovery Act's (RCRA) Corrective Action Program. Because this set of 3,880 facilities has national remediation goals which will culminate in the year 2020, it is referred to as the 2020 Corrective Action Universe. Your facility is part of this 2020 Universe.

As a result, a final remedy needs to be in place (i.e., remedy construction completed) at your facility by 2020 (although actual attainment of cleanup goals through remedy implementation may take a while longer). If we have not already done so, we will be working with you to develop a plan and a schedule that achieves this goal before 2020.

Your facility has been included in the 2020 Universe because one or more of the following is true:

- It has a RCRA permit obligation,
- Illinois EPA and U.S. EPA agreed that it needs to be addressed under the RCRA Corrective Action Program, as it at one time operated a hazardous waste management unit subject to the interim status or permit requirements of RCRA.

Inclusion on this list does not imply failure on your part to meet any legal obligation, nor should it be construed as an adverse action against you. It only means that Illinois EPA and U.S. EPA have identified your facility – and every other facility in the 2020 Universe – as needing to complete RCRA Corrective Action if they have not done so already. Our national program goal is to address these cleanup obligations before the end of 2020. Accordingly, progress will be tracked for each facility in the 2020 Universe. The list of facilities will be posted on our web site at <a href="http://www.epa.gov/correctiveaction">http://www.epa.gov/correctiveaction</a> in the near future.

Illinois EPA will work to address remediation concerns at your facility in a manner consistent with your plans for the property. There are a variety of options available for completing the required remediation efforts at your facility, ranging from participation in Illinois EPA's Site Remediation Program to establishment of an Administrative Order on Consent with USEPA under Section 3008(h) of RCRA.

Illinois EPA would like to schedule a meeting with you in the near future to discuss remedial activities at your facility and achievement of the goal mentioned in the second paragraph of this letter. Please contact James K. Moore, P.E. of my staff at 217/524-3295 if you have any questions regarding this letter and to schedule a meeting to discuss the contents of this letter.

Sincerely,

Stephen F. Nightingale, P.E.

Manager, Permit Section

Bureau of Land

SFN:JKM:bjh\072572s.dot

cc: Hak Cho, USEPA, Region 5



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

DE-9J

April 17, 2007

Mr. David Gurrie
Manager,
Environmental and Safety Compliance
Northrop Grumman Systems Corp.
600 Hicks Road
M.S. H-6282
Rolling Meadows, IL 60008

RE: Northrop Grumman Systems Corp. EPA ID# ILD005128988 RCRA 2020 Corrective Action Universe

Dear Mr. Gurrie:

Thank you for taking the opportunity to discuss the Northrop Grumman Systems Corp. facility with us. As we discussed in our call, please find the enclosed copy of the April 15, 1994 Preliminary Assessment/Visual Site Inspection (PA/VSI) report from the investigation conducted on behalf of the United States Environmental Protection Agency (US EPA) by PRC Environmental Management, Inc. Please note that certain pages from this report stamped as "enforcement confidential" have now been released for distribution to Northrop Grumman, and are stamped as such.

The PA/VSI report indicated the presence of 8 solid waste management units (SWMUs) and one area of concern (AOC) at your facility. Although none of the SWMUs or AOCs indicated evidence of a release, certain recommendations for further action were noted for US EPA's attention. They are:

SWMU 3 (Room 6419)-Operated from 1988 until the time of the PA/VSI: PA/VSI recommended application of new floor covering obtaining an air permit if necessary.

SWMU 5 (Room 5097)-Operated from 1980 until the PA/VSI, RCRA closed in 1987: PA/VSI recommended inspection, sampling underneath, and repair of floor cracks, and to reapply epoxy floor covering, and obtain air permit if necessary.

AOC (Former UST Location) - Operated from 1971 to 1977: PA/VSI recommended collection of subsurface soil samples.

We would appreciate receiving any new information that you have developed since the PA/VSI report was prepared. We are especially interested in any sample analytical results that you may have. US EPA will work with you to address any remediation concerns at your facility for which the evidence discussed above does not exist, or for which further evidence is required.

If you have any questions on this correspondence or this call, please don't hesitate to contact me at (312) 353-2720, or by e-mail at <a href="mailto:freeman.brian@epa.gov">freeman.brian@epa.gov</a>.

Sincerely,

Brian P. Freeman

Senior Chemist

Corrective Action Project Manager

cc: Northrop Grumman Systems Corrective Action File



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

DE-9J

April 17, 2007

Mr. David Gurrie
Manager,
Environmental and Safety Compliance
Northrop Grumman Systems Corp.
600 Hicks Road
M.S. H-6282
Rolling Meadows, IL 60008

RE: Northrop Grumman Systems Corp.

EPA ID# ILD005128988

RCRA 2020 Corrective Action Universe

Dear Mr. Gurrie:

Thank you for taking the opportunity to discuss the Northrop Grumman Systems Corp. facility with us. As we discussed in our call, please find the enclosed copy of the April 15, 1994 Preliminary Assessment/Visual Site Inspection (PA/VSI) report from the investigation conducted on behalf of the United States Environmental Protection Agency (US EPA) by PRC Environmental Management, Inc. Please note that certain pages from this report stamped as "enforcement confidential" have now been released for distribution to Northrop Grumman, and are stamped as such.

The PA/VSI report indicated the presence of 8 solid waste management units (SWMUs) and one area of concern (AOC) at your facility. Although none of the SWMUs or AOCs indicated evidence of a release, certain recommendations for further action were noted for US EPA's attention. They are:

SWMU 3 (Room 6419)-Operated from 1988 until the time of the PAVSI: PAVSI recommended application of new floor covering obtaining an air permit if necessary.

SWMU 5 (Room 5097)-Operated from 1980 until the PA/VSI, RCRA closed in 1987: PA/VSI recommended inspection, sampling underneath, and repair of floor cracks, and to reapply epoxy floor covering, and obtain air permit if necessary.

AOC (Former UST Location) - Operated from 1971 to 1977: PA/VSI recommended collection of subsurface\soil samples.

Autually 1967 - Original Blog Brann 500 on 100% Recycled Paper (50% Postonoumer) Collecto "Collina"

Recycled/Recyclable • Printed with Vegetable Oil Based Inks on 100% Recycled Paper (50% Post

We would appreciate receiving any new information that you have developed since the PA/VSI report was prepared. We are especially interested in any sample analytical results that you may have. US EPA will work with you to address any remediation concerns at your facility for which the evidence discussed above does not exist, or for which further evidence is required.

If you have any questions on this correspondence or this call, please don't hesitate to contact me at (312) 353-2720, or by e-mail at <a href="mailto:freeman.brian@epa.gov">freeman.brian@epa.gov</a>.

Sincerely,

Brian P. Freeman

Senior Chemist

Corrective Action Project Manager

cc: Northrop Grumman Systems Corrective Action File



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

APR 0 3 2007

REPLY TO THE ATTENTION OF 191

## CERTIFIED MAIL RETURN RECEIP REQUESTED

William Cameron Northrop Gumman Systems Corp 600 Hicks Road Room H6282 Rolling Meadows, Illinois 60008

RE:

Northrop Gumman Systems Corp

500/600/600A Hicks Road, Rolling Meadows, Illinois – EPA ID # ILD005128988

Dear Mr. Cameron:

The Illinois Environmental Protection Agency (IEPA) and the United States Environmental Protection Agency (U.S. EPA) have compiled a list of all facilities deemed appropriate and important to address using the Resource Conservation and Recovery Act's (RCRA) Corrective Action Program. Because this set of 3,880 facilities has national remediation goals which will culminate in the year 2020, it is referred to as the 2020 Corrective Action Universe. Your facility is part of this 2020 Universe.

As a result, the IEPA and U.S. EPA expect that a final remedy will be in place (i.e. remedy construction completed) at your facility by 2020 (although actual attainment of cleanup goals through remedy implementation may take a while longer). If we have not already done so, we will be working with you to develop a plan and a schedule that achieves this goal before 2020.

Your facility has been included in the 2020 Universe because one or more of the following is true:

- It already belongs to the 2008 Corrective Action Baseline,
- It has a RCRA permit obligation,
- IEPA and U.S. EPA agreed that it needs to be addressed under the RCRA Corrective Action Program.

Inclusion on this list does not imply failure on your part to meet any legal obligation, nor should it be construed as an adverse action against you. It only means that IEPA and U.S. EPA have identified your facility—and every other facility in the 2020 Universe—as needing to complete RCRA Corrective Action if they have not done so already. Our national program goal is to largely address these cleanup obligations before the end of 2020. Accordingly, progress will be tracked for each facility in the 2020 Universe. The list of facilities will be posted on our web site at http://www.epa.gov/correctiveaction on April 16, 2007.

U.S. EPA Region 5 will work to address remediation concerns at your facility in a manner consistent with your plans for the property. If you believe that facility-wide corrective actions are already complete for your site, or if you have any questions regarding this letter, please contact Brian Freeman at (312) 353-2720.

Sincerely,

Jose G. Cisneros, Chief

Waste Management Branch

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

DATE:

JAN 26 100

SUBJECT:

Revised FOIA Procedures for Preliminary Assessment/

Visual Site Inspection (PA/VSI) Reports

FROM:

Joseph Boyle, Chief AND

Willie Harris. Chief

Enforcement and Compliance Program Management Branch

Assurance Branch

TO: All ECAB and PMB Staff

> This memorandum outlines the revised procedures to be used when a releasability determination under FOIA needs to be made for a PA/VSI. All facilities with PA/VSI reports completed have been ranked as high (H), medium (M), or low (L) priority facilities for corrective action. The old procedure required that any PA/VSI report requested under FOIA be submitted to the Enforcement and Compliance Assurance Branch for a determination of releasability. In an effort to streamline this process and better serve our customers the responsibility of evaluating releasability of these documents will reside with PMB. The following process shall be utilized:

- For those facilities designated as high. medium, or low priority facilities, the PMB staff person shall send a WPO or voicemail message to the appropriate Enforcement Section Chief (currently Lorna Jereza for IL/IN, George Hamper for MN/OH, and Paul Little for MI/WI) to inquire as to the releasability of information concerning the facility. If there are no pending actions, the complete PA/VSI report can be sent out with the standard disclaimer that the conclusions and recommendations are those of a U.S. EPA contractor and may not reflect those of U.S. EPA. If there is a pending enforcement situation, then the procedure outlined in the bullet below shall be followed. Note that information concerning any pending enforcement action should not be released or discussed with the requestor.
- For those facilities designated as high priority facilities where an enforcement action is imminent, the "Executive Summary" and "Recommendations and Conclusions" sections of the PA/VSI should be withheld as enforcement confidential. The enforcement individual responsible for the site must prepare a Statement of Harm memorandum for withholding those portions of the PA/VSI report. For more information on preparing this memorandum, please refer to the memorandum dated June 29, 1995, "FOIA Discretionary Release Policy Statements of Harm for PA/VSI Reports" from Thomas Williams, ORC to Laura Lodisio (Confidential-Privileged Attorney Client Communication).

de pends on 670 s. 4 some devials the statent of Hour is required

REGEIVED

# NORTHROP GRUMMANUS. EPA, REGION VI

Electronics Systems Division Northrop Grumman Corporation 600 Hicks Road Rolling Meadows, IL 60008-1098 Telephone 708-259-9600

September 14, 1994

Kevin M. Pierard, Chief Minnesota/Ohio Technical Enforcement Section RCRA Enforcement Branch USEPA Region 5 77 W. Jackson Boulevard Chicago, Il. 60604-3590 RECEIVED WMD RECORD CENTER OCT 04 1994

Re: Visual Site Inspection
Northrop Corporation
Electronics Systems Division
Rolling Meadows, IL.
ILD 005 128 988

Dear Mr. Pierard,

We have received the site's copy of the USEPA final Preliminary Assessment/Visual Site Inspection (PA/VSI) report issued by your office on June 29, 1994 for our site. Our review of the report has identified several points where the auditors have misinterpreted the discussions of our processes. We contacted PRC who advised us to submit our corrections in writing to your office.

We consider correcting these points to be important as they may give the reader an inaccurate perception of the facility and may prove to be problematic if left uncorrected. We assume that addressing these errors is also important to you since any report submitted to the Agency should be accurate. Therefore, Northrop is submitting the following corrections for review and incorporation by your office into the final report.

1. The wastewater treatment system, referred to as "WWTP (SWMU 1)" in the report, incorrectly describes this system as treating waste from all areas of the facility. Additionally, other errors within the report concerning the operation of the WWTP would be clarified by the following system description.

The WWTP system only treats rinsewater and spent plating baths generated within the Printed Wiring Board manufacturing area (PWB). Rinsewater, which represents > 99% of the daily treated waste water, is transported via floor drains to sumps, and is then pumped directly to the system in overhead pipes. Drum

## PA/VSI RESPONSE Page 2

rinsate, from PWB raw material drums, is discharged into the same floor drains and is combined with the rinsewater. Spent plating baths are pumped through a separate piping system to a holding tank which is then bled into the waste water stream for treatment.

Treatment is accomplished by filtering the waste water, removing metals using four ion exchange columns, adjusting the pH, and then discharging the waste water into the sanitary sewer system. The columns are periodically regenerated by stripping off contaminant metals with strong acid. The regenerating acid, containing concentrated metals, is reclaimed using an electrolytic cell where the metals are plated out as recyclable metal sheets. The acid is then returned to a holding tank to be used for future column regeneration.

The WWTP system also treats PWB effluent from the photoresist stripping process. Since the photoresist contains plastics which will damage the waste water treatment system, the material is batch treated separately. This is accomplished by segregating the photoresist in barrels, transporting it into the WWTP room, and then treating it in a separate section of the system. Treatment involves chemical precipitation of the dissolved plastic followed by filtration. The effluent from the filter press is introduced into the system's final pH adjust tank prior to discharge to the sanitary sewer. The filter cake is accumulated in 55 gallon drums, moved into hazardous waste storage, room H6419, for storage, then shipped off site for disposal.

PWB wastes which are not compatible with the system are spent baths containing gold cyanide, concentrated nickel and lead. These wastes are transported in 55 gallon drums to hazardous waste storage, room 6419, where they are stored for up to 90 days, then shipped off site for recycling or treatment.

2. Two Baron-Blakeslay Freon degreasers/stills, identified as "SWMU 6" in the report, are described as Freon reclaim units. Actually, the primary operation of these units is for non-critical cleaning (degreasing) of parts.

The Freon quality requirement for non-critical Freon cleaning operations is lower than that of most other Freon cleaning operations on site. Therefore, as part of a Freon conservation and phase out program that Northrop initiated in 1990, spent material from other degreasers is used as feed stock for these degreasers. This cascade approach eliminated the need to purchase new Freon for these two units.

At the time of the inspection, two Baron-Blakeslay degreasers were independently piped to two Baron-Blakeslay stills. Since

PA/VSI RESPONSE Page 3

the inspection, one degreaser and still has been phased out of service. The systems operate by continuously flowing Freon through the stills where impurities are separated by distillation. The still bottoms are periodically removed, accumulated, then sent to Safety Kleen for recycling.

Prior to 1990 all degreasers, including these two, used new Freon. As the Freon became contaminated, it was removed, accumulated in 55 gallon drums, then sent to Safety Kleen where it was recycled. The conservation program significantly reduced the volume of spent Freon recycled off site and the purchase of new Freon.

3. The report's section on "History of Documented Releases" should elaborate the description of our environmental setting to explain why trace metals might be found at the perimeter of our site.

The report identifies a 1987 environmental boundary survey of our site which indicated the presence of arsenic, chromium, and lead. However, it does not provide any insight to the environmental setting that may have contributed to the findings.

Most of the environmental factors that could have contributed to the metals found were discussed at the time of the survey. These factors were the topography, prior use, and present use of the land in the immediate area. Prior to 1980 the northeast corner of Northrop's property was a low lying marshy area which collected rainwater runoff from the surrounding area. As a result, it seemed highly likely that the farming in the area up to the mid 1960's, the proximity of several major highways, the proximity of the Chicago & Northwestern Railroad line, the fill from the railroad spur along the east property line, and the fill from our parking lot could all be contributors.

Additionally, the sampling that was performed for the survey was designed simply to provide an indication of any problem. The samples were composited over a wide area and depth and there was inadequate information to differentiate between a single sample issue and area wide problem.

4. In the report's discussions on the PWB & Electron Tubes processes there appears to be confusion on the use of cyanide. The report incorrectly identifies cyanide used for rinsing product.

All product rinsing in both PWB and Electron Tubes is performed in deionized water rinse tanks (baths). Cyanide is used as a component of one gold plating bath in PWB and in copper, silver, and gold plating baths in Electron Tubes.

PA/VSI RESPONSE Page 4

5. The report states that our retention basin does not discharge to any sewer or surface body. Actually, the retention basin does discharge to a storm sewer as described below.

The retention basin is designed to act as a buffer to the flow of water entering the Rolling Meadows storm sewer located along the east side of the property. Pumps, activated by floats, pump water up and into the storm sewer at a controlled rate. This sewer runs south, then east, and discharges into Salt Creek.

6. Under the Regulatory History section, the report incorrectly interpreted our "bubble" air permit to mean that multiple Northrop facilities are grouped together under one air permit. This permit applies only to the 500/600/600A facility; multiple facilities require independent permits.

The term "bubble" was intended to mean that all air emission sources are grouped under a collection of categories as opposed to individual point sources. In this manner we can accurately account for fugitive as well as point source emissions.

I have attached a copy of the final report which has been highlighted and annotated to correspond to our comments. Minor corrections not incorporated in this response are also noted in the report. This should help expedite your review and corrections to the report.

We expect that conclusions drawn from this report should reflect our true environmental status. We at Northrop Corporation's Electronics Systems Division take pride in our environmental record and accomplishments. Over the past five years we have successfully reduced our hazardous waste generation and disposal by 92%. We are working toward totally eliminating our use of ozone depleting chemicals by mid 1995, and are instituting a pollution prevention program that will reduce the use of volatile organic, toxic, and other hazardous chemicals in the plant. We believe that, under the constraints of our DoD environment, these accomplishments are significant.

If there is any additional information you may need or questions on the above please call me at (708)259-9600 on X5099.

Sincerely,

David A. Gurrie Mgr. Environmental & Safety Compliance



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

HRE-8J

June 29, 1994

Mr. David A. Currie Northrop Corporation Electronic Systems Division 600 Hicks Road Rolling Meadows, IL 60008 RECEIVED WMD RECORD CENTER JUL 07 1994



Re:

Visual Site Inspection Northrop Corporation Electronic Systems Division Rolling Meadows, Illinois ILD 005 128 988

Dear Mr. Currie:

The U.S. Environmental Protection Agency is enclosing a copy of the final Preliminary Assessment/ Visual Site Inspection (PA/VSI) report for the referenced facility. The executive summary and conclusions and recommendations sections have been withheld as Enforcement Confidential.

If you have any questions, please call Francene Harris at (312) 886-2884.

Sincerely yours,

Kevin M. Pierard, Chief

Minnesota/Ohio Technical Enforcement Section

RCRA Enforcement Branch



## TES 9

Technical Enforcement Support at Hazardous Waste Sites Zone III Regions 5,6, and 7





PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



## PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

NORTHROP CORPORATION ELECTRONIC SYSTEMS DIVISION ROLLING MEADOWS, ILLINOIS ILD 005 128 988

## FINAL REPORT

## Prepared for

## U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

Work Assignment No. : R05032

EPA Region : 5

 Site No.
 :
 ILD 005 128 988

 Date Prepared
 :
 April 15, 1994

 Contract No.
 :
 68-W9-0006

 PRC No.
 :
 309-R05032IL76

Prepared by : PRC Environmental Management, Inc.

(Jeff Swano)

Contractor Project Manager : Shin Ahn
Telephone No. : (312) 856-8700

EPA Work Assignment Manager : Kevin Pierard Telephone No. : (312) 886-4448

## CONTENTS

Section	<u>n</u>			Page		
EXEC	UTIVE	SUMMARY		ES-1		
1.0	INTRO	DUCTION		. 1		
2.0	FACIL	ITY DESCRIPT	TION	. 4		
	2.1 2.2 2.3 2.4 2.5 2.6	FACILITY OP WASTE GENE HISTORY OF REGULATOR	CATION DERATIONS DERATION AND MANAGEMENT DOCUMENTED RELEASES Y HISTORY NTAL SETTING	. 4 . 8 . 16 . 17		
		2.6.1 2.6.2 2.6.3 2.6.4	Climate	. 22 . 22		
	2.7	RECEPTORS	**************************************	. 23		
3.0	SOLID	WASTE MANA	AGEMENȚ UNITS	. 25		
4.0	AREAS	OF CONCERN	٠	. 36		
5.0	CONCI	LUSIONS AND	RECOMMENDATIONS	. 37		
REFE	RENCES	S		. 42		
Appen	dices					
Α	VISUA	L SITE INSPE	CTION SUMMARY AND PHOTOGRAPHS			
В	VISUAL SITE INSPECTION FIELD NOTES					
С	SOIL A	AND GROUND	WATER ANALYTICAL RESULTS			
D	SOIL I	BORING LOG				

## **FIGURES**

<u>Figu</u>	<u>ire</u>	Page					
1	FACILITY LOCATION	5					
2	FACILITY LAYOUT	10					
	•						
TABLES							
<u>Tabl</u>	<u>le</u>	Page					
1	SOLID WASTE MANAGEMENT UNITS	9					
2	SOLID WASTES	11					
3	SWMU AND AOC SUMMARY	41					

RELEASEPLY P DATE RIN # INITIALS THE



#### **EXECUTIVE SUMMARY**

PRC Environmental Management, Inc. (PRC), performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from solid waste management units (SWMU) and other areas of concern (AOC) at the Northrop Corporation, Electronic Systems Division (Northrop) facility in Rolling Meadows, Cook County, Illinois. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from SWMUs and AOCs identified.

The Northrop facility employs about 2,700 people and is used as a research and development (R&D) and manufacturing facility to produce electronic countermeasures for the U.S. Department of Defense (DOD). Manufacturing activities include metal finishing, metal plating, and degreasing to produce printed wire board (PWB), electron tubes, and micro-integrated circuits (MIC). Wastes derived from the manufacturing processes consist of waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), waste filters (D011), spent solvents (F001, F002, F005, D001, D006, D007, D018, D035, D039), and miscellaneous wastes such as solvent-contaminated waste oil (F001), solvent-contaminated rags (F005, D001, D035), spent photodeveloper (D008), laboratory packs of expired chemicals (which the facility designates as LABP). Rinsing raw material drums generates empty drums and rinsate. The facility's wastewater treatment plant (WWTP) (SWMU 1), generates nonhazardous filter bags, photoresist solids, copper sheeting, and treated wastewater.

Waste acids, waste caustics, and waste cyanides are collected in Satellite Accumulation Areas (SWMU 8) and stored in segregated areas of Room 6419 (SWMU 3) prior to off-site disposal. Waste filters are placed in 55-gallon drums near the plating baths and transferred to Room 5097 (SWMU 5) when full prior to off-site disposal. Spent solvents were identified in the facility's original Part A permit application. All spent solvents, except for some freon, are collected in Satellite Accumulation Areas (SWMU 8) and stored in Room 5097 (SWMU 5) prior to off-site disposal. Spent freon is treated on site in stills (SWMU 6). The still bottoms are drummed and stored in Room 5097 (SWMU 5). Solvent-contaminated waste oil, solvent-contaminated rags, and spent photodeveloper are collected in Satellite Accumulation Areas (SWMU 8) and stored in Room 5097 (SWMU 5) prior to off-site disposal. Expired chemicals, such as polyeurethane coatings, lubricants, and detergents are

placed into lab packs and stored in Room 5097 (SWMU 5) prior to off-site disposal. Empty raw material drums are rinsed out, the rinsate is treated in the WWTP (SWMU 1), and the drums are stacked in the Empty Drum Storage Area (SWMU 7). Filter bags are accumulated in Room 6409 (SWMU 1) and disposed of off-site. Photoresist solids are drummed in Room 6409 (SWMU 1) and disposed of off-site in a municipal landfill. Copper sheeting is recovered in the WWTP in Room 6409 (SWMU 1) and recycled off site. Treated wastewater is discharged to the Municipal Water Reclamation District (MWRD) sewer system.

The facility began operations as a ham radio manufacturer in 1967; prior to that the property was farmland. In 1980, the facility submitted a Part A permit application indicating that it was a generator of spent solvents (F001, F003, D001, D007), and waste commercial chemicals (P030, P104, U151, U154). In 1983, the facility began producing PWB and, hence, generating waste acids, waste caustics, and waste cyanides. The facility's three buildings currently occupy 940,000 square feet of a 52-acre parcel of land in a light manufacturing area. The facility's current status is that of a large quantity generator of hazardous waste.

The PA/VSI identified the following eight SWMUs and one AOC at the facility:

## Solid Waste Management Units

- 1. Wastewater Treatment Plant
- 2. Room 6407
- 3. Room 6419
- 4. Room 5087
- 5. Room 5097
- 6. Freon Stills
- 7. Empty Drum Storage Area
- 8. Satellite Accumulation Areas

## Area of Concern

1. Former Underground Storage Tank Location

No releases from the facility to the environment have been documented. In July 1988, IEPA conducted an air pollution control inspection at the facility and found the facility did not have an air permit for a laser trimmer of MIC ceramics containing beryllium oxide. The facility was fined





\$10,000 for the violation, but the state did not consider this an air release. No emergency or corrective actions have occurred at the facility.

In 1987, Northrop installed monitoring wells around the perimeter of the facility property to monitor groundwater quality due to concerns regarding industrial activities at neighboring properties. At this time, Northrop collected soil and groundwater samples. Soil sampling results revealed arsenic at 1.92 milligrams per kilogram (mg/kg) on the south boundary; arsenic at 1.83 mg/kg and chromium at 22.8 mg/kg on the east boundary; arsenic at 1.68 mg/kg, chromium at 46.5 mg/kg, and lead at 69.7 mg/kg on the north boundary. Groundwater sampling identified bromoform at 3.6 micrograms per liter from the north boundary. Groundwater is encountered at about 7 to 15 feet below ground surface at the facility. Groundwater flow beneath the facility appears to be to the northeast.


The primary source of drinking water in the vicinity of the facility is Lake Michigan, the intakes of which are located about 30 miles southeast of the facility. Groundwater is used as a municipal and private water supply. The City of Rolling Meadows has one municipal well located 0.25 mile south and downgradient of the facility and draws water from a sandstone aquifer. The Village of Palatine has six municipal wells. These wells are estimated to draw water from a limestone aquifer. Three of these wells are located within a 3-mile radius of the facility in Rolling Meadows: 0.25 mile north, 2 miles northwest, and 2.5 miles southwest of the facility. Groundwater from these wells is used only in emergencies and has not been used in over 10 years. Private drinking water wells within a 3-mile radius of the facility are located about 1 mile south and 1.5 miles southwest of the facility. The nearest residence is located about 0.25 mile north of the facility. The facility's east boundary is fenced. Security guards control the building entrances of the entire facility 24 hours per day because of Northrop's DOD-related activities.

No sensitive environments exist at the facility. The nearest sensitive environment is a 25-acre wetland located about 1.5 miles northwest of the facility. Endangered species listed for Cook County include Peregrine falcon (breeding habitat) and Prairie bush-clover. Prior to 1979, a marshy area was located in the northeast portion of the facility where the parking lot is currently located. According to facility personnel, this marshy area was filled in when the retention pond and parking lots were built in 1979-1980.





PRC recommends applying new epoxy floor covering for the floor in Room 6419 (SWMU 3). PRC recommends inspecting, sampling, and repairing the floor cracks present in Room 5097 (SWMU 5), and to reapply epoxy floor covering. For both Room 6419 (SWMU 3) and Room 5097 (SWMU 5), PRC recommends verifying that the facility's air permits include emissions from the exhaust vents located in those rooms. PRC recommends subsurface soil sampling the Former Underground Storage Tank Location (AOC 1) to determine if a release from the silicone-oil coolant tank occurred.





#### 1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC), received Work Assignment No. R05032 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5.

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has usually exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents. Such areas might include a wood preservative drippage area, a loading or unloading area, or an area where solvent used to wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release of hazardous waste or constituents to the environment has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where a strong possibility exists that such a release might occur in the future.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility
- Obtain information on the operational history of the facility
- Obtain information on releases from any units at the facility
- Identify data gaps and other informational needs to be filled during the VSI

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA
- Identify releases not discovered during the PA
- Provide a specific description of the environmental setting
- Provide information on release pathways and the potential for releases to each medium
- Confirm information obtained during the PA regarding operations, SWMUs, AOCs, and releases

The VSI includes interviewing appropriate facility staff; inspecting the entire facility to identify all SWMUs and AOCs; photographing all visible SWMUs; identifying evidence of releases; making a preliminary selection of potential sampling parameters and locations, if needed; and obtaining additional information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the Northrop Corporation, Electronic Systems Division (Northrop) facility (EPA Identification No. ILD 005 128 988) in Rolling Meadows, Cook

County, Illinois. The PA was completed on May 5, 1993. PRC gathered and reviewed information from the Illinois Environmental Protection Agency (IEPA) and from EPA Region 5 RCRA files. The VSI was conducted on May 21, 1993. It included interviews with facility representatives and a walk-through inspection of the facility. PRC identified eight SWMUs and one AOC at the facility.

The VSI is summarized and 18 inspection photographs are included in Appendix A. Field notes from the VSI are included in Appendix B. Results from 1987 soil and groundwater sampling are included in Appendix C. A boring log, representative of the soil geology is included in Appendix D.

#### 2.0 FACILITY DESCRIPTION

This section describes the facility's location; past and present operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors.

## 2.1 FACILITY LOCATION

The Northrop facility is located at 600 Hicks Road in Rolling Meadows, Cook County, Illinois. Figure 1 shows the location of the facility in relation to the surrounding topographic features (latitude 42° 05' 50" N and longitude 88° 02' 10" W). The three manufacturing buildings cover about 940,000 square feet of a 52-acre property in a light manufacturing area.


The facility is bordered on the north by trucking company and the village of Palatine, on the east by a chemical manufacturing company, on the south by a nail manufacturing company, and on the west by Hicks Road and the village of Palatine. A baseball field is located northeast of the facility.

## 2.2 FACILITY OPERATIONS

The Northrop facility is currently used as a research and development (R&D) and manufacturing facility to produce electronic countermeasures for the U.S. Department of Defense (DOD) and employs about 2,700 people. The components of these products are manufactured at the facility and include printed wire boards (PWB), electron tubes, and micro-integrated circuits (MIC).

Raw materials for production include copper sheeting, photoresist strips, lubricants, epoxies, polyurethane sealants, silicone adhesives, and solvents. Raw material chemicals are purchased in 5-and 55-gallon quantities and stored indoors.

PWB production began at the Northrop facility in 1983. To produce a PWB layer, a plastic circuit card is covered with copper sheeting. A photoresist strip, which is made of acrylic, is applied to the copper sheeting. An image of electronic circuitry is photographed onto the photoresist strip and developed at the facility like a photograph. The circuit card is then placed in a cupric chloride acid



bath to etch off copper. After the acid bath, the PWB is rinsed in a caustic bath. Finally, the photoresist strip is removed in an acid bath leaving the electronic circuitry on the PWB. To permit solder points to be adhered to the PWB later in the production process, a photoresist strip is again applied to the PWB. The PWB is placed in a lead-tin plating bath and rinsed in a cyanide bath. The photoresist strip is removed in an acid bath and the lead-tin points remain. This entire process may be repeated in order to produce several layers of circuitry on one PWB. The number of processes and baths a PWB goes through varies depending on the PWB specifications.

To adhere solder points to a completed PWB, the PWB is cleaned with freon. Solder points are attached to the lead-tin points. Solder flux is removed from the PWB with freon. The PWB is cleaned with freon once more before a coat of polyeurethane sealant is applied to it.

Several PWBs can be laminated together to produce a PWB panel. Some PWB panels are drilled through in order to create electronic connections between the layers. The PWB panel is placed in a copper plating bath to fill the holes with a copper conduit. Panels are cleaned in a cyanide bath. Some PWBs require a protective nickel coating around the board edges to protect the metal. The PWB is placed in a nickel plating bath and rinsed in a cyanide bath. Other metal plating baths, such as gold and silver, are used on an as-needed basis. Most metal plating baths are replenished with additional metals and are not disposed of. Acid baths, caustic baths, and cyanide baths are either treated or disposed of.

Electron tube production began at the facility in the early 1970s. Electron tubes are made up of a series of intricately assembled, small metal components that resemble a stack of washers. The metal components are either machined in-house or purchased from other companies. Metal components are plated with nickel, copper, silver, or gold in plating baths in order to allow for a proper braze. After metal plating, the tubes are rinsed in a cyanide bath. To form a tube, metal components are usually brazed together but they can also be gas welded. Once a tube is formed it is evacuated to remove the air. A tube is cleaned frequently with freon or 1,1,1 trichloroethane (1,1,1 TCA). The tube is housed in a tin casing and wiring leads are soldered onto the casing. Finally, a silicone rubber is applied to seal the entire casing and wires. The finished tube is stored and sold as spare parts for radar jamming in older defense-related products.

MIC manufacturing consists of a ceramic substrate onto which various resistive and conductive components are added. Typically, silver and gold inks are printed on the ceramic substrate using a silk screening process. The MIC is degreased using freon. In order to fine-tune the electronic tolerances of the metal inks, a laser is used to remove ink from the ceramic substrate. The MIC is degreased again and tested. Next, transistors and resistors are manually and mechanically wire bonded to the MIC. The MIC is degreased again. Smaller components are attached to the MIC using adhesives. The MIC is degreased again, placed in a tin casing, and sealed. Sometimes a MIC will require etching in a nitric acid bath. Sometimes toluene is used as a degreaser.

These manufacturing activities generate waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), waste filters (D011), spent solvents (F001, F002, F005, D001, D006, D007, D018, D035, D039), and miscellaneous wastes such as solvent-contaminated waste oil (F001), solvent-contaminated rags (F005, D001, D035), spent photodeveloper (D008), laboratory packs of expired chemicals (LABP), empty drums, and raw material drum rinsate. The facility's wastewater treatment plant (WWTP), located in Room 6409 (SWMU 1) generates nonhazardous filter bags, nonhazardous photoresist solids, copper sheeting, and treated wastewater.

Hazardous wastes generated throughout the facility are collected in Satellite Accumulation Areas (SAA) (SWMU 8) and then transferred to accumulation areas (SWMUs 3 and 5) prior to off-site disposal. Wastewaters generated on site are drummed at their source and transferred to the WWTP (SWMU 1) where they are pretreated prior to discharge to the municipal sewer system. Wastewaters that cannot be treated on site are drummed and stored in SWMU 3 prior to off-site disposal. Most of the facility's spent freon is reclaimed on-site is a still (SWMU 6).

Prior to 1967, the property was farmland. The facility began operations in 1967 as a HAM radio manufacturer in a 208,000-square-foot building owned and operated by Hellicrafters, Inc. (Hellicrafters). Shortly thereafter, Northrop Corporation took over Hellicrafters, and the facility began DOD-related electronics manufacturing. Northrop has either constructed or expanded its manufacturing buildings in 1977, 1981, 1984, 1987, and 1993. The facility currently consists of three manufacturing buildings covering 940,000 square feet on a 52-acre parcel of land.

Prior to 1979, a marshy area was located in the northeast portion of the facility where a parking lot is currently located. This area was filled in 1979 to 1980, when the parking lot and retention pond were built (PRC 1994).

Solid wastes generated from facility operations and the SWMUs where they are managed are discussed in detail in Section 2.3.

## 2.3 WASTE GENERATION AND MANAGEMENT

This section describes waste generation and management at the Northrop facility. The facility's SWMUs are identified in Table 1. The facility layout, including SWMUs and AOCs, is shown in Figure 2. The facility's waste streams are summarized in Table 2.

The manufacturing operations that generate wastes include developing, metal finishing, metal plating, and degreasing. These operations generate waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), waste filters (D011) from cyanide baths, and spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039). Miscellaneous wastes generated throughout the facility include solvent-contaminated waste oil (F001) from machining pumps, solvent-contaminated rags (F005, D001, D035), spent photodeveloper (D008), lab packs of expired chemicals (which the facility designates as LABP) of expired chemicals, and nonhazardous empty drums. Rinsing out empty raw material drums generates raw material drum rinsate. The facility's WWTP (SWMU 1) treats spent acid baths, spent rinsing baths, and raw material drum rinsate, and generates nonhazardous filter bags, photoresist solids, copper sheeting, and treated wastewater. According to facility representatives, all wastes have been taken off-site for disposal since 1975. No records of on-site disposal of chemicals at the facility exist (PRC 1994). The waste streams produced by the manufacturing operations and the facility's waste management practices are discussed below.

Metal finishing operations occur during PWB and MIC production and generate some waste acids (D002, D007, D008) that cannot be treated in the WWTP (SWMU 1). Waste acids generated from finishing baths are either accumulated in 5-gallon containers or 55-gallon drums located in SAAs (SWMU 8). Once a container is full, it is moved to Room 6419 (SWMU 3); contents of 5-gallon

TABLE 1
SOLID WASTE MANAGEMENT UNITS

SWMU Number	SWMU Name	RCRA Hazardous Waste  Management Unit <sup>a</sup>	Status
1	Wastewater Treatment Plant	Yes	Active; RCRA-closed in 1987
2	Room 6407	Yes	Inactive; RCRA-closed in 1987
3	Room 6419	No	Active; less than 90-day storage
4	Room 5087	Yes	Inactive; RCRA-closed in 1987
5	Room 5097	Yes	Active; less than 90-day storage; RCRA-closed in 1987
6	Freon Stills	No	Active
7	Empty Drum Storage Area	No	Active
8	Satellite Accumulation Areas	No	Active

Note:

A RCRA hazardous waste management unit is one that currently requires or formerly required submittal of a RCRA Part A or Part B permit application.

TABLE 2 **SOLID WASTES** 

Waste/EPA Waste Code <sup>a</sup>	Source	Solid Waste Management Unit <sup>b</sup>	
Waste acids/D002, D007, D008	PWB and MIC production	1, 2, 3, 4, 8	
Waste caustics/D002, D008	PWB production	1, 2, 3, 4, 8	
Waste cyanides/F007, D002, D011	PWB and electron tube production	1, 2, 3, 4, 8	
Waste filters/D011	PWB and electron tube production	3, 8	
Spent solvents/F001, F002, F003, F005, D001, D006, D007, D018, D035, D039	PWB and MIC production	1, 2, 4, 5, 6, 8	
Solvent-contaminated waste oil/F001	Hot oil solder reflow machining pumps	5, 8	
Solvent-contaminated rags/F005, D001, D035	Manufacturing; R&D	5, 9	
Spent photodeveloper/D008	PWB manufacturing	5, 9	
Raw material drum rinsate/D002, D007, D008	Drum cleaning	1	
Lab packs/LABP <sup>c</sup>	Expired chemicals	5	
Empty drums/NA	Manufacturing	7	
Filter bags/NA	WWTP	1, 3	
Photoresist solids/NA	WWTP	1, 3	
Copper Sheeting/NA	WWTP	None	
Treated wastewater/NA	WWTP	1	

## Notes:

Not applicable (NA) designates nonhazardous waste. "None" indicates that the waste stream is not managed on site. This is the facility's waste code designation. ь

С

containers are transferred into a 55-gallon drum. Full drums in Room 6419 (SWMU 3) are prepared for off-site disposal. Since 1989, Clean Harbors of Chicago, Inc. (Clean Harbors) has transported the drums in a trailer truck to either its Chicago, Illinois or Braintree, Massachusetts facilities for wastewater treatment. The facility generated about 34,400 gallons of waste acids (D002, D007, D008) in 1992. Between 1986 and 1988, some waste acids (D002, D007, D008) were treated by Chem Clear, Inc. (CCI), of Chicago, Illinois. Between 1983 and 1990 some waste acids (D002, D007, D008) were also treated by Envirite Corporation (Envirite) in Harvey, Illinois. Waste acids that can be treated in the WWTP (SWMU 1) are placed in 55-gallon drums at the source of generation, stored next to the WWTP (SWMU 1), and treated on-site in batches.

Metal finishing operations also generate some waste caustics (D002, D008), used as rinses after acid baths, that cannot be treated in the WWTP. Waste caustics generated from rinsing baths are either accumulated in 5-gallon containers or 55-gallon drums located in SAAs (SWMU 8). Once a container is full, it is moved to Room 6419 (SWMU 3); contents of 5-gallon containers are then transferred into a 55-gallon drum. Full drums in Room 6419 (SWMU 3) are prepared for off-site disposal. Since 1990, Clean Harbors has transported the drums of waste in a trailer truck to its Chicago, Illinois facility for wastewater treatment., Since 1983, C. P. Inorganics, Inc. (CPI), has transported drums of waste in a trailer truck to its Joliet, Illinois facility for reclaiming. In 1992, the facility generated about 45,700 gallons of waste caustics (D002, D008), of which about 330 gallons were treated off-site by Clean Harbors and about 3,400 gallons were reclaimed off-site by CPI. Between 1983 and 1990, Envirite transported the wastes to its treatment facility. Between 1983 and 1989, some wastes were also treated by CCI. Waste caustics that can be treated in the WWTP (SWMU 1) are placed in 55-gallon drums at the source of generation, moved to be stored next to the WWTP (SWMU 1), and treated on-site in batches in the WWTP (SWMU 1).

Metal plating operations occur during PWB and electron tube production and generate waste cyanides (F007, D002, D011), none of which can be treated in the WWTP (SWMU 1). Waste cyanides generated from rinsing baths are either accumulated in 5-gallon containers or 55-gallon drums located in SAAs (SWMU 8). Once a container is full, it is moved to Room 6419 (SWMU 3); contents of 5-gallon containers are then transferred into a 55-gallon drum. Full drums in Room 6419 (SWMU 3) are prepared for off-site disposal. Since 1987, Cyanokem, Inc., has transported the drums of wastes in a trailer truck to its Detroit, Michigan facility for treatment. The facility generated about 30

gallons of waste cyanides in 1992. Once every 3 to 5 years, the facility generates about 55 gallons of potassium gold cyanide (F007), which is transported off site by SET Environmental Services, Inc., to the Handy and Harman, Inc. facility in Villa Park, Illinois for reclamation. In 1992, the facility generated about 15 gallons of this waste cyanide. Between 1983 and 1986, waste cyanide was treated by Nelson Industrial Services, Inc., in Detroit, Michigan.

Between 1983 and 1987, waste acids (D002, D007, D008), waste caustics (D002, D008), and waste cyanides (F007, D002, D011) were stored in Room 6409, where the WWTP (SWMU 1) is currently located. In addition, these wastes were stored in Room 6407 (SWMU 2) and Room 5087 (SWMU 4). No information is available on the specific wastes or waste quantities stored in these rooms during this time period.

Metal plating operations also generate waste filters (D011) used in silver cyanide plating baths for PWB and electron tube manufacturing. The facility began using filters in 1990. The filters are accumulated in 5-gallon buckets located in SAAs (SWMU 8) and transferred to 55-gallon drums in Room 6419 (SWMU 3). Since 1991, Environmental Systems Company, Inc. (ENSCO), has transported the drums of waste in a trailer truck to its incinerator in El Dorado, Arkansas. In 1992, the facility generated 193 pounds of waste filters.

Degreasing operations use freon, 1,1,1 TCE, and toluene. As a result, a variety of spent solvents (F001, F002, F003, D001, D006, D007, D018, D035, D039) are generated. All spent solvents are either accumulated in 5-gallon containers or 55-gallon drums located in SAAs (SWMU 8). Once a container is full, it is moved to Room 5097 (SWMU 5); contents of 5-gallon containers are then transferred into a 55-gallon drum. About 90 percent of spent freon (F001) regenerated in the Freon Stills (SWMU 6). Still bottoms from the Freon Stills (SWMU 6) are placed in 5-gallon buckets, transferred into 55-gallon drums, and stored less than 90 days in Room 5097 (SWMU 5). The 10 percent of spent freon that is not regenerated is accumulated in 55-gallon drums in Room 5097 (SWMU 5).

Full drums of all solvent wastes are prepared for off-site disposal. Since 1987, Safety-Kleen Corporation (Safety-Kleen) has transported the drums of all spent solvent wastes in a trailer truck to its fuel blending facility in Dolton, Illinois. Thereafter, the blended wastes are transported to cement

kilns to be burned as fuel. In 1992, the facility generated about 3,670 gallons of spent solvents. Between 1980 and 1989, LWD, Inc. transported some of the wastes to their incinerator in Calvert City, Kentucky. Between 1980 and 1988, BDT, Inc., transported some of the wastes to its incinerator in Clarence, New York. In 1986, McKesson Envirosystems, Inc. transported some of the wastes to its reclamation facility in Dolton, Illinois. No information is available on disposal practices prior to 1980.

Between 1983 and 1987, spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039) were stored in Room 6407 (SWMU 2), Room 5087 (SWMU 4), and Room 6409, where the WWTP (SWMU 1) is currently located. No information is available on the specific wastes or waste quantities stored in these rooms during this time period.

In 1989, the facility generated waste isopropanol (F003) from degreasing operations. This waste was either accumulated in 5-gallon containers or 55-gallon drums located in SAAs (SWMU 8). Once a container was full, it was moved to Room 5097 (SWMU 5); contents of 5-gallon containers were transferred into a 55-gallon drum. Full drums were prepared for off-site disposal. LWD, Inc., transported the drums to its Calvert City, Kentucky facility for incineration. In 1989, the facility generated about 385 gallons of waste isopropanol.

Solvent-contaminated waste oil (F001) is generated from hot oil solder reflow machining pumps. Solvent-contaminated waste oil is accumulated in 5-gallon buckets located in SAAs (SWMU 8). Once the container is full, it is moved to Room 5097 (SWMU 5) and its contents transferred to a 55-gallon drum. Full drums of waste are prepared for off-site disposal. Since 1989, Safety-Kleen has transported the drums of waste in a trailer truck to its fuel blending facility in Dolton, Illinois. Thereafter, the blended wastes are transported to cement kilns to be burned as fuel. In 1992, the facility generated about 1,045 gallons of solvent-contaminated waste oil.

Solvent-contaminated rags (F005, D001, D035) are generated throughout the manufacturing areas and R&D laboratories of the facility. Rags are placed in 5-gallon buckets with self-closing-lid SAAs (SWMU 8) and emptied nightly. The rags are stored in 55-gallon drums in Room 5097 (SWMU 5). Rineco transports drums of rags to its fuel blending facility in Benton, Arkansas where they are shredded. In 1992, the facility generated about 1,680 pounds of solvent-contaminated rags. From

1989 to 1993, ENSCO transported the rags to its El Dorado, Arkansas facility for incineration. Prior to 1989, LWD, Inc., transported the rags to its Calvert City, Kentucky facility for incineration.

Developing the photoresist strips used in PWB production, generates spent photodeveloper (D008). This waste is placed in 5-gallon buckets in SAAs (SWMU 8). Once the container is full, it is moved to Room 5097 (SWMU 5) and its contents transferred into a 55-gallon drum. Full drums of waste are prepared for off-site disposal. Between 1983 and 1989, CCI transported the drums of waste in a trailer truck to its wastewater treatment facility in Chicago, Illinois. In 1989 CCI became Clean Harbors and has transported the drums of waste in a trailer truck to its wastewater treatment facility in Chicago, Illinois. In 1992, the facility generated about 330 gallons of spent photodeveloper.

Occasionally, raw material chemicals expire and require disposal. DOD does not allow the use of expired materials in the products it buys. Northrop, however, re-evaluates chemicals to extend their shelf-life and attempts to find other uses for them because they are not substandard. These chemicals include polyeurethane coatings, lubricants, and detergents and are stored in Room 5097 (SWMU 5). If no alternative uses for expired chemicals can be identified, the facility prepares a labpack for off-site disposal. The facility designates the waste code for this waste as LABP. Since the late 1980s, Clean Harbors has transported lab packs in a trailer truck to its treatment facility in Chicago, Illinois. In 1992, the facility disposed of about 630 gallons of expired chemicals. Between 1982 and 1986, U.S. Ecology transported the wastes to its incinerator in Beaty, Nevada.

Empty drums from raw material chemicals are rinsed out using a continuous flow washing unit located near the plating bath lines. This generates raw material drum rinsate, which is treated in the WWTP (SWMU 1). Since 1987, the empty drums have been stacked in the Empty Drum Storage Area (SWMU 7) and have been picked up by either chemical distributors or chemical manufacturers to be reused. Prior to 1987, few drummed chemicals were used at the facility. At that time, empty drums were stored near the areas where the chemicals were being used. Off-site disposal then was the same as current operations.

The facility's WWTP (SWMU 1) became operational in 1990 and is maintained in Room 6409. The WWTP (SWMU 1) receives spent plating baths and rinse waters generated from metal plating operations and treats them in batches. Drums of wastes for the next batch are stored in Room 6409

near the WWTP (SWMU 1). The WWTP (SWMU 1) generates nonhazardous filter bags, photoresist solids, copper sheeting, and treated wastewater. Nonhazardous filter bags are air dried, placed in a 55-gallon SAA (SWMU 8), transferred to Room 6419 (SWMU 3) when full, and disposed of off-site in a landfill by Browning Ferris Industries (BFI). Nonhazardous photoresist solids are pressed to remove water and placed in a 2-cubic-yard hopper. The photoresist solids are then shoveled into 55-gallon drums and stored in Room 6419 (SWMU 3). BFI transports the photoresist solids off site for disposal in a landfill. Nonhazardous copper sheeting is generated from the a recovery tank of the WWTP (SWMU 1) equipped with an electrolytic cell. The copper sheeting is pulled off the cell and stacked nearby and eventually sold to off-site metals recyclers. Nonhazardous treated wastewater is discharged to the Metropolitan Water Reclamation District (MWRD) sewer system. MWRD monitors this effluent stream daily.

The PWB production process that generates spent bath and rinse waters began in 1983. Between 1983 and 1990, spent baths and rinse waters were bulked in 55-gallon drums and stored in Room 6409 (SWMU 1). Once per week, either Envirite or CCI of Chicago, Illinois pumped out the drums into a tanker truck and transported the wastes to its off-site treatment facilities.

## 2.4 HISTORY OF DOCUMENTED RELEASES

No releases from the facility to the environment have been documented. In 1987, Northrop installed monitoring wells around the northern, eastern, and southern perimeters of the facility property to monitor groundwater quality. This is because Northrop had concerns of industrial activities at neighboring properties; the facility is bordered on the east by a chemical manufacturer. At this time, Northrop collected soil and groundwater samples. Soil sampling results identified arsenic at 1.92 milligrams per kilogram (mg/kg) on the south boundary; arsenic at 1.83 mg/kg and chromium at 22.8 mg/kg on the east boundary; and arsenic at 1.68 mg/kg, chromium at 46.5 mg/kg, and lead at 69.7 mg/kg on the north boundary. Groundwater sampling identified bromoform at 3.6 micrograms per liter on the north boundary (Warzyn 1987). This report did not indicate the source of contamination. Northrop's consultant reported these results were consistent with results expected in an industrial area adjacent to a highway (PRC 1994). A copy of these results are included in Appendix C.

No further soil or groundwater sampling has been conducted at the Northrop facility. During the VSI, PRC did not observe any evidence of releases.

## 2.5 REGULATORY HISTORY

Northrop submitted a Notification of Hazardous Waste Activity form to EPA on August 15, 1980 indicating the facility both generated and treated, stored, or disposed of hazardous wastes (Northrop 1980a). Northrop submitted a RCRA Part A permit application on November 18, 1980 (Northrop 1980b). The permit application was for a 5,811-gallon container storage area in Room 5097 (SWMU 5), process code S01. Room 5097 (SWMU 5) stored waste solvents (F001, F002, F003, D001, D007). The application did not include electroplating wastes because they were not generated at that time. Information from Baxter and Woodman, Inc. (BAW), indicates Room 5097 (SWMU 5) was used only to store waste solvents (B&W 1986). This permit application erroneously indicated wastes being disposed of in an on-site landfill with an incorrect process code of D80. Waste code F006 was also listed erroneously because the facility did not treat wastewater at that time.

In December 1982, Northrop submitted a revised Part A permit application to increase its hazardous waste container storage capacity to 7,600 gallons (Northrop 1982b). In 1983, the facility began producing PWBs generating waste acids, caustics, and cyanides. In March 1984, Northrop submitted a revised Part A permit application to indicate the facility was increasing its hazardous waste storage capacity to 14,000 gallons and planned to treat about 20 gallons per day of hazardous wastes in Room 6409 (SWMU 1) (Northrop 1984a).

In 1984, Northrop submitted a supplemental waste stream permit application to accept waste from another Northrop plant in Elk Grove Village, Illinois. IEPA denied the application because the facility was not permitted to accept waste for storage (IEPA 1985a). IEPA discussed with Northrop the status of both facilities. IEPA determined that the Elk Grove Village facility could ship no more than 220 pounds of solvent wastes per month to the Rolling Meadows facility without permits or manifests (IEPA 1985b).

In December 1985, Northrop submitted a special waste stream application to store chromic plating bath waste from the Elk Grove Village plant and from a Northrop plant in Palatine, Illinois. IEPA

denied the application because Northrop had not been issued a development or operating permit for waste storage, waste treatment, or waste disposal operations. In addition, the waste analyses submitted with the application did not adequately characterize the wastes (IEPA 1986a). Northrop corrected these deficiencies and was allowed to receive and store wastes generated from other Northrop facilities (IEPA 1986c). A December 1986 compliance inspection conducted by IEPA determined that the wastes were properly manifested and transported from the other facilities, properly stored with wastes generated at the Northrop facility, and properly remanifested and transported for off-site disposal.

Northrop submitted a closure plan for its hazardous waste storage areas in April 1984 (Northrop 1984b). In December 1986, Northrop notified IEPA that the company had retained Baxter and Woodman, Inc. (B&W), to prepare a closure plan and oversee the implementation of the closure plan for the facility's hazardous waste storage areas (B&W 1986). Room 6409 (SWMU 1), Room 6407 (SWMU 2), Room 5087 (SWMU 4), and Room 5097 (SWMU 5) were the units to be closed. In January 1987, Northrop submitted a revised Part A permit application to indicate that Room 6409 (SWMU 1), Room 6407 (SWMU 2), and Room 5087 (SWMU 4) were being used to store volatile wastes (F001, F002, F003, D001, D007) and electroplating wastes (F007) (B&W 1986; Northrop 1987a). This revision did not indicate any treatment process codes, and it returned the waste storage capacity to 5,811 gallons (Northrop 1987a). IEPA received the closure plan on January 8, 1987 and approved it on March 9, 1987 (IEPA 1987b).

Closure included removing wastes and cleaning the four rooms, collecting samples, and disposing of all wastes. The rooms were emptied and cleaned prior to sampling activities. In March and April 1987, wipe samples for cyanide and metals were collected in Room 6409 (SWMU 1), Room 6407 (SWMU 2), Room 5087 (SWMU 4), and Room 5907 (SWMU 5) (B&W 1986). Between April and June 1987, about 60,000 pounds of waste were disposed of off site (B&W 1986). On July 14, 1987, B&W prepared a decontamination report, closure report, and closure certification for Northrop to submit to IEPA (B&W, 1987). On July 20, 1987, Northrop sent IEPA a Part A permit withdrawal request letter (Northrop 1987c).

In August 1987, IEPA determined that the closure of this facility was not conducted in accordance with the approved closure plan. Closure was not approved because the facility did not provide the

location of background samples; closure photographs revealed a significant floor crack in Room 5087 (SWMU 4), floor seams in Room 6407 (SWMU 2) and Room 5097 (SWMU 5), and drum stains on the floor in Room 5097 (SWMU 5). In addition, analyses from wipe samples collected in Room 6409 (SWMU 1), Room 6407 (SWMU 2), Room 5087 (SWMU 4), Room 5097 (SWMU 5) identified elevated levels of chromium, mercury, silver, and nickel (IEPA 1987c).

In October 1987, Northrop responded to the IEPA closure denial. Northrop provided a map of the locations of background samples. Northrop took two cores from the floor crack in Room 5097 (SWMU 5) and provided photographs of the cores. The photographs allegedly showed that the crack did not penetrate the concrete completely. Northrop considered the drum stains on the floor in Room 5097 (SWMU 5) to have been caused by rust. Northrop argued that because background samples were collected from very clean areas, the target goals for a remedial action should be adjusted to the concentrations found in the sampled areas, thereby allowing closure without remedial action (Northrop 1987d).

On November 2, 1987, IEPA inspected the Northrop facility and determined that closure had been completed in accordance with the approved closure plan. On December 21, 1987, IEPA notified Northrop that the agency approved of the closure and had withdrawn the Part A permit application to reflect the facility's status change. In addition, the agency returned Northrop's surety bond (IEPA 1987d).

The Northrop facility's current regulatory status is that of large-quantity generator of hazardous waste. The facility stores hazardous wastes for less than 90 days.

On March 23, 1982, IEPA conducted a RCRA compliance inspection at the Northrop facility. The inspection found numerous paperwork deficiencies including a lack of operating records and a contingency plan at the facility (IEPA 1982). IEPA notified Northrop on May 7, 1982, of the facility's deficiencies, and Northrop responded to the notification on May 24 (Northrop 1982a).

On December 19, 1986, IEPA conducted a RCRA compliance inspection at the Northrop facility. The inspection found that the facility did not have a waste analysis plan (IEPA 1986c; IEPA 1987a).

IEPA notified Northrop of the violations on February 6, 1987. Northrop responded to the notification on February 16, 1987 (Northrop 1987b).

On March 23, 1989, IEPA notified Northrop that the facility had not submitted a 1988 annual report (IEPA 1989). Northrop responded to the violation notice by submitting a 1988 annual report. Northrop considered that since the RCRA storage units were closed that annual reports were no longer required (Northrop 1989).

On July 7, 1988, IEPA conducted an air pollution control inspection at the Northrop facility. The inspection found that the facility did not have an air permit for a laser trimmer of MIC ceramics containing beryllium oxide. On July 21, 1988, IEPA notified Northrop of the violation and instructed the facility to obtain an air permit (IEPA 1988). In December 1988, Northrop submitted an air permit for the laser trimmer. IEPA rejected the permit due to insufficient sample analyses and gave Northrop 60 days to reapply (PRC 1993d). Northrop failed to respond within the allotted time; as a result, IEPA found Northrop in violation of Illinois administrative codes. On February 9, 1990, a hearing was held and Northrop agreed to pay a \$10,000 civil penalty for the violations (Illinois Pollution Control Board 1990). Northrop filed an air permit application for the operations in April 1990, and on April 20, 1990, IEPA issued an air permit (IEPA 1990b). The facility is required to have operating air permits and currently has eight operating air permits. These permits are bubbled to cover other Northrop facilities in Palatine and Elk Grove Village, Illinois. The facility has no history of odor complaints from area residents.

In January 1985, IEPA issued Northrop a water pollution control (WPC) permit to operate water pollution control facilities (IEPA 1985c). This permit covered wastewaters from several production lines, cooling water, and sanitary waste. In February 1986, IEPA issued Northrop a WPC permit to operate an pretreatment recovery unit to remove metals with discharges to MWRD (IEPA 1986b). On January 30, 1990, IEPA issued Northrop a WPC permit to construct the facility's WWTP (IEPA 1990a).

All facility water discharges are to the MWRD which have been permitted and are monitored daily. The facility has no history of water discharge permit violations. Storm water runoff from the facility parking lots and roofs is channelled to a 2.5 acre-retention basin located near the northeast side of the

facility property. The retention basin does not have a discharge to any other sewer or surface water body. All other facility storm water runoff is directed into storm sewers that flow into Salt Creek.

The facility had one underground storage tank (UST) located at the Former Underground Storage Tank Location (AOC 1) on the southwest side of the facility. This UST contained silicone oil that was used as a coolant. It was excavated in 1977; however, no paperwork is available on whether the removal was approved, if the tank was leak-tested, or if any contamination remains.

#### 2.6 ENVIRONMENTAL SETTING

This section describes the climate; flood plain and surface water; geology and soils; and groundwater in the vicinity of the facility.

## **2.6.1** Climate

The climate in Cook County is cold and snowy in winter and warm in summer. According to information from the U.S. Department of Agriculture (USDA), the average daily temperature in winter is 25 °F and in summer is 71 °F. The lowest average daily temperature is 13 °F in January. The highest average daily temperature is 82 °F in July (USDA 1979).

The average total annual precipitation for the county is 33 inches. Average seasonal snowfall is 39 inches (USDA 1979). The U.S. Department of Commerce (USDOC) lists mean annual lake evaporation for the area at about 30 inches (USDOC, 1968). The 1-year, 24-hour maximum rainfall is about 2.25 inches (USDOC 1963).

The average relative humidity in midafternoon in spring is less than 15 percent; during the rest of the year it is about 61 percent. Humidity is higher at night, and the average at dawn is about 80 percent (USDA 1979).

## 2.6.2 Flood Plain and Surface Water

Information from the Federal Emergency Management Agency (FEMA) indicates the Northrop facility is not located in a flood plain, but the area has been designated an area of minimal flooding (FEMA 1985). According to facility representatives, the water table is high in the area and the parking lots flood easily (PRC 1993a). The nearest surface water body is Salt Creek, located about 0.75 mile west of the facility. This creek is used for recreation and storm water runoff (PRC 1993b). Salt Creek flows south for about 36 miles to the Des Plaines River.

Storm water runoff from the facility parking lots and roofs flows into the retention basin located on the northeast side of the facility. Aboveground runoff from the Empty Drum Storage Area (SWMU 7) flows into the retention basin, which does not discharge to a sewer or surface water body (IT Corporation 1992). All other storm water runoff is directed to storm water sewers that flow into Salt Creek. Treated wastewater and sanitary water discharges to MWRD, which monitors the effluent daily.

## 2.6.3 Geology and Soils

Soils on the area of the facility consist of Urban land areas mixed with the Orthents Complex soils that have been altered. The Urban land aspects of the landscape have been covered by buildings and parking lots. The Orthents Complex areas consist of clayey, fine-textured soils. The soils formerly had a surface layer of silt loam, silty clay loam, or silty clay and a subsoil of silty clay or clay. The underlying material was calcareous silty clay loam. This unit is not assigned a suitability subclass. Low spots of Orthents soils collect water and dry slowly. Permeability is variable because the soil material is altered and has been compacted by construction equipment. Runoff is medium to very rapid, depending on slope and vegetation cover (USDA 1979).

Underlying the soils in the vicinity of the facility are thick, Wisconsinan age deposits of glacial till (Bogner 1976). The material primarily consists of clay and gravel from glacial outwash (Bogner 1976). Boring logs from monitoring wells installed on site indicate a predominance of stiff, silty clay (Warzyn Engineering, Inc. 1987). A sample boring log is included in Appendix D. The total

thickness of the unconsolidated units varies between 80 and 150 feet (Illinois Department of Public Health 1967).

Silurian age bedrock underlying the glacial deposits consists of Niagaran Dolomite. Ordovician age bedrock underlying the glacial deposits is composed of Maquoketa Shale (Bogner 1976).

#### 2.6.4 Groundwater

Groundwater in the vicinity of the facility is encountered in shallow, perched aquifers; sand and gravel deposits in the glacial till; and deeper bedrock formations. Shallow aquifers exist between 4 and 30 feet below ground surface (bgs), at times daylighting in depressions. Sand and gravel deposits within the glacial till are encountered between 30 and 75 feet bgs. Dolomite and shale bedrock aquifers are located between 150 and 750 feet bgs; sandstone bedrock aquifers are located over 750 feet bgs (Illinois Department of Public Health, 1967; Bogner 1976).

Groundwater flow in shallow aquifers beneath the facility is unknown. Groundwater is encountered about 7 to 18 feet bgs. Groundwater flow appears to be northeast. Groundwater flow of other aquifers in the vicinity of the facility is unknown but most likely follows the topography of the area toward the south and east (USGS 1961; Bogner 1976).

#### 2.7 RECEPTORS

The Northrop facility is located at 600 Hicks Road in Rolling Meadows, Cook County, Illinois. The facility property occupies 52 acres in a light manufacturing area. Rolling Meadows has a population of about 20,000, and Palatine has a population of about 30,000. The facility is bordered on the north by light manufacturing companies and the village of Palatine, on the east and south by light manufacturing companies, and on the west by Hicks Road and the village of Palatine. A baseball field is located near the facility's northeast corner. The nearest school is located about 0.75 mile northwest of the facility. The nearest residence is located about 0.25 mile north of the facility. The facility's east boundary is fenced. Security guards control the entrances to the entire facility 24 hours per day because of Northrop's DOD-related activities.

The nearest surface water body, Salt Creek, is located about 0.75 mile west of the facility and is used for storm water runoff and recreational purposes (PRC 1993b). Other surface water bodies in the area include small marshy areas in low-lying areas, ephemeral streams, and small unnamed lakes (USGS 1961). These surface water bodies are not used for drinking water purposes. The primary source of drinking water in the vicinity of the site is Lake Michigan. The intakes on Lake Michigan are located about 30 miles southeast of the facility (PRC 1993b; PRC 1993c).

Groundwater is used as a municipal and private water supply. The City of Rolling Meadows has one municipal well located 0.25 mile south and downgradient of the facility. This well is about 1,600 feet deep and draws water from a sandstone aquifer. About 60,000 gallons per month of this groundwater is blended with the Lake Michigan water prior to distribution (PRC 1993c). The Village of Palatine has six municipal wells. These wells are estimated to be about 170 feet deep and draw water from a limestone aquifer. Three of these wells are located within a 3-mile radius of the site: 0.25 mile north, 2 miles northwest, and 2.5 miles southwest of the facility. Groundwater from these wells is blended with Lake Michigan water prior to distribution only in emergencies and has not been used in over 10 years (PRC 1993b). Private drinking water wells within a 3-mile radius of the site are located about 1 mile south and 1.5 miles southwest of the facility in Rolling Meadows (PRC 1993b; PRC 1993c).

No sensitive environments exist at the facility. The nearest sensitive environment is a 25-acre wetland located about 1.5 miles northwest of the facility (USGS 1961). Endangered species listed by the U.S. Department of the Interior (DOI) for Cook County include Peregrine falcon (breeding habitat) and Prairie bush-clover (U.S. DOI 1989). Prior to 1979, a marshy area was encountered in the northeast corner of the facility where the parking lot is currently located. The marshy area was filled in when the retention pond was built in 1979-1980 (PRC 1994).

#### 3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the eight SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and PRC's observations. Figure 2 shows the SWMU locations.

## SWMU 1

## Wastewater Treatment Plant

Unit Description:

This unit is maintained indoors on the east central side of 600 Building. This unit currently covers about 2,000 square feet. Spent acid and caustic baths are treated in batches, some of which are staged in 55-gallon drums on the north side of the room. This unit also treats raw material drum rinsate. Prior to closure, this unit measured 400 square feet and was used to store corrosive wastes and raw material chemicals.

Date of Startup:

This unit began operations in 1983 for corrosives waste storage. Between 1984 and 1987, this unit was used for raw material chemicals storage. In 1990 the room was enlarged and the WWTP began operation.

Date of Closure:

In 1984, the facility stopped storing wastes in this unit and began storing raw material chemicals. In 1987, IEPA approved RCRA closure of the unit.

Wastes Managed:

This unit treats waste acids and waste caustics generated from metal finishing baths. Raw material drum rinsate is also treated. The WWTP generates nonhazardous filter bags and nonhazardous photoresist solids, which are disposed of off site in a municipal landfill; copper sheeting, which is recycled; and treated wastewater, which is discharged to MWRD and monitored daily. Between 1983

and 1984, this unit managed waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanide (F007, D002, D011), and spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039) stored in 55-gallon drums. No information is available on whether these incompatible wastes were isolated from one another. These wastes were either incinerated, treated, or reclaimed off site. In 1984, the facility stopped storing wastes in the unit, and from 1984 to 1987 raw material chemicals were stored in the unit.

Release Controls:

This unit has always been maintained indoors and equipped with a sprinkler system and an emergency shower. The floors are recessed and sealed with an epoxy coating. No floor drains or windows are present in this unit.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

PRC observed that this unit was in good condition and wastes were being well managed (see Photograph No. 1). The filter bags were air dried and then placed in a 55-gallon drum. Photoresist solids were pressed dry and dropped into a hopper (see Photograph No. 2) prior to being shoveled into a 55-gallon drum that was about half full. Copper sheeting was stacked near the ionizing unit that generates the copper sheeting (see Photograph No. 3).

SWMU 2

Room 6407

Unit Description:

This unit is maintained indoors on the east central side of 600 Building north of Room 6409 (SWMU 1). This unit is currently used for raw material chemical storage. This unit was used to store hazardous wastes in 55-gallon drums for less than 90 days between 1983 and

1984. This room measures 400 square feet and had a concrete floor. No floor drains are present in this room.

Date of Startup:

This unit began operations around 1983 for waste storage. Since 1984, this unit has been used for raw material chemicals storage.

Date of Closure:

In 1984, the facility stopped storing wastes in this unit and began storing raw material chemicals. In 1987, IEPA approved RCRA closure of the unit.

Wastes Managed:

No wastes are currently managed in this unit. Between 1983 and 1984, this unit managed waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), and spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039) stored in 55-gallon drums. No information is available on whether these incompatible wastes were isolated from one another. These wastes were either incinerated, treated, or reclaimed off site.

Release Controls:

This unit has always been maintained indoors and equipped with a sprinkler system. The floors are recessed and were covered with an epoxy coating when the unit stored wastes. This unit had a floor drain that was filled with concrete in late 1984. This drain was connected to the facility's sanitary sewers which discharged to and were monitored daily by MWRD. This unit is equipped with explosion proof lighting, blow-out panels, and a blow-off roof. No windows are present in this unit.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

During the VSI, no wastes were stored in this unit. The unit currently stores freon and flammable raw materials (see Photograph No. 4).

The floor has seams, and PRC observed some cracks. The epoxy coating on the floor appeared to be eroding. PRC observed some staining on the floor but could not determine the source. PRC did not observe the floor drain that had been filled in 1984.

SWMU 3

Room 6419

Unit Description:

This unit is maintained indoors on the east central side of 600 Building south and adjacent to the WWTP (SWMU 1). This unit is currently used to store all hazardous corrosive wastes in drums that are to be shipped off site for treatment. This unit measures about 800 square feet and has a concrete floor that is tiled in some areas, bare in others, and epoxy-coated in others. No floor drains are present in this room. This room was not included on the facility's original or revised Part A permit applications.

Date of Startup:

This unit began operation in 1988.

Date of Closure:

This unit is active for storing hazardous wastes for less than 90-days.

Wastes Managed:

This unit manages waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), waste filters (D011), nonhazardous filter bags, and nonhazardous photoresist solids. Berms and walls are used to keep incompatible wastes separated. The hazardous wastes are transported off site for either treatment or reclamation. The nonhazardous wastes are disposed of off site in a municipal landfill.

Release Controls:

In this unit, the northern half of the floor is bermed and has an epoxycoated concrete area, a tiled concrete area, and a bare concrete area. The southern half of the floor is bare concrete. The room is equipped with a sprinkler system. No floor drains or windows are present in this unit.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

At the time of the VSI, 3 55-gallon drums of waste cyanide were located under a ventilation hood. At this hood, 5-gallon buckets of wastes, collected in SAAs (SWMU 8), are transferred into 55-gallon drums. This vent has been operating since 1989 and leads directly outdoors. In addition to these drums, the room contained 7 55-gallon drums of waste acids, 13 55-gallon drums of waste caustics, 7 drums of waste cyanides, and 2 55-gallon drums of nonhazardous filter bags. A concrete berm has been constructed in the middle of the room (see Photograph No. 5). PRC observed some drum ring marks on the floor south of the bermed area.

SWMU 4

Room 5087

Unit Description:

This unit is maintained indoors on the east central side of the 500 Building. This unit is currently used as a testing facility for finished products but was used to store hazardous wastes in 55-gallon drums between 1982 and 1984. This room measures 400 square feet and has a tiled concrete floor. No floor drains are present in this room.

Date of Startup:

This unit began storing waste for less than 90 days around 1983.

Between 1984 and 1987, this unit was used for raw material chemicals storage. Currently, the unit is used for testing finished products.

Date of Closure:

In 1984, the facility stopped storing wastes in this unit and began storing raw material chemicals. In 1987, IEPA approved RCRA closure of the unit.

Wastes Managed:

No wastes are currently managed in this unit. Between 1983 and 1984, this unit managed waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), and spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039) stored in 55-gallon drums. No information is available on whether these incompatible wastes were isolated from one another. These wastes were either incinerated, treated, or reclaimed off site.

Release Controls:

This unit has always been maintained indoors and equipped with a sprinkler system. The floors are not recessed but were coated with epoxy when the unit stored wastes. This unit has no floor drains and no windows.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

PRC observed finished products on shelves (see Photograph No. 6). This unit contains diagnostic equipment to test finished products. The floor was tiled; no floor drains were observed.

SWMU 5

Room 5097

Unit Description:

This unit is maintained indoors on the east central side of the 500 Building south of Room 5087 (SWMU 4). This unit is currently used to store all waste solvents in 55-gallon drums for less than 90 days. This room measures about 400 square feet and has a concrete floor that is bare in some areas and epoxy-coated in others. No floor drains are present in this room. This was the only room included on the facility's original Part A permit application.

Date of Startup:

This unit began operation in 1980.

Date of Closure:

In 1987, IEAP approved RCRA closure of the unit. This unit is currently used for less than 90-day storage of hazardous waste.

Wastes Managed:

This unit manages spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039), solvent-contaminated waste oil (F001), solvent-contaminated rags (F005, D001, D035), spent photodeveloper (D008), and LABPs of expired chemicals. These wastes are transported off site for either fuel blending or treatment.

Release Controls:

This unit has always been maintained indoors and equipped with a sprinkler system. The floors are recessed and partially covered with an epoxy coating. This unit has no floor drains and no windows. This unit is equipped with explosion proof lighting, blow-out panels, and a blow-off roof.

History of Documented Releases:

No releases from this unit have been documented.

Observations:

At the time of the VSI, two 55-gallon drums of spent freon were located under a ventilation hood (see Photograph No. 7). At this hood, 5-gallon buckets of wastes, collected in SAAs (SWMU 8), are transferred into 55-gallon drums. This vent has been operating since 1981 and leads directly outdoors, but it is not covered by an operating permit. The unit also stored eight 55-gallon drums of spent solvents, one 55-gallon drum of solvent-contaminated waste oil, one 5-gallon bucket of solvent-based paint, seven 55-gallon drums of nonhazardous waste, and six empty 55-gallon drums (see Photograph No. 9). PRC observed stains on the floor and areas where the epoxy coating is wearing away. No floor drains were observed in this unit. Shelving on the north side of the room stores expired chemicals that are awaiting other uses (see Photograph No. 8).

#### SWMU 6

#### Freon Stills

Unit Description:

Two stills are located indoors in the 500 Building where degreasing activities occur. One unit is an Electrovert degreaser and still. The other unit is a Barron-Blakeslay degreaser and still. Each has a 220gallon capacity. The rate of regeneration varies with the facility's production level. The floors in these areas are tiled and do not have

floor drains.

Date of Startup:

These units began operation in 1990.

Date of Closure:

The units are active.

Wastes Managed:

These units are used to distill dirty freon used in degreasing operations. In 1992, the facility recycled about 810 gallons of freon. Still bottoms generated from the distillation process are placed in 5gallon buckets SAAs (SWMU 8), transported to Room 5097 (SWMU 5), transferred into 55-gallon drums and stored prior to being disposed of off site.

Release Controls:

The one unit observed by PRC is maintained indoors on a tiled floor with no floor drains in the vicinity.

History of

Documented Releases:

No releases from these units have been documented.

Observations:

At the time of the VSI, one still was out of service, and the other was not in use (see Photograph No. 10). PRC observed only the operating unit and it appeared to be in good condition. PRC observed no evidence of release.

## SWMU 7

## **Empty Drum Storage Area**

Unit Description:

This unit is maintained on an asphalt paved area outdoors between the 600 Building and the 600A Building. The total area used for drum storage is about 650 square feet. Empty drums from raw material chemicals are rinsed in a continuous-flow washer for a few minutes in the PWB production wet process area in Room 6424. The rinse water is treated in the WWTP (SWMU 1). The drums are then stored outdoors to be picked up by chemical distributors or manufacturers for reuse.

Date of Startup:

This unit is estimated to have begun operating in 1987.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages empty drums that contained raw material acids, caustics, 1,1,1 TCA, and toluene. Prior to storage, the drums are rinsed. Empty drums are picked up by chemical distributors and manufacturers to be reused. Prior to 1987, few drummed products were used. At that time, empty drums were stored near the areas where they were used. Off-site disposal was identical to current management practices.

Release Controls:

The drums are rinsed and drained prior to storage. The pavement slopes to a storm water sewer that flows into the retention basin (IT 1992).

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

PRC observed empty drums stored on their sides up to five drums high. Drums are stored on east and west sides of the pavement

between the two buildings. The pavement slopes north toward a storm water sewer. At the time of the VSI, about 100 drums were being stored (see Photograph Nos. 11 and 12). PRC observed a 1.5-foot-radius stain of unknown origin on the asphalt about 20 feet north of the drum storage and upgradient from the storm sewer. It appeared this stain could have been from trucks parked in the area to pick up drums.

SWMU 8

Satellite Accumulation Areas

Unit Description:

These areas are maintained indoors and are located near production areas and laboratories. These areas consist of 5-gallon buckets or 55-gallon drums.

Date of Startup:

These areas began operating in 1967.

Date of Closure:

These areas are active.

Wastes Managed:

These units manage waste acids (D002, D007, D008), waste caustics (D002, D008), waste cyanides (F007, D002, D011), spent solvents (F001, F002, F003, F005, D001, D006, D007, D018, D035, D039), solvent-contaminated waste oil (F001), solvent-contaminated rags (F005, D001, D035), spent photodeveloper (D008). These wastes are stored in either 5-gallon buckets or 55 gallon drums for treatment or reclamation off site.

Release Controls:

All containers are stored closed and maintained indoors.

History of

Documented Releases:

No releases from these areas have been documented.

Observations:

PRC observed numerous satellite accumulation areas throughout the facility, consisting of a variety of containers (see Photograph Nos. 13 through 17). All containers were stored closed and appeared to be in good condition. Floor drains were not present near these areas except for drums in the PWB area. The PWB area has floor drains and a sump that are connected to the facility's WWTP.

## 4.0 AREAS OF CONCERN

PRC identified one AOC during the PA/VSI. This AOC is discussed below; its location is shown in Figure 2.

# AOC 1 Former Underground Storage Tank Location

This AOC is located outside the southwest corner of the 600 Building (see Photograph No. 18). This 500-gallon, steel UST was installed about 1971 and was used to store a silicone-oil coolant. The tank was excavated in 1977, but no soil sampling or leak testing was conducted to verify that no releases to subsurface soils had occurred. No documentation exists of state or local approval of the tank removal. According to facility representatives, the tank was taken off site and used to store diesel fuel, implying that the tank was in good condition.

RELEASED YOUR AND THE 


INITIA 5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified eight SWMUs and one AOC at the Northrop facility. Background information on the facility's location; operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is presented in Section 3.0. AOCs are discussed in Section 4.0. Following are PRC's conclusions and recommendations for each SWMU and AOC. Table 3, located at the end of this section, summarizes the SWMUs and AOCs at the facility and the recommended further actions.

SWMU 1

Wastewater Treatment Plant

Conclusions:

Between 1983 and 1984, this unit was used to store a variety of wastes generated at the facility. IEPA approved closure of this unit in 1987. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 2

Room 6407

Conclusions:

Between 1983 and 1984, this unit was used to store a variety of wastes generated at the facility. IEPA approved closure of this unit in 1987. The unit is maintained indoors and is currently used for raw material chemicals storage. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 3

Room 6419

Conclusions:

This unit began operating in 1988 and is currently used to store for less than 90 days any hazardous corrosive waste that cannot be treated in the WWTP.

The unit is maintained indoors. The potential for release to environmental media is low.

Recommendations:

PRC recommends applying epoxy to bare concrete areas on the southern half of the room. PRC also recommends determining if a distinct air permit is needed for the exhaust vent.

SWMU 4

Room 5087

Conclusions:

Between 1983 and 1987, this unit was used to store a variety of wastes generated at the facility. IEPA approved closure of this unit in 1987. The unit is maintained indoors and is currently used for testing finished products. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 5

Room 5097

Conclusions:

Between 1980 and 1987, this unit was used to store solvent wastes. IEPA approved closure of this unit in 1987. This unit is currently used for less than 90-day storage of solvent wastes only. The potential for release to environmental media is low.

Recommendations:


PRC recommends inspecting, sampling, and repairing floor cracks. PRC also recommends reapplying epoxy coating to the floor surface and determining if a distinct air permit is needed for the exhaust vent.


SWMU 6

Freon Stills

Conclusions:

The facility began using freon stills in 1990. Currently one is out of service and one is operated in the facility. Freon is used as a degreaser, and dirty freon is distilled and reused. Still bottoms are collected in 55-gallon drums







and stored in Room 5097 (SWMU 5) prior to being disposed of off site. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 7

**Empty Drum Storage Area** 

Conclusions:

This unit is maintained outdoors and upgradient from a storm water sewer that flows into the retention basin. Drums from raw material chemicals are rinsed in a continuous-flow washer for a few minutes. The rinsewater is treated in the WWTP located in Room 6409 (SWMU 1). The empty drums are then stored outdoors to be picked up by chemical distributors or manufacturers for reuse. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 8

Satellite Accumulation Areas

Conclusions:

These units have been active since the facility began operation. Either 5-gallon buckets or 55-gallon drums are used to accumulate wastes near their point of generation. These units are maintained indoors and can be located near all manufacturing areas and laboratories within the facility. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

AOC 1

Former Underground Storage Tank Location

Conclusions:

Between 1971 and 1977, this tank was used to store a silicone-oil coolant. It was excavated in 1977; however, no samples were collected, the tank was not leak tested, and no documentation exists on whether the removal was approved by state or local authorities.


CONFIDENCIAL

Recommendations:

PRC recommends collecting subsurface soil samples to verify that no releases from the tank occurred.

RIN F. MV







	SWMU	Dates of Operation	Evidence of Release	Recommended Further Action
1.	Wastewater Treatment Plant	1983 to 1987; 1990 to present	None	None
2.	Room 6407	1983 to 1987	None	None
3.	Room 6419	1988 to present	None	Apply new epoxy floor covering; obtain air permit if necessary
4.	Room 5087	1983 to 1987	None	None
5.	Room 5097	1980 to present RCRA-closed in 1987	None	Inspect, sample, and repair floor cracks; reapply epoxy floor covering; obtain air permit if necessary
6.	Freon Stills	1990 to present	None	None
7.	Empty Drum Storage Area	1987 to present	None	None
8.	Satellite Accumulation Areas	1967 to present	None	None
	AOC	Dates of Operation	Evidence of Release	Recommended Further Action
1.	Former UST Location	1971 to 1977	None	Collect subsurface soil samples

#### REFERENCES

- Baxter and Woodman, Inc. (B&W), 1986. Letter from Bruce G. Mack, to Lawrence Eastep, Manager, Division of Land Pollution Control, Permit Section. December 22.
- B&W. 1987. "Hazardous Waste Storage Facility Closure Plan." Northrop Corporation, Defense Systems Division, Rolling Meadows, Illinois. July 14.
- Bogner, Jean E. 1976. Geology for Planning in Northeastern Illinois. Part V, Geology for Planning in Cook County, Illinois State Geological Survey. August 31.
- Federal Emergency Management Agency (FEMA). 1985. Flood Insurance Rate Map. City of Rolling Meadows, Illinois, Cook County. Community-Panel Number, 170155 0005 C. Revised June 19.
- Illinois Department of Public Health. 1967. "Well Construction Report." Geological Water Surveys Water Well Record. September.
- Illinois Environmental Protection Agency (IEPA). 1982. Violation Letter from Kenneth P. Bechely, Northern Region Manager, Division of Land Pollution Control, to James Nelson, Northrop Corporation. May 7.
- IEPA. 1985a. Application Denial Letter from Eugene P. Theios, Manager, Disposal Alternatives Unit, Permit Section, Division of Land Pollution Control. January 8.
- IEPA. 1985b. E. Theios, Internal Communication Regarding Northrop Corporation's Supplemental Waste Stream Permit. January 16.
- IEPA. 1985c. Water Pollution Control Permit No. 1985-EP-1804, Issued to Northrop Corporation, Defense Systems Division, for Metal Finishing Line 1. Issued January 17.
- IEPA. 1986a. Application Denial Letter from Lawrence W. Eastep, Manager, Permit Section, Division of Land Pollution Control to Lisa Riggle, Northrop. February 6.
- IEPA. 1986b. Water Pollution Control Permit No. 1986-EE-0077. Issued to Northrop Corporation, Defense Systems Division, for Industrial Pretreatment, Issued February 27.
- IEPA. 1986c. "RCRA Facility Inspection Report." Completed by Caroline Panico. December 19.
- IEPA. 1987a. Compliance Inquiry Letter from Harry A. Chappel, Acting Manager, Facilities Compliance Unit, Division of Land Pollution Control, to John Protheroe, Northrop. February 6.
- IEPA. 1987b. Closure Plan Approval Letter from Lawrence Eastep, Manager, Permit Section, Division of Land Pollution Control, to Northrop Corporation. March 9.

- IEPA. 1987c. RCRA Closure Denial Letter from Lawrence Eastep, Manager, Permit Section, Division of Land Pollution Control, to Northrop Corporation. August 18.
- IEPA. 1987d. Closure Approval Letter from Lawrence Eastep, Manager, Permit Section, Division of Land Pollution Control, to Robert Langlois, Northrop Corporation. December 21.
- IEPA. 1988. Compliance Inquiry Letter from Miles Zamco, Manager, Field Operations, Division of Air Pollution Control, to John Protheroe, Environmental Engineer, Northrop Corporation. July 21.
- IEPA. 1989. Compliance Inquiry Letter from Eugene P. Theios, Manager, Administrative Compliance Unit, Compliance Section, Division of Land Pollution Control, to Lisa Riggle, Northrop Corporation. March 23.
- IEPA. 1990a. Water Pollution Control Permit No. 1990-EN-4663, Issued to Northrop Corporation, Defense Systems Division, for Pretreatment of Metal Finishing Wastewater, Issued January 30.
- IEPA. 1990b. Air Operating Permit for Plating and Beryllium Deburring Operations. Issued to Northrop Corporation, I.D. No. 031815AAC. Issued on April 20.
- Illinois Pollution Control Board. 1990. Opinion and Order of the Board, PCB 89-192. March 22.
- IT Corporation. 1992. "Spill Prevention Control and Countermeasure Plan. "Northrop Corporation, Electronic Systems Division, Rolling Meadows, Illinois. January.
- Northrop Corporation (Northrop). 1980a. Notification of Hazardous Waste Activity Form. Submitted August 15.
- Northrop. 1980b. Hazardous Waste Permit Application. Submitted November 18.
- Northrop. 1982a. Response Letter from James L. Nelson to Kenneth P. Bechely, IEPA. May 24.
- Northrop. 1982b. Hazardous Waste Permit Application. Submitted December 14.
- Northrop. 1984a. Hazardous Waste Permit Application. Submitted March 15.
- Northrop. 1984b. Closure Plan, Document No. 099-006257. Effective April 4.
- Northrop. 1987a. Hazardous Waste Permit Application. Submitted January 6.
- Northrop. 1987b. Response Letter from R. Langlois, Director, Facilities/Administration, to Harry A. Chappel, Acting Manager, Facilities Compliance Unit, IEPA. February 16.
- Northrop. 1987c. RCRA Part A Permit Withdrawal Letter from Richard Ng, Manager, Safety and Industrial Hygiene, to Lawrence Eastep, Manager, Permit Section, Division of Land Pollution Control, IEPA. July 20.

- Northrop. 1987d. Response to IEPA Disapproval Letter from Robert Langlois, Director, Facilities/Administration, to Lawrence Eastep, Manager, Permit Section, Division of Land Pollution Control, IEPA. October 5.
- Northrop. 1989. Response to Compliance Inquiry Letter, from David A. Gurrie, Manager, Facilities Support Services, to Dana Curtiss, Administrative Compliance Unit, Compliance Section, IEPA. March 29.
- PRC Environmental Management, Inc. (PRC). 1993a. Record of Telephone Conversation Regarding General Information, between Jeff Swano, and Dave Gurrie, Northrop. June 9.
- PRC. 1993b. Record of Telephone Conversation Regarding Groundwater and Surface Water Uses, between Jeff Swano, and Orrin Helms, Water Foreman, Palatine Public Works, June 9.
- PRC. 1993c. Record of Telephone Conversation Regarding Groundwater and Surface Water Uses, between Jeff Swano, and John Somogyi, Water Production Supervisor, City of Rolling Meadows. June 9.
- PRC. 1993d. Record of Telephone Conversation Regarding Facility Operations, between Jeff Swano, and Ed Glod and David Gurrie, Northrop. July 1.
- PRC. 1994. Record of Telephone Conversation Regarding General Information, between Cathy Collins, and Dave Gurrie, Northrop. April 14.
- U.S. Department of Agriculture (USDA). 1979. Soil Survey of DuPage and Part of Cook Counties, Illinois. Soil Conservation Service.
- U.S. Department of Commerce (USDOC). 1963. Rainfall Frequency Atlas of the United States. Technical Paper No. 40. Government Printing Office, Washington, DC.
- USDOC. 1968. Climatic Atlas of the United States. Government Printing Office, Washington, DC.
- U.S. Department of the Interior (DOI). 1989. Endangered, Threatened, and Proposed Species to be Considered During Section 7 Consultations. March.
- U.S. Geological Survey (USGS). 1961. Palatine Quadrangle, Illinois, Cook County. 7.5 Minute Series Topographic Map. Photorevised 1972 and 1980.
- Warzyn Engineering, Inc. 1987. Log of Test Boring, Environmental Boundary Survey, 600 Hicks Road, Northrop,. March 11.

# APPENDIX A VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

(11 Pages)

# VISUAL SITE INSPECTION SUMMARY

Northrop Corporation, Electronics Systems Division 600 Hicks Road Rolling Meadows, Illinois 60008 ILD 005 128 988

Date:

May 21, 1993

Primary Facility Representative: Representative Telephone No.:

Additional Facility Representatives:

David A. Gurrie (708) 259-9600 Edward F. Glod

Eric B. Howell

William A. Cameron

Inspection Team:

Jeff Swano, PRC Environmental Management, Inc. (PRC)

Ron Baker, PRC

Photographer:

Ron Baker

Weather Conditions:

Sunny, calm, about 65 °F

Summary of Activities:

The visual site inspection (VSI) began at 8:15 a.m. with an introductory meeting. The inspection team explained the purpose of the VSI and the agenda for the visit. Facility representatives then discussed the facility's past and current operations, solid wastes generated, and release history. Facility representatives provided the inspection team with copies of requested documents.

The VSI tour began at 12:00 p.m. outside of the facility by the Former Underground Storage Tank Location (AOC 1). The inspection team walked around the outside of the entire facility and observed the retention basin, the Empty Drum Storage Area (SWMU 7). The inspection team then went inside to observe the manufacturing processes and waste management practices. The inspection team observed the printed wire board (PWB) area and SAAs (SWMU 8). The team then entered Room 6409 and observed the WWTP (SWMU 1). The inspection team next entered Room 6407 (SWMU 2) and saw that raw material chemicals were being stored in this room. Next the inspection team entered Room 6419 (SWMU 3) and observed how corrosive wastes are handled. The inspection team entered assembly area and an engineering laboratory and saw more SAAs (SWMU 8). After obtaining security clearance, the team entered Room 5087

(SWMU 4) and observed testing of finished products. The inspection team entered a large assembly area and observed a Freon Still (SWMU 6). The team next entered Room 5097 (SWMU 5) and observed how solvent wastes are handled.

The tour concluded at 3:50 p.m., after which the inspection team held an exit meeting with facility representatives. The VSI was completed and the inspection team left the facility at 4:30 p.m.



Photograph No. 1 Orientation: Southeast

Description: Partial perspective of the WWTP (SWMU 1).

Location: SWMU 1 Date: 05/21/93



Photograph No. 2 Orientation: West Location: SWMU 1

Date: 05/21/93

Description: Hopper containing photoresist solids generated in the WWTP (SWMU 1). The drum

in the foreground contains photoresist solids.



Photograph No. 3 Location: SWMU 1
Orientation: North Date: 05/21/93

Description: Ionizing tank of the WWTP (SWMU 1) that regenerates copper sheeting.



Photograph No. 4 Orientation: East Location: SWMU 2

Date: 05/21/93

Description: Room 6407 (SWMU 2) was formerly used as a hazardous waste storage room; it is

currently used to store raw material chemicals.



Photograph No. 5 Orientation: East

Description:

Location: SWMU 3

Room 6419 (SWMU 3) is the corrosives waste storage room. The northern half of

floor is bermed; the southern half of floor is bare concrete; the ventilation hood is

located to the left and marked with a caution sign.



Photograph No. 6

Location: SWMU 4

Orientation: Southeast

Date: 05/21/93

Description:

Room 5087 (SWMU 4) was formerly used to store hazardous waste. It is currently

used to test finished products.



Photograph No. 7 Orientation: East Location: SWMU 5

Date: 05/21/93

Description: Room 5097 (SWMU 5) is the solvent waste storage room. Note the ventilation hood.

Also, note the eroding epoxy floor covering.



Photograph No. 8 Orientation: North

Description:

Location: SWMU 5

orth Date: 05/21/93 Room 5097 (SWMU 5); expired chemicals storage shelf at north end of room. Sign

on shelf reads "out dated material disposition to be determined".



Photograph No. 9 Orientation: North Location: SWMU 5 Date: 05/21/93

Description:

Room 5097 (SWMU 5); drum storage in north half of room. Note expired chemical

storage on shelves in foreground and on back wall.



Photograph No. 10

Location: SWMU 6 Orientation: East Date: 05/21/93

Freon Still (SWMU 6); dark blue objects in the foreground and in the background are Description:

the Electrovert's degreaser and a freon still, respectively.




Photograph No. 11

Location: SWMU 7 Date: 05/21/93

Orientation: Northwest Description: Empty 5

Empty 55-gallon plastic drums on west side of driveway in Empty Drum Storage Area

(SWMU 7) awaiting pick-up.



Photograph No. 12

Location: SWMU 7


Orientation: Northeast

Date: 05/21/93

Description:

Empty 55-gallon steel and plastic drums on east side of driveway in Empty Drum

Storage Area (SWMU 7) awaiting pickup.



Photograph No. 13

Location: SWMU 8


Orientation: East

Date: 05/21/93

Description:

Waste caustics (D002, D008) in a satellite accumulation area (SWMU 8) in PWB

production area. Etched copper is drying on the table to the left.



Photograph No. 14 Orientation: South Location: SWMU 8 Date: 05/21/93

Description:


Spent photodeveloper (D008) in SAA (SWMU 8).



Photograph No. 15 Orientation: North

Spent freon (F001) in SAA (SWMU 8).

Location: SWMU 8 Date: 05/21/93



Photograph No. 16

Location: SWMU 8

Orientation: South

Date: 05/21/93

Spent solvents (F001, F002, F003, F005) in SAA (SWMU 8) in the MIC production Description:

area.



Photograph No. 17 Orientation: South Location: SWMU 8

Date: 05/21/93

Description: Solvent-contaminated rags (F005, D001, D035) in SAA (SWMU 8).



Photograph No. 18 Orientation: North Location: AOC 1 Date: 05/21/93

Description: Former Underground Storage Tank Location (AOC 1); the tank was located beneath

the bushes.

# APPENDIX B VISUAL SITE INSPECTION FIELD NOTES

(16 Pages)

+ eliminarith program. USIS. Meet in conference volum to Manufacturing that dura go Checkin at security diste. 0810 Dave Guril Dicks us up describes to by and are lure on is electronic circuit Start Medicen Seft MOST manufaterning gaes Dave uses over heres to plandypols, so any little in 600 A Blag. Products suit here are manafacturing coes on. Build elecander tubes. tar this inspection give a presentation. Baral

Ed now gives a presentation. prior to purchase. They lake Worthrop want to de end. Stewardship Fredu reduction Dave Kinshes brock dudies, as Wealth & Saleny as well as many factioning Concerns dought out + lake like All Chemicals there can ter the Chemical strange areas on least star start start starts borowark is producting an building and redigued H+5 | ssups | are | well no romanial majue a good program.

Frans Sportes

Forant 5/21/93

So FODG was mishbul --Morthrop Corp ESD, Belling Medows Site. it should not have been on the largest defense contractor are munimis that Northrop Part. A permin application. trumple and sevento wurps Manufacening & Paw mosteries Circuit ands; 5.gallar 97795 of chemicals is a from to 1984, everything was Odnorship is Northop Cap. Juano stayo3 off site (4/50 11 tan fews) a publically held forp. age grouns. BFE TO a land All Clownis a leyen 1 yard. Us mested. Its play and a powder-the sissone desisting" is stryp ing off plan tile- like. This will not as a special waste by (50 ld plumy bounds create Small anits. The Solution sent to a recycler once STARE operated by BFI Comes out Theoris our go Mongh. Columns. It is show attheore Copper shutting. Der 4 ans.


Generates Flux, Thinner +
Freah. There is a small
Container for Waste
5-gillon, Flowble Storage Will now by Safery Kleen bor Hamable pick up. Thers Seur | TO Hillis (14 & 5/4/19) Abon ILL Fuel 6leding of land 6/65) Transferred uso 155 gallon drums. When hill labled + ready for shipment. combustable Contoliners, Once Rilad ar Mrs locanon Then Wire/Component preparation S-K Lill do 14.5) July 5/2/93 e lectionics testing - maybe some Flux paints, the nners also. puchased in small <5 gallon 0920 Bill Cameron amores Most. labs in this focium are Plax, a harle thinners them. in bays + 53 gallons."
Acids + bases are bought solumis, alabels, ore all WWTP | chemidals are bought (Silizan sealeys adhersive) Lubridants, epskies, RTV No rail Ing mansportation Circuit - board sealants. In 55 galler drums.

<b>3</b>		(FS)
Swind	SWMM Reminder check list:	1.1. Trichloro ethane fram a
Jak Jak	Date legan detranous.	Solder-cleaning (Tinger cleaner).
Ch. Te	The received opera ming	5 gallen congainers and
Cmss	Construction materials	accumulated in 55 gallons in
Din	Dimonsions / Capacity	5097 room.
[457	last releases!	
Sec.	Secondary Con Tain ment and	Town Supply assembly.
0	other deservanions.	Building aunglifiers Isome
		fireig bounds) that supply
North	Northing that's to keep wastes	The power go no products.
Sepus	Sepreated in different dums.	IT is also the a mansform.
		Wastes are Fron, cleaning
Minney (	Mined Orthit Band Assembly.	solvening, mast methy he chloride,
Fee		Wire: Frear is cascoded & when dury
(Contraction)	Contras (Humiseal, a clar	in gets to a bigger degraser
Pobyn	Dobyerethane sealer Ins	That his a shill SHI bettoms
gaes	goes to 5097, Additionally	go to 5397, This is have
7		mosi fear is hardled.
	Mone 5/21/93	
		Child Mam > (3)

1 Silcare rubber is encopsilated wound some Supplies; some to. it. Alabals are used for cleaning. Whe insularian, hear Sinks.
Amy left over silicone is Smill bettoms go to Satury Kieen who registes The Cail Assembly. | Authorise from soft site, waterials. Dolron, IL Mnesses. Works as Duana 5/41/93 Encapsulation Parility. & start ( Eminion mental Eysoten's Company) Ruca used since 1993. Before Drie of decision and anually. grands them and find blends. what memerated by Ensco This for Northorp. LWD, Inc. Of KY Wipe 1995 come our of all Day, Gaus, picked up douby. vasce handly or disposal Whener Northrep choses a from El Donale, Arkan Sas. Rineco , Senton Arkausas, taxilim, it is audited Evan 5/2/93 for meneralizan. SMCB / 1984.

bittanide. Goes to Flean How bors Primped out of disture stored in one room. Environte, time. is reclaimed by the poducer hydrachloris acid. Goes To Clean Harbors of Chroga bulked; I tanker per week. Before WWTP everything was Trailer | Truck takes diums. Treather workers. Fin /lead Stripper solution Ammonia copper enthing of hydrogen phrase: de Ssdienn CP Inorganics, Inc. Hi Ferric chlorhides Brown 5/21/93 Same as above. Jal:4, EL The plant. They are straved beaths campt be treated by municipal wasre landfilling. M. SS. gallon drums, These 200 Stored 1 1000 6419 there into a cushe bu for The mystim of wastes Clearaniz Gomponpurs. cured. Suepr up soft the all corrosings come here, Same rags. Terrs to Dudus Stall93 Prince Wir my Boards. Some Rays See house ESTING

to a copper you do paring buth. 53-galons each once even ~3-years. Goes to Grandchem & shy, Cyano Kem, of Destroit, Silver Granide plasmy bath. biggest user of TCE. Gres To dow 5094. lags, acetone, some toluene, Include | degrepsing | Salumbn Building my chips, Wasers 11so ymister Rags, Fron 1 M c/m brid cycuits DWar 5/21/93 5 gal dums and accumulated Gold planny booth every 3-5 years 55 gallan drum goes Ack, kne. in IL. Same Fren + 111 migdes One planna area. The Solutions are collected in Michie - Plane Solumin. To physphoriz and. Same as Acid Brige dip night (Suburhan (Arrago). a separate product An 5/4/93 Clean Harbort Elecaran Tubes. in Room 6419. 布 5097 abour,



Might be arning from	Out UST removed in 1977. Contained Silicone vil. a coolant from earlier Systems (8-52 Sombus)	Our indergrand dress! the! LINE from an noor-gionel touth. No other gants	Nothing arrenally comes over as waste from other Northop facilities	Air permits (bubbled), about 8. Ewans 5/2/193
USENS. Even the its expired it is not a wash	Coron 5087 now Storaye 6409 is now WWTP. 6407 Chuncal Storage	No wells for closure. Wipe	Some grandanter sampling around 1957 after closure Some wells mignified	To precontionary st what

K

	in it is removing any 840.			beryllyan didn't the the data.		Remed was	SED CEramics Morthop Corp Owns property	elean Meressary to report. A	₩ 2 KW T	Javan 5/01/93
(ES)	Air permir vislation of 1990. JEPA souted	STEPA NUMBERED THE INFO.	franked by Northop.	Oxido. A vacuum clearer	Said to get the r	Abraisive change	-	(Degraser doesn't work	The material. In	July 5/21/93

FIRE SECONSE all pummits A NPDES permit was Filed in Mid-1950s (1950) Servedy problems and Send PRC 3 cyp.75 will get negatives any of all photos are obid. And we will yet negatives only of the obid photos To Morthop. Northrop Will were hild at same mue + will hand over the film PRC will rake photographs 1120 Inrevolution ends it 1120 develop film review it to Juster 5/21/93 Steen on Leventran Gasin.
(Spring 1992) Round.
Source to be from Detemption basin callects of Hend of Cleaned up Industs. Legal Councel later Decoded it wasn't Sporm nater collected from Snow-removal equipment The emotive property. terosene unped on tran a contractor. Sum 5/2/93 acres Necessary

Segregard 6, who will picked	up by dismibutists for mets.	Ou asphult that slopes Nowth. Some spilled or	Stained as phali north	Storm sent North of it.	1315 Observe planny lines. An actuals have go to	9226, a first my Solution	Emply both 12 we flow wash of	(Slugar 5/21/93
1130 Break For Much	1200 End lunch began walt around.	<del></del>	ing + some ranspactation	the 11.7% around the	1232 Shipping her his flow dains	Starm Water source	1245 See among DSA out don's	2/19/43.

	Some staining the fluor	A 6/02-off Josef Bround	doorway, Some cracks	a gien epory pina on		Wast Stavage Are on	Why six at my has	Been birmed of 12 di	Sahrs are fall a with 146els. Alta	2 55 gal down sox paging	A war or large love	(Wans 5/21/83
,	1335 Ente worth ste	MEUNTER Menufactured the	Lywi TP	Filters are actived and drammed	-	at the north end of		Bromed floors		<b>~</b> }i	Property of the Store	(Swaws 5/24/93

.

Hord Vents straight sur Drums and wholeofer out acomply the room is lower than the rest of the building Sport angral material of the rom to a dick God Signage the is Blow off windows. Soor is berneft -Trains is Lage 1520 Rom 5097. Stains on these of hord and have dring been 9114 Hamiseal Lesger 5235 (ma 5-gallen). Paino 13 2 a Egallen Sucker 13 Another Nan-Lez waste LOTS of "but bate" Also 6 duns of non-haz morterials on Shelvis. Hor non-regulated was be Under hood of frams Fram 5/21/92

		·			
94 - 12	Gled a Moribianoss Wasse Aconstry L Closure ITA did not.	Scharge C. Carlo	on meeting.	er the	
End walk thou	See it they ared a Moribianows of Hazardaus Wasser Activity Report after Closure its	into Sover dis  into Salo Coule  Dogen 17m pond  parteny (or and	Begin Rebrieh	PRC hands over 1311 of film T	Deput Worthrop
SS 52			<u> </u>	1620	1630

# APPENDIX C SOIL AND GROUNDWATER ANALYTICAL RESULTS

(10 Pages)

LAPZYN ENGINEERING

VOL TILE ORGANIC COMPOUND RESULTS ROJECT: NORTHROP BOUNDARY SURVEY

DCATION: CHICAGO, ILLINOIS

C#: 60222.00

CK'D: KAW APP'D: CAW DATE ISSUED: 4-9-87

·				
	REPORTABLE			
	DETECTION	14851	14852	14853
	LIMIT	82-1	P1-1	B1-3
JOHPOUND	(UG/KG)	03/06/87	03/06/87	03/06/87
=======================================	========	======	=======	=======
INZENE	50	Χ	X	X
ROMODICHLOROMETHANE	50	Χ	X	X
BROMOFORM	100	Χ	Χ	X
TRBON TETRACHLORIDE	50	Χ	X	X
ILOROBENZENE	50	X	X	X
CHLORODIBROMOMETHANE	50	Χ	X	X
CHLOROETHANE	50	X	X	X
-CHLOROETHYVINYL ETHER	1000	X	X	X
LÁLOROFORM	50	χ	X	X
1,2-DICHLOROBENZENE	250	X	X	X
3-DICHLOROBENZENE	250	Χ	X	X
.,4-DICHLOROBENZENE	250	X	X	X
1,1-DICHLOROETHANE	50	X	· X	X
, 2-DICHLOROETHANE	50	X	X	X
-1-DICHLOROETHENE	50	, X	X	X
1,2-DICHLOROETHENE	50	X	χ	X
T+1,3-DICHLOROPROPENE	50	X	X	X
-1.3-DICHLOROPROPENE	50	Χ	X	X
1,2-DICHLOROPROPANE	50	X	X	X
FTHYLBENZENE	50	Х	X	X
ETHYL BROMIDE	100	Χ	X	X
nETHYL CHLORIDE	50	Χ	X	X
METHYLENE CHLORIDE	1000	X	X	- X
1,2,2-TETRACHLOROETHANE	50	X	X	Х
ETRACHLOROETHENE	50	Х	X	Х
TOLUENE	50	X	X	X
: 1,1-TRICHLOROETHANE	50	X	X	X
1,2-TRICHLOROETHANE	50	Χ	X	X
TRICHLOROETHENE	50	X	X	X
"INYL CHLORIDE	50	Χ	X	X
/LENES	50	X	X	X

 $Y_i = ANALYZED_i$  BUT NOT DETECTED.

<sup>1</sup>DL = DETECTED, BUT LESS THAN REPORTABLE DETECTION LIMIT.

CK, D: KAM Abb, D: CAM

DATE ISSUED: 4-9-87

JARZYN ENGINEERING

VOLATILE ORGANIC COMPOUND RESULTS

JECT: NORTHROP BOUNDARY SURVEY

.OCATION: CHICAGO, ILLINOIS

#: 60222.00

	REPORTABLE DETECTION LIMIT	14924 B3-1	14925 84-2	14927 85-1	14928 86-1
OMPOUND	(UG/KG)	03/09/87	03/10/87	03/10/87	03/10/87
	=======================================	=======	=======	=======	=======
BENZENE	50	X	X	X	X
ROMODICHLOROMETHANE	50	X	X	X	X
JROMOFORM	100	X	X	X	Χ
CARBON TETRACHLORIDE	50	X	X	X	X
HLOROBENZENE	50	X	X	X	X
:HLORODIBROMOMETHANE	50	X	X	X	X
CHLOROETHANE	50	X	X	X	X
?-CHLOROETHYVINYL ETHER	1000	X	Χ	X	X
HLOROFORM	50	Χ	X	X	X
1:2-DICHLOROBENZENE	250	Χ	X	X	X
13-DICHLOROBENZENE	250	X	X	X	X
4-DICHLOROBENZENE	250	X	X	X	X
1.1-DICHLOROETHANE	50	X	Χ	X	X
1,2-DICHLOROETHANE	50	X	X	Χ	X
-1-DICHLOROETHENE	50	, X	Х	X	X
1,2-DICHLOROETHENE	50	X	Χ	X	X
T-1,3-DICHLOROPROPENE	50	X	X	X	Χ ,
-1,3-DICHLOROPROPENE	50	X	X	X	X
⇒ 2-DICHLOROPROPANE	SO	X	X	X	Χ
ETHYLBENZENE	50	X	X	X	X
ETHYL BROMIDE	100	X	Х	Х	Χ
SETHYL CHLORIDE	50	X	X	X	X
METHYLENE CHLORIDE	1000	X	X	X	X
1,1,2,2-TETRACHLOROETHANE	50	X	X	X	X
ETRACHLOROETHENE	50	X	X	Χ	X
TOLUENE	50	X	X	X	Х
1,1,1-TRICHLOROETHANE	50	X	Х	Χ	X
312-TRICHLOROETHANE	50	X	X	X	X
RICHLOROETHENE	50	X	X	Χ	X
VINYL CHLORIDE	50	X	X	X	X
YLENES	50	X	X	X	X

X = ANALYZED, BUT NOT DETECTED.

MDL = DETECTED, BUT LESS THAN REPORTABLE DETECTION LIMIT.

JARZYN ENGINEERING

JOLATILE ORGANIC COMPOUND RESULTS

JECT: NORTHROP BOUNDARY SURVEY

OCATION: CHICAGO, ILLINOIS

S#: 60222.00

CK'D: KAW APP'D: CAW
DATE ISSUED: 4-9-83

	REPORTABLE DETECTION LIMIT	14929 86-1 DUP	14932 P11-1	14933 P7-1	14934 P4-1
OMPOUND	(UG/KG)	03/10/87		03/11/87	
	========			=======	=======
BENZENE	50	X	Χ	X	X
BROMODICHLOROMETHANE	50	X	X	Χ	X
JROMOFORM	100	X	Х	X	X
CARBON TETRACHLORIDE	50	X	X	X	X
HLOROBENZENE	50	X.	X	X	X
CHLORODIBROMOMETHANE	50	X	X	X	X
CHLOROETHANE	50	Χ	X	Χ	Χ
2-CHLOROETHYVINYL ETHER	1000	X	X	X	X
HLOROFORM	50	X	X	X	X
1,2-DICHLOROBENZENE	250	Χ	X	X	X
1,3-DICHLOROBENZENE	250	X	Χ	. X	X
,4-DICHLOROBENZENE	250	X	X	Χ	X
1,1-DICHLOROETHANE	50	Χ	X	Χ	Χ
1,2-DICHLOROETHANE	50	X	X	X	X
-1-DICHLOROETHENE	50	X	Χ	X	Χ
1,2-DICHLOROETHENE	50	X	X	X	X
T-1,3-DICHLOROPROPENE	50	X	Χ	, X	X
:-1,3-DICHLOROPROPENE	50	X	X	X	X
,2-DICHLOROPROPANE	50	X	Χ	X	X
ETHYLBENZENE	50	X	X	X	X
TETHYL BROMIDE	100	X	X	X	X
1ETHYL CHLORIDE	50	X	X	Χ	X
METHYLENE CHLORIDE	1000	Х	X	X	X
1,1,2,2-TETRACHLOROETHANE	50	X	X	X	X
ETRACHLOROETHENE	50	X	X	X	X
TOLUENE	50	X	X	X	X
1,1,1-TRICHLOROETHANE	50	X	X	X	X
.,1,2-TRICHLOROETHANE	50	. X	X	X	Χ
FRICHLOROETHENE	50	X	X	X	X
VINYL CHLORIDE	50	X	X	X	X
YLENES	50	X	X	BMDL	Χ

X = ANALYZED, BUT NOT DETECTED.

HDL = DETECTED, BUT LESS THAN REPORTABLE DETECTION LIMIT.

### - WARZYN ENGINEERING ANALYTICAL LABORATORY RESULTS

PROJECT: WARZYN ENGINEERING INC.

NORTHROP BOUNDARY SURVEY

LOCATION: CHICAGO, ILLINOIS

C#: 60222.00

CK'D: KAN APP'D: CAN

DATE	ISSUED:	4-9-87

LAB # SAMPLE DESCRIPTION DATE SAMPLED ====================================	14930 SOUTH BOUNDARY 03/10/87	14931 EAST BOUNDARY 03/09/87
ARSENIC	1.92	1.83
BARIUM	<200	<200
CHROMIUM	<20.0	22.8
CADMIUM	<4.00	<4.00
LEAD	<60.0	<60.0
MERCURY	<0.103	<0.084
SELENIUM	<0.50	<0.50
SILVER	<10.0	<10.0

RESULTS ARE REPORTED IN MG/KG DRY WEIGHT BASIS.

## WARZYN ENGINEERING ANALYTICAL LABORATORY RESULTS

PROJECT: WARZYN ENGINEERING INC.

NORTHROP BOUNDARY SURVEY

LOCATION: CHICAGO, ILLINOIS

C#: 60222.00

DATE SAMPLED: 03/06/87

CK'D: KNW APP'D: CNW

DATE ISSUED: 4-14-87 RE-ISSUED

				*	
	LAB # SAMPLE DESCRIPTION			4850 BOUNDAR	۲۲
	=======================================		=====	======	==
	ARSENIC		1	. 68	
	BARIUM		<21	00	
	CADMIUM		< 4	.00	
	CHROMIUM		4	6.5	
1	LEAD		6	9.7	
	MERCURY		<0	.101	
	SELENIUM	3	<0	.500	
	SILVER		<1	0.0	

RESULTS ARE REPORTED IN MG/KG DRY WEIGHT BASIS.

0.5

3301 KINSMAN BLVD. • P.O. BOX 7545 • MADISON, WISCONSIN 53707 • PHONE (608) 241-4471 • TLX 703956 HAZRAL M.

# REPORT OF ANALYSIS

# SOIL SAMPLE

ELWOOD

YN ENGINEERING, INC.

SCIENCE COURT

ERSITY RESEARCH PARK

SON, WI 53705

SAMPLE NUMBER: 70, 1221

DATE ENTERED: 03:12/

REPORT PRINTED: 03/17/2

14926 B4-1

SE ORDER NUMBER: 60222.00-3/12/87

FORMALDEHYDE

LESS THAN 10.0

PPM

# GOD REFERENCE

OSH P & CAM 125 WITH MODIFICATIONS PER HAZLETON LABORATORY WORKSHEET NUMBER 5016.

# REFERENCES

MAL ANALYSIS: ASSAY NAME AND METHOD LISTED ABOVE WITH RESULTS

CK'D: KAW APPID: CAW

DATE ISSUED: 4-9-87

W/ TYN ENGINEERING

UQ\_\_TILE ORGANIC COMPOUND RESULTS

ROJECT: NORTHROP BOUNDARY SURVEY

LUCATION: CHICAGO, ILLINOIS

C#: 60222.00

	REPORTABLE				
TA CONTRACTOR	DETECTION	15264	15265	15266	15267
1995 1945	LIMIT	B1	82	83	84
COMPOUND	(UG/L)	03/26/87	03/26/87	03/26/87	03/26/87
***************************************	=========	=======	=======	======	=======
! NZENE	1.0	Х	Χ	X	X
bROMODICHLOROMETHANE	1.0	Х	X	X	X
BROMOFORM	2.0	X	3.6	X	X
RBON TETRACHLORIDE	1.0	X	X	X	X
UNLOROBENZENE	1.0	X	X	X	X
CHLORODIBROMOMETHANE	1.0	Χ	X	X	X
LOROETHANE	1.0	Х	X	X	X
CHLOROETHYVINYL ETHER	20	X	X	X	X
CHLOROFORM	1.0	X	Χ	X	Χ
2-DICHLOROBENZENE	5.0	X	X	X	X
3-DICHLOROBENZENE	5.0	X	Χ	X	X
1,4-DICHLOROBENZENE	5.0	X	Χ	Χ	X
1-1-DICHLOROETHANE	1.0	X	X	X	X
2-DICHLOROETHANE	1.0	, X	X	X	X
1-1-DICHLOROETHENE	1.0	X	Χ	X	X
1,2-DICHLOROETHENE	1.0	X	X	Х	X
1,3-DICHLOROPROPENE	1.0	Χ	X	Χ	X
U-1.3-DICHLOROPROPENE	1.0	Χ	、Χ	X	X
1,2-DICHLOROPROPANE	1.0	Х	X	X	X
HYLBENZENE	1.0	X	X	` X	X
THYL BROMIDE	2.0	Х	X	X	X
METHYL CHLORIDE	1.0	Χ	Х	X	X
METHYLENE CHLORIDE	1.0	Х	Χ	Χ	X
1,2,2-TETRACHLOROETHANE	1.0	X	X	X	X
TETRACHLOROETHENE	1.0	X	X	X	Χ
TOLUENE	<b>1.0</b> .	X	X	BMDL	X
1 1 1-TRICHLOROETHANE	1.0	X	X	X	X
1,1,2-TRICHLOROETHANE	1.0	X	X	X	X
TRICHLOROETHENE	1.0	X	X	X	X
NYL CHLORIDE	1.0	X	X	X	X
λ LENES	1.0	Χ	X	X	X

<sup>: =</sup> ANALYZED, BUT NOT DETECTED.

<sup>₹</sup> DL = DETECTED, BUT LESS THAN REPORTABLE DETECTION LIMIT.

L ZYN ENGINEERING

OLATILE ORGANIC COMPOUND RESULTS
ROJECT: NORTHROP BOUNDARY SURVEY

LOCATION: CHICAGO, ILLINOIS

CK'D: YAW APP'D: CAW DATE ISSUED: 4-9-87

	REPORTABLE DETECTION LIMIT	15268 85	15269 B6	15270 EQUIPMENT BLANK	15271 TRIP BLANK	15272 B1 FIELD DUP
COMPOUND	(UG/L)	03/26/87	03/26/87	03/26/87	03/26/87	03/26/87
=======================================	=========	=======		=======		======
_ENZENE	1.0	X	X	X	X	Х
BROMODICHLOROMETHANE	1.0	X	X	X	χ	X
ROMOFORM	2.0	X	X	Χ	X	X
ARBON TETRACHLORIDE	1.0	X	X	X	Χ	Х
CHLOROBENZENE	1.0	X	Х	Х	X	X
^4LORODIBROMOMETHANE	1.0	X	χ	X	χ	X
HLOROETHANE	1.0	X	X	X	X	X
Z-CHLOROETHYVINYL ETHER	20	X	Χ	X	Χ	X
CHLOROFORM	1.0	X	X	X	Χ	X
2-DICHLOROBENZENE	5.0	Х	X	X	Χ	X
13-DICHLOROBENZENE	5.0	X	X	Х	X	X
1,4-DICHLOROBENZENE	5.0	X	X	X	X	Χ
11-DICHLOROETHANE	1.0	, X	X	X	Χ	X
2-DICHLOROETHANE	1.0	· X	X	X ·	X	X
1-1-DICHLOROETHENE	1.0	X	X	X	Χ	X
: 2-DICHLOROETHENE	1.0	Χ	X	Χ	Х	Χ
-1.3-DICHLOROPROPENE	1.0	X	X	Χ	X	X
C-1,3-DICHLOROPROPENE	1.0	X	Χ	X	Χ	X
1,2-DICHLOROPROPANE	1.0	X	X	Х	Χ	χ
HYLBENZENE	1.0	Х	Χ	X	Х	X
METHYL BROMIDE	2.0	Χ	Χ	X	X	X
METHYL CHLORIDE	1.0	X	X	X	Χ	Х
ETHYLENE CHLORIDE	1.0	X	X	X	X	X
1,1,2,2-TETRACHLOROETHANE	1.0	X	Χ	X	X	· X
TETRACHLOROETHENE	1.0	X	Х	X	X	X
LUENE	1.0	BMDL	Χ	2.0	2.0	X
_,1,1-TRICHLOROETHANE	1.0	X	X	X	Х	X
1,1,2-TRICHLOROETHANE	1.0	X	X	X	Χ	X
RICHLOROETHENE	1.0	X	X	X	Χ	X
INYL CHLORIDE	1.0	Χ	X T	Χ	X	X
XYLENES	1.0	X	X	X	X	Χ

<sup>=</sup> ANALYZED, BUT NOT DETECTED.

BMDL = DETECTED, BUT LESS THAN REPORTABLE DETECTION LIMIT.

### WARZYN ENGINEERING ANALYTICAL LABORATORY RESULTS

PROJECT: WARZYN ENGINEERING INC.

NORTHROP BOUNDARY SURVEY

LOCATION: CHICAGO, ILLINOIS

C#: 60222.00

DATE SAMPLED: 03/26/87 CK'D: KAW APP'D: LAW

DATE ISSUED: 4-9-87

LAB #	SAMPLE DESCRIPTION	CALCIUM	CHLORIDE
=====		222222	=======
15273	83	189	395

RESULTS ARE REPORTED IN MG/L.

3301 KINSMAN BLVD. • P.O. BOX 7545 • MADISON, WISCONSIN 53707 • PHONE (608) 241-4471 • TLX 703956 HAZRAL MDS UD

#### REPORT OF ANALYSIS

WATER SAMPLE

page 10

IN ELWOOD

LARZYN ENGINEERING, INC.

1 SCIENCE COURT

HIVERSITY RESEARCH PARK

DISON, WI 53705

SAMPLE NUMBER: 7030526

DATE ENTERED: 03/27/8

REPORT PRINTED: 04/06/8

TER: WEI # 15267; B4

RCHASE ORDER NUMBER: 60222.00-3/27/87

RMALDEHYDE BY CHROMOTROPIC ACID

LESS THAN 5

#### ETHOD REFERENCE

DSH P&CAM 125.

#### | THOD REFERENCES

PTCIAL ANALYSIS: ASSAY NAME AND METHOD LISTED ABOVE WITH RESULTS

APPENDIX D
SOIL BORING LOG

(1 Page)



# LOG OF TEST BORING

Project Environmental Boundary Survey

600 Hicks Road - Northrop
Location Rolling Meadows, Illinois

Boring N	lo.	P-9
Surface	Ele	evation
Job No.		60222
Sheet _	1	of1

WARZYN ENGINEERING INC. . ONE SCIENCE COURT . UNIVERSITY RESEARCH PARK . P.O. BOX 5385 . MADISON, WISCONSIN 53705

SAMPLE			VISUAL CLASSIFICATION		SOIL PROPERTIES					
Rec	Recovery Moisture		Maiatura		and Remarks		***			2
Type	<b>\</b>	į į	N	Depth		Çu	W	l LL	PL	0
					Mottled Yellow Brown with Dark Brown to Black Clayey SAND, Some Fine and Coarse Gravel (SC)					
+				E 2 -	8 N 8					
					Black Silty CLAY, Trace Fine Sand (CL)					
				E 4 -	Strong Fuel Oil Odor					
+					Mottled, Light Gray with Yellow Olive Brown Clayey SILT, Trace Fine to Coarse Sand and Fine					
		17			Gravel (ML)					
				-8 - - - -	8	7.81				
				F.	End Probe at 8.5'					
				E 101	Probe backfilled immediately with cuttings.		2	8		
-				E 12:		3				
		Q.		- 14- -						
				E 16-						
	industry in	W	AT	ER	LEVEL OBSERVATIONS	-	NER			
Upon Completion of Drilling  Fime After Drilling  Depth to Water			Crev	3/11/8 v Chief ng Me	SYLF	Rig CM	E 55.			
epth t	o Cav	ve In	is	-			30.00		80	



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

# REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

RECEIVED MAY 1 7 1993
WMD RCRA
RECORD CENTER Compliance

REPLY TO THE ATTENTION OF:

HRE-8J

May 13, 1993

David A. Gurrie Manager, Environmental and Safety Compliance Northrop Corporation 600 Hicks Road Rolling Meadows, IL 60008-1098

Re:

Visual Site Inspection Northrop Corporation Electronic Systems Division Rolling Meadows, IL ID No. ILD 005 128 988

Dear Mr. Gurrie:

The United States Environmental Protection Agency (U.S. EPA) Region V will conduct a Preliminary Assessment and a Visual Site Inspection (PA/VSI) at the referenced facility. This inspection is conducted pursuant to the Resource Conservation and Recovery Act, as amended (RCRA) Section 3007 and the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA) Section 104(e). The referenced facility has generated, treated, stored, or disposed of hazardous waste subject to RCRA. The PA/VSI requires identification and systematic review of all solid waste streams at the facility. The objective of the PA/VSI is to determine whether or not releases of hazardous wastes or hazardous constituents have occurred or are occurring at the facility which may require further investigation. This analysis will also provide information to establish priorities for addressing any confirmed releases.

The visual site inspection of your facility is to verify the location of all solid waste management units (SWMUs) and areas of concern (AOCs) and to make a cursory determination of their condition by visual observation. The definitions of SWMUs and AOCs are included in Attachment I. The VSI supplements and updates data gathered during a preliminary file review. During this site inspection, no samples will be taken. A sampling visit to ascertain if releases of hazardous waste or constituents have occurred may be required at a later date.

Assistance of some of your personnel may be required in reviewing solid waste flow(s) or previous disposal practices. The site inspection is to provide a technical understanding of the present and past

David A. Gurrie May 13, 1993 Page 2

waste flows and handling, treatment, storage, and disposal practices. Photographs of the facility are necessary to document the condition of the units at the facility and the waste management practices used.

The VSI has been scheduled for Friday, May 21, 1993 at 8:00 a.m. The inspection team will consist of Jeff Swano and Shin Ahn of PRC Environmental Management, Inc., a contractor for the U.S. EPA. Representatives of the Illinois Environmental Protection Agency (IEPA) may also be present. Your cooperation in admitting and assisting them while on site is appreciated.

The U.S. EPA recommends that personnel who are familiar with present and past manufacturing and waste management activities be available during the VSI. Access to any relevant maps, diagrams, hydrogeologic reports, environmental assessment reports, sampling data sheets, environmental permits (air, NPDES), manifests and/or correspondence is also necessary, as such information is needed to complete the PA/VSI.

If you have any questions, please contact me at (312) 886-4448 or Francene Harris at (312) 886-2884. A copy of the Preliminary Assessment/Visual Site Inspection Report, excluding the conclusions and Executive Summary portion will be sent when the report is available.

Sincerely yours,

Kevin M. Pierard, Chief

OH/MN Technical Enforcement Section

Enclosure

cc:

Bill Ingersoll, IEPA Larry Eastep, IEPA

#### ATTACHMENT I

The definitions of solid waste management unit (SWMU) and area of concern (AOC) are as follows.

A SWMU is defined as any discernable unit where solid wastes have been placed at any time from which hazardous constituents might migrate, regardless of whether the unit was intended for the management of a solid or hazardous waste.

#### The SWMU definition includes the following:

- RCRA regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that
   U.S. Environmental Protection Agency has generally exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents, such as wood preservative treatment dripping areas, loading or unloading areas, or solvent washing areas

An AOC is defined as any area where a release to the environment of hazardous wastes or constituents has occurred or is suspected to have occurred on a nonroutine or nonsystematic basis. This includes any area where such a release in the future is judged to be a strong possibility.

PRC requests that, if available, the following facility information be provided during the VSI:

- 1. Two copies of a detailed map of the facility
- 2. Facility history, including dates of operation, ownership changes, and production processes
- 3. Current facility operations
- 4. Processes that generate waste that is treated, stored, or disposed of at the facility
- 5. Records of disposal of wastes generated at the facility (manifests, annual reports, etc...)
- 6. Security at the facility
- 7. Information regarding geology and the uses of ground water and surface water in the area
- 8. Permits (air, NPDES, etc...) the facility currently holds or has held in the past and documentation of any permit violations that may have occurred
- 9. Records of any spills that may have occurred at the facility
- 10. Descriptive operational information (location, dimensions, capacity, materials of construction, etc...), dates of start-up and closure, wastes managed, release controls, and release history for each SWMU



217/782-6762

Refer to: 0312730002 -- Cook County

Northrop Corp. Defense Systems

ILD005128988 RCRA General

March 2, 1987

Karl E. Bremer, Chief Technical Program Section U.S. Environmental Protection Agency Region V 230 South Dearborn Chicago, Illinois 60604



MAR 0 9 1987

SULID PRADIE DIMPINIH U.S. EPA, REGION V

Dear Mr. Bremer:

Enclosed you will find the following:

- The Initial Screening for Environmental Significance form for the above referenced facility.
- 2. A copy of the Certification Regarding Potential Releases from Solid Waste Management Units for the above referenced facility and/or the reply the Agency received in response to our request for information regarding the above.

The following form(s) were not on file at the IEPA for this facility:

- 1. Notification of Hazardous Waste Site (EPA Form 8900-1).
- Notification of Hazardous Waste Site (EPA Form 8900-1) for the above referenced facility.

Based upon a review of the information available on the above referenced facility, the Agency has determined that this facility is not environmentally significant and that a Facility Management Plan should not be prepared. Please let us know if you do not agree with this determination.



### Page 2

If you have any questions regarding this initial screening, please contact Mark A. Schollenberger of my staff at 217/782-6762.

Very truly yours,

Kawrence W. Eastep, P.E., Manager

Permit Section

Division of Land Pollution Control

LWE:MAS:jab/1755g/3-4

**Enclosure** 

cc: Division File

USEPA Region V -- Ann Budich FOS Northern Region

295 Closure

Copied to Rey 2-19-87

MAS

NORTHROP

Defense Systems Division Electronics Systems Group

\_\_\_\_\_

Northrop Corporation

600 Hicks Road Rolling Meadows, Illinois 60008-1098 Telephone 312 259-9600 TWX 910 687-3785 TLX 270566

February 16, 1987

Mr. Lawrence Eastep Division of Land Pollution Control Permit Section Illinois Environmental Protection Agency 2200 Churchill Road Springfield, IL 62706

Subject: Northrop Corporation

Defense Systems Division Rolling Meadows, Illinois USEPA ID No. ILD 005 128 988

Dear Mr. Eastep:

Attached is the completed and signed certification form regarding releases from solid waste management units for closure plan review.

If you have any questions, please call Richard Ng at (312) 394-7716.

Very truly yours,

NORTHROP CORPORATION

Robert Langlois

Director

Administration/Facilities

RL/rr028/01R Encl. CC: W. Burks Terry

Tom Tutien
Baxter & Woodman
8678 Ridgefield Rd.
Crystal Lake, IL 60014

RECEIVED

FEB 19 1987

# CERTIFICATION REGARDING POTENTIAL RELEASES FROM SOLID WASTE MANAGEMENT UNITS (CLOSURE PLAN REVIEW)

A I.D. NUMBER:	ILD005128988	ion - Defense Systems Di	
		Rolling Meadows	
CATION CITY:			
STATE:	Illinois 60010		
closed) at your	facility? NOTE - D	d waste management units NOT INCLUDE HAZARDOUS W ICATION and in your clos	ASTES UNITS
		YES NO	
° Landfill		<u>X</u>	
<ul><li>Surface Impou</li><li>Land Farm</li></ul>	indment	X X X X X X X X X X X X	·
<ul> <li>Waste Pile</li> </ul>		<u> </u>	
Incinerator	(Above Ground)	<u>X</u>	
<ul> <li>Storage Tank</li> </ul>	(Underground)	X	
<ul><li>Container Sto</li><li>Injection Well</li></ul>	rage Area 11s	<u>X</u>	
Wastewater Tr	reatment Units	<u> </u>	
transier Star	ions ing Operations		·
* Waste Treatme	ent, Detoxification	<u> </u>	
° Other			
provide a descri of in each unit. would be conside RCRA. Also incl disposed on and	iption of the waste. In particular, pered as hazardous wolude any available the dates of dispositionally,	of the items in Number 1 s that were stored, treat lease focus on whether or astes or hazardous constitutes on quantities or volsal. Please also provide dimensions, location at	ted or disposed r not the wastes ituents under lume of wastes e a description
Nc	ot Applicable		
	,		
			RECEIVE

NOTE: Hazardous waste are those identified in 40 CFR 261. Hazardous constituents are those listed in Appendix VIII Of 40 CFR Part 261.

3.	For the units noted in Number 1 above and also those hazardous waste units
	in your Part A application and in your closure plan. please describe for
	each unit any data available on any prior or current releases of hazardous
	wastes or constituents to the environment that may have occurred in the part
	or still be occurring.
	Please provide the following information

2	Dat.	<u> </u>	· rol	ease
<b>a</b> .	Dat	. 01	rei	rase

- b. Type of waste released.
- c. Quantity or volume of waste released
- d. Describe nature of release (i.e., spill, overflow, ruptured pipe or tank, etc.)

- No	knov	vledge	of	hazardous	wastes	or	constituents	released	
to	the	envir	onm	ent.					
									*

4. In regard to the prior releases described in Number 3 above, please provide (for each unit) any analytical data that may be available which would describe the nature and extent of environmental contamination that exists as a result of such releases, Please focus on concentrations of hazardous wastes or constituents present in contaminated soil or groundwater.

Not	Applicable.		 	

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the submittal is, to the best of my knowledge and belief, true, accurate, and complete. 1 am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (42 U.S.C. 6902 et seq. and 40 CFR 270.11(d))

200

\* Robert Langlois Director, Facilities/Administration

RECEIVED

Typed Name and Title

2/11/87

FEB 19 1981

Signature

Date

EPA-DLFC

# CERTI: \_ATION REGARDING POTENTIAL RELE: S FROM SOLID WASTE MANAGEMENT UNITS



FACILITY NAME:	Northrop Corporatio	on Defense Syste	em Division	
EPA I.D. NUMBER:	ILD 005 <mark>128</mark> 988	2		
LOCATION CITY:	Rolling Meadows			
STATE:	Illinois		*	
closed) at your	f the following soli facility? NOTE - DO IN YOUR PART A APPL	NOT INCLUDE HA	ent units (ex ZARDOUS WASTE	isting or UNITS
<ul> <li>Storage Tank</li> <li>Container St</li> <li>Injection We</li> <li>Wastewater T</li> <li>Transfer Sta</li> <li>Waste Recycl</li> </ul>	(Above Ground) (Underground) orage Area 11s reatment Units	YES	NO	
provide a descr of in each unit would be consid RCRA. Also ind disposed of and of each unit ar	ription of the wastes  In particular, placed as hazardous was clude any available of the dates of disposed include capacity, plan if available.	s that were stor lease focus on w astes or hazardo data on quantit sal. Please als	red, treated of whether or not bus constituenties or volume so provide a d	the wastes  its under  of wastes  iescription
				559

NOTE: Hazardous wastes are those identified in 40 CFR 261. Hazardous constituents are those listed in Appendix VIII of 40 CFR Part 261.

For the units noted in Number 1 above and also those hazardous waste units in your Part A application, please describe for each unit any data available on any prior or current releases of hazardous wastes or constituents
to the environment that may have occurred in the past or may still be occurring.

Please provide the following information

- a. Date of release
- b. Type of waste released

No releases have occurred

- c. Quantity or volume of waste released
- d. Describe nature of release (i.e., spill, overflow, ruptured pipe or tank, etc.)

**				
		•		<u> </u>
please provi which would that exists	the prior or conti de (for each unit) describe the nature as a result of such stes or constituent	any analytical and extent of releases. Plo	data that may be a environmental cont ease focus on conce	available tamination entrations of
_Not_applica	hle			
<u></u>				

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the submittal is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (42 U.S.C. 6902 et seq. and 40 CFR 270.11(d))

John H. McNaughton

Vice President, Financial Management

Typed Name and Title

2/9/86 Date